

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21000688/UBA3Q2

Date: 05/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	FBR4361M	Insured Vehicle No :	YP1918R
Date of Loss:	10/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR4361M	Engine No:	G3H6E0017511
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000013912
Reg. Date:	01/07/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,707.50	2,200.05	507.45	18.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	812.00	385.00	427.00	52.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,519.50	2,585.05	934.45	26.55
+ GST 7.00/7.00% (\$\$)	246.37	180.95	65.42	26.55
Nett Amount (\$\$)	3,765.87	2,766.00	999.87	26.55
+ Loss of Use (4.0 x S\$20.00/day) (\$\$)		80.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,853.45		
Global Sum Settlement (\$\$)		2,750.00		

INSPECTION

Date of Assignment:	14/01/2021		
Date Inspected:	14/01/2021	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ)
			No. 6 Defu Lane 4
			Singapore 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Mar 2021)	
Parts:	N/A	YAMAHA NMAX155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR4361M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR HANDLE	Bent	32.00 F	*32.00 FL
2	1		*BEARING STEERING CONE UPPER	Necessary	42.00 F	*42.00 FL
3	1		*BELLY PAN	Torn	33.00 F	*33.00 FL
4	1		*BOARD FOOTREST LH	Not Necessary	50.00 F	*- FL
5	1		*BOARD FOOTREST RH	Not Necessary	50.00 F	*- FL
6	1		*BRACKET BAR HANDLE	Not Necessary	38.00 F	*- FL
7	1		*CAMETA (V-SYS) M6 (NON-WIFI VERSION) (NEW)	Broken / Torn	308.00 F	*308.00 FL
8	1		*COVER CLUTCH OUTER (Scratched)	Not Consistent With The Impact	28.00 F	*- FL
9	1		*COVER CLUTCH OUTER DAMPER 1	Not Necessary	12.00 F	*- FL
10	1		*COVER CLUTCH OUTER DAMPER 2	Not Necessary	7.00 F	*- FL
11	1		*COVER CLUTCH OUTER DAMPER 3	Not Necessary	7.00 F	*- FL
12	1		*COVER CLUTCH OUTER DAMPER 4	Not Necessary	12.00 F	*- FL
13	1		*COVE FRONT LOWER (GREY)	Not Necessary	21.00 F	*- FL
14	1		*COVE FRONT UPPER (GREY)	Cracked	35.00 F	*35.00 FL
15	1		*COVER SIDE CENTRE LH (GREY)	Cracked	21.00 F	*21.00 FL
16	1		*COVER SIDE CENTRE RH (GREY)	Cracked	21.00 F	*21.00 FL
17	1		*COVER SIDE LH (MATTE BLACK)	Cracked	38.00 F	*38.00 FL
18	1		*EMBLEM (YAMAHA) LOGO	Necessary	14.00 F	*14.00 FL
19	2		*EMBLEM ABS	Necessary	8.00 F	*8.00 FL
20	1		*FORK FRONT ASSY	Bent / Twisted	740.00 F	*740.00 FL
21	1		*FRONT COWLING LH (GREY)	Cracked	32.00 F	*32.00 FL
22	1		*FRONT COWLING RH (GREY)	Cracked	32.00 F	*32.00 FL
23	1		*HEADLAMP ASSY	Cracked	299.00 F	*299.00 FL
24	1		*HORN	Bent	28.00 F	*28.00 FL
25	1		*LAMP SIGNAL FRONT LH	Cracked	34.00 F	*34.00 FL
26	1		*LAMP SIGNAL FRONT RH	Cracked	34.00 F	*34.00 FL
27	1		*LEVER BRAKE LH	Scratched	18.00 F	*18.00 FL
28	1		*MIRROR RH	Missing	35.00 F	*35.00 FL
29	1		*MUDGUARD FRONT (GREY)	Cut	45.00 F	*45.00 FL
30	1		*PANEL 1 (MATTE BLACK) LH	Cracked	21.00 F	*21.00 FL
31	1		*PANEL CONSOLE 2	Not Necessary	38.00 F	*- FL
32	1		*PANEL METER	Cut	16.00 F	*16.00 FL
33	1		*RACVE BALL 1	Necessary	12.00 F	*12.00 FL
34	1		*RACVE BALL 2	Necessary	12.00 F	*12.00 FL
35	1		*RETAINER BALL BEARING	Necessary	12.00 F	*12.00 FL
36	5		*RIVET	Necessary	7.50 F	*7.50 FL
37	4		*SCREW (VISOR)	Necessary	12.00 F	*12.00 FL
38	1		*SPEEDOMETER ASSY	Cracked	198.00 F	*198.00 FL
39	1		*STAY FRONT HEADLAMP	Bent	90.00 F	*90.00 FL
40	1		*STAY HORN	Bent	32.00 F	*32.00 FL
41	1		*WINDSHIELD	Missing	56.00 F	*56.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*WIRE HARNESS ASSY	Cracked	70.00 F	*70.00 FL
43	1		*PANEL 1 (MATT BLACK) LH		-	-
44	1		*PANEL CONSOLE 2		-	-
45	1		*PANEL METER		-	-
46	1		*RACE BALL 1		-	-
47	1		*RACE BALL 2		-	-
48	1		*RETAINER BALL BEARING		-	-
49	5		*RIVET		-	-
50	4		*SCREW (VISOR)		-	-
51	1		*SPEEDOMETER ASSY		-	-
52	1		*STAY FRONT HEADLAMP		-	-
53	1		*STAY HORN		-	-
54	1		*WINDSHIELD		-	-
55	1		*WIRE HARNESS ASSY		-	-
56	1		*COVER BAR HANDLE LOWER	Cracked	20.00 F	*20.00 FL
57	1		*COVER METER GREY	Cracked	7.00 F	*7.00 FL
58	1		*STICKER (MCDNALDS) SIDECOVER/WINDSHIELD	Necessary	16.00 F	*16.00 FL
59	1		*STICKER NUMBER PLATE FRONT (BLACK)	Necessary	14.00 F	*14.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,707.50	2,444.50
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	244.45
Total Parts (S\$)	2,707.50	2,200.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT CHARGES	New	56.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	756.00	350.00
Gross Labour Cost (\$\$)			812.00	385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >