

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000696/KVF3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00025812001
Claimant Vehicle No :	SLG7329C	Insured Vehicle No :	SMJ199D
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200160/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7329C	Engine No:	P520373825
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BM42A8G0345803
Reg. Date:	12/10/2016 (Man. Year: 2016)	Odometer:	63272 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,300.16	2,906.64	1,393.52	32.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,310.00	1,190.00	47.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,800.16	4,216.64	2,583.52	37.99
+ GST 7.00/7.00% (\$\$)	476.01	295.16	180.85	37.99
Nett Amount (\$\$)	7,276.17	4,511.80	2,764.37	37.99

INSPECTION

Date of Assignment:	14/01/2021	
Date Inspected:	15/01/2021	Inspected At:
		Spark Car Care @ Braddell (HQ)
		205 BRADDELL RD
		Singapore 579701
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$619.04 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7329C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER }	Cracked	971.40 FL	*971.40 FL
2	1		*FRONT BUMPER LOWER CENTRE GRILLE }		0.00 FL	*- FL
3	1		*FRONT BUMPER SIGNAL LAMP LH	*Check	165.20 FL	*- FL
4	1		*FRONT BUMPER COVER LH	Dented	29.40 FL	*29.40 FL
5	1		*FRONT BUMPER TOW COVER	Serviceable	30.10 FL	*- FL
6	1		*FRONT BUMPER BRACKET LH	*Check	15.90 FL	*- FL
7	1		*FRONT BUMPER BRACKET RH	Repair	15.90 FL	*- FL
8	1		*FRONT BUMPER RETAINER LH	Cracked	19.70 FL	*19.70 FL
9	1		*FRONT BUMPER RETAINER RH	Serviceable	19.70 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Repair	466.80 FL	*- FL
11	6		*FRONT BUMPER CLIPS	Necessary	18.00 FL	*18.00 FL
12	1		*FRONT GRILLE	*Check	125.60 FL	*- FL
13	1		*FRONT GRILLE BADGE LOGO	*Check	46.50 FL	*- FL
14	1		*FRONT GRILLE CHROME MOULDING LH	Dented	185.60 FL	*185.60 FL
15	1		*FRONT GRILLE CHROME MOULDING RH	Serviceable	185.60 FL	*- FL
16	1		*FRONT UPPER GRILLE (NPA)	Not Necessary	0.00 FL	*- FL
17	4		*FRONT GRILLE RIVETS	*Check	36.80 FL	*- FL
18	4		*FRONT UPPER GRILLE RIVETS	*Check	32.00 FL	*- FL
19	1		*LH HEADLAMP ASSY	Broken	812.00 FL	*812.00 FL
20	1		*BONNET	Bent	1,120.70 FL	*1,120.70 FL
21	1		*FRONT TOP PANEL	*Check	351.80 FL	*- FL
22	1		*LH FRONT FENDER	Bent	350.60 FL	*350.60 FL
23	1		*LH FRONT FENDER INNER SHIELD	Distorted	101.90 FL	*101.90 FL
24	8		*LH FRONT FENDER INNER SHIELD CLIPS	Necessary	24.00 FL	*24.00 FL
25	1		*LH FRONT TYRE (DAVANTI DX390)	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,325.20	3,633.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,025.04	726.66
Total Parts (\$\$)	4,300.16	2,906.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE LH FRONT FENDER INNER PANEL AND REPLACE DAMAGED PARTS	New	720.00	480.00
2	TO CHECK WIRING FUNCTIONS AND FOCUS HEADLAMPS	New	60.00	20.00
3	TO PUTTY,APPLY PRIMER & SPRAY-PAINT THE FRONT BUMPER,BUMPER REINFORCEMENT,BONNET,LH FRONT FENDER,LH FRONT FENDER INNER PANEL,LH FRONT DOOR AND AFFECTED AREAS	New	1,500.00	750.00
4	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	100.00	60.00
5	TO CHECK/RE-SET STEERING GEOMETRY AND WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			2,500.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >