

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21000697/KGA3Q2**Date:** 21/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507440
Claimant Vehicle No :	SHD5143Y	Insured Vehicle No :	SJD2399Y
Date of Loss:	08/01/2021	Nature of Claim:	TP
		Claim No:	1566501798SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5143Y		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2B45719
Reg. Date:	26/10/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FUX03073258
Colour:	Metallic Pearl White/Red	Odometer:	181741 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,480.90	432.22	2,048.68	82.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	300.00	4,540.00	93.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,320.90	732.22	6,588.68	90.00
+ GST 7.00/7.00% (S\$)	512.46	51.26	461.20	90.00
Nett Amount (S\$)	7,833.36	783.48	7,049.88	90.00
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	13/01/2021		
Date Inspected:	13/01/2021	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	1.0 days		

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Repair	442.60 FL	*- FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
4	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
7	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
8	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
9	1		*BUMPER CENTER GUARD CLIP	Not Necessary	80.00 FS	*- FS
10	1		*REAR TAILGATE STICKER TRAS-CAB	Not Necessary	80.00 FS	*- FS
11	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
12	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
13	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,881.20	576.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	400.30	144.08
Total Parts (\$\$)	2,480.90	432.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	80.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$\$)			4,840.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >