

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21000699/R1PA3Q2
Date: 20/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070015122
Claimant Vehicle No :	SMS5149T	Insured Vehicle No :	SGL6155B
Date of Loss:	13/01/2021	Nature of Claim:	TP
		Claim No:	0725467236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5149T		
Make & Model:	SKODA OCTAVIA, 2.0 RS TSI AIDISPLAY (A)	Engine No:	DLB032457
Reg. Date:	28/02/2020 (Man. Year: 2019)	Chassis No:	TMBBU7NE9L0053813
Colour:	White	Odometer:	22198 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/35 R19	Rear Tyre Size:	225/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,796.19	12,157.18	6,639.01	35.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	37,445.00	21,405.00	16,040.00	42.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	56,241.19	33,562.18	22,679.01	40.32
+ GST 7.00/7.00% (S\$)	3,936.88	2,349.35	1,587.53	40.32

Nett Amount (S\$)	60,178.07	35,911.53	24,266.54	40.32
+ Loss of Use (35.0 x S\$100.00/day) (S\$)		3,500.00		
Nett Liability (S\$)		39,411.53		

INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021

Estimated Period of Repair: 23.0 days

Inspected At:

VOLKSWAGEN GROUP SINGAPORE PTE LTD
NO 17 TUAS AVE 9
SINGAPORE 639197**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR FRT BUMPER	Repair	1,539.67 FS	*- FS
2	1		*SENSOR BRA	Serviceable	13.05 FS	*- FS
3	1		*SENSOR BRA	Serviceable	13.05 FS	*- FS
4	1		*BUFFER FRT BUMPER FOAM	Cracked	49.49 FS	*49.49 FS
5	1		*REAR TRUNK	Bent	3,255.00 FS	*3,255.00 FS
6	1		*REAR WINDO REAR W/SCREEN	Necessary	811.06 FS	*811.06 FS
7	2		*1K WINDOW ADHESIVE	Necessary	102.22 FS	*102.22 FS
8	1		*ALL PURPOSE CLEANER	Necessary	94.03 FS	*94.03 FS
9	1		*PRIMER	Necessary	27.39 FS	*27.39 FS
10	1		*ACTIVATOR FOR PRECOATED W	Necessary	25.14 FS	*25.14 FS
11	2		*APPLICATOR	Necessary	20.24 FS	*20.24 FS
12	1		*STRIP 3RD BRAKE LIGHT STRIP	Necessary	20.54 FS	*20.54 FS
13	1		*DECKLID WE REAR BOOT WEATHERSTRIP	Necessary	130.64 FS	*130.64 FS
14	2		*RIVETTED CAP NUT	Necessary	4.56 FS	*4.56 FS
15	1		*SKODA EMBI	Necessary	64.32 FS	*64.32 FS
16	1		*INSCRIPTIO EMBLEM -SKODA	Necessary	73.51 FS	*73.51 FS
17	1		*ISCRPTIO EMBLEM -OCTAVIA	Necessary	82.45 FS	*82.45 FS
18	1		*ISCRPTIO EMBLEM -RS	Necessary	82.45 FS	*82.45 FS
19	1		*COVER FOR REAR BUMPER	Cracked	1,371.14 FS	*1,371.14 FS
20	1		*SPOILER	Deformed	178.34 FS	*178.34 FS
21	1		*COVER FOR REAR BUMPER TOWING COVER	Cut	7.25 FS	*7.25 FS
22	1		*BRACKET EXHAUST PIPE CHROM BRACKET RH	Cracked	20.41 FS	*20.41 FS
23	1		*EXH TAIL P EXH PIPE CHROM RH	Bent	466.09 FS	*466.09 FS
24	1		*REINFORCEMENT REAR REINFORCEMENT	Bent	448.02 FS	*448.02 FS
25	1		*CONNECTING BUMPER END TRIM LH	Necessary	28.48 FS	*28.48 FS
26	1		*CONNECTING BUMPER END TRIM RH	Necessary	28.48 FS	*28.48 FS
27	1		*RETAINING BUMPER CTR BRACKET LH	Cracked	65.74 FS	*65.74 FS
28	1		*RETAINING BUMPER CTR BRACKET RH	Cracked	65.74 FS	*65.74 FS
29	1		*GUIDE PIEC BUMPER SIDE BRACKET LH	Cracked	20.46 FS	*20.46 FS
30	1		*GUIDE PIEC BUMPER SIDE BRACKET RH	Cracked	20.46 FS	*20.46 FS
31	6		*UNBEKANNT NUT	Necessary	1.14 FS	*1.14 FS
32	10		*EXPANDING NUT	Necessary	18.00 FS	*18.00 FS
33	1		*SENSOR BRA	Necessary	11.63 FS	*11.63 FS
34	1		*SENSOR BRA	Necessary	11.63 FS	*11.63 FS
35	2		*SENSOR BRA	Necessary	23.26 FS	*23.26 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*SENSOR PRIMED	Necessary	329.24 FS	*329.24 FS
37	2		*SEAL RING SATIN BLACK	Necessary	2.56 FS	*2.56 FS
38	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
39	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
40	1		*TAILLIGHT TAILLIGHT RH	Cracked	691.81 FS	*691.81 FS
41	1		*REFLECTOR REFLECTOR RH	Missing	35.76 FS	*35.76 FS
42	1		*REFLECTOR REFLECTOR CTR	Cracked	54.64 FS	*54.64 FS
43	1		*REAR PANEL END PANEL INNER	Bent	581.29 FS	*581.29 FS
44	1		*END PLATE END PANEL OUTER	Bent	120.67 FS	*120.67 FS
45	1		*ZINC SPRAY	Necessary	62.88 FS	*62.88 FS
46	1		*2K-BODY ADHESIVE	Necessary	428.72 FS	*428.72 FS
47	1		*SEALANT CAN BE SPRAYED	Necessary	64.15 FS	*64.15 FS
48	1		*WHEELHOUSE RHR FENDER LINER	Cut	120.88 FS	*120.88 FS
49	1		*FLOOR PAN	Bent	522.30 FS	*522.30 FS
50	1		*RETAINER SPARE WHEEL BOLT BRACKET	Necessary	44.66 FS	*44.66 FS
51	1		*BOLT FOR SPARE WHEEL MOUN	Necessary	19.75 FS	*19.75 FS
52	1		*CONTROL UNIT FOR BLIND SP	Serviceable	864.09 FS	*- FS
53	1		*BRACKET CONTROL UNIT BLIND SPOT BRACKET	Serviceable	22.66 FS	*- FS
54	1		*MIDDLE EXH REAR SILENCER	Serviceable	4,124.43 FS	*- FS
55	1		*DUAL CLAMP	Not Necessary	62.04 FS	*- FS
56	1		*HEAT SHIELD FOR EXHAUST M	Bent	112.50 FS	*112.50 FS
57	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
58	1		*REAR W/SCREEN SOLAR FILM	Necessary	400.00 FS	*400.00 FS
59	1		*FRT BUMPER CTR LOWER GRILLE	Cracked	92.93 FS	*92.93 FS
60	1		*DUAL CLAMP	Necessary	60.12 FS	*60.12 FS
61	1		*CLIP	Necessary	4.91 FS	*4.91 FS
62	1		*LH FOIL	Bent	52.35 FS	*52.35 FS
63	1		*RH FOIL	Bent	52.35 FS	*52.35 FS
64	1		*END PANEL TRIM COVER	Deformed	133.58 FS	*133.58 FS
65	2		*FLOOR PAN INSULATOR	Necessary	87.30 FS	*87.30 FS
66	4		*HEXAGON FLANGE SCREW	Necessary	10.00 FS	*10.00 FS
67	8		*PLUG	Necessary	10.64 FS	*10.64 FS
68	4		*HEXAGON FLANGE SCREW	Necessary	35.40 FS	*35.40 FS
69	2		*HEXAGON FLANGE SCREW	Necessary	7.00 FS	*7.00 FS
70	8		*BOLT HEX .HD	Necessary	48.00 FS	*48.00 FS
71	2		*ECCENTRIC SCREW	Necessary	32.08 FS	*32.06 FS
72	2		*SHOULDERED HEX .NUT SELF	Necessary	6.22 FS	*6.22 FS
73	2		*BOLTHEX HD.WITH SHOUL	Necessary	16.74 FS	*16.74 FS
74	4		*BOLT HEX .HD	Necessary	24.00 FS	*24.00 FS
75	2		*BOLT HEX .HD WITH SHOULD	Necessary	17.70 FS	*17.70 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	2		*SHOULDERED HEX .NUT SELF	Necessary	6.22 FS	*6.22 FS
77	2		*HEXAGON FLANGE SCREW	Necessary	10.78 FS	*10.78 FS
78	2		*HEXAGON COLLAR NUT SELF-L	Necessary	6.04 FS	*6.04 FS
					Total Parts (S\$)	18,796.19
						12,157.18

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	R&R REAR EXHAUST	New	840.00	420.00
4	R&R REAR SUB FRAME	New	3,360.00	840.00
5	R&R ROOFLINING	New	2,520.00	1,260.00
6	R&R FUEL TANK	New	2,520.00	840.00
7	CHANGE LINE ASSIST SYSTEM CALIBRATION	New	840.00	840.00
8	TOWING ASSISTTANCE -AWP	New	195.00	195.00
9	LABOUR FRT	New	2,520.00	840.00
10	SPRAY PAINT FRT	New	1,600.00	800.00
11	LABOUR REAR	New	10,080.00	7,560.00
12	SPRAY PAINT REAR	New	7,200.00	4,800.00
13	R&R REAR W/SCREEN	New	840.00	840.00
14	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
15	R&R REAR LUGGAGE TRIM	New	840.00	420.00
16	R&R REAR SEAT	New	840.00	420.00
17	VEHICLE ON BENCH -CELETTE	New	1,500.00	0.00
18	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (S\$)			37,445.00	21,405.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >