

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000700/T1QF3E2

Date: 03/11/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000957580
Claimant Vehicle No :	SKG3477X	Insured Vehicle No :	SKM9389X
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	251975

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG3477X	Engine No:	R18A13860130
Make & Model:	HONDA STREAM, 1.8 L RSZ (A)	Chassis No:	JHMRN6880AC200130
Reg. Date:	27/01/2010 (Man. Year: 2009)	Odometer:	106066 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,573.32	3,985.68	8,587.64	68.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,170.00	1,790.00	4,380.00	70.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,743.32	5,775.68	12,967.64	69.19
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	18,743.32	4,200.00	14,543.32	77.59
+ GST 7.00/7.00% (S\$)	1,312.03	294.00	1,018.03	77.59
Nett Amount (S\$)	20,055.35	4,494.00	15,561.35	77.59

INSPECTION

Date of Assignment:	14/01/2021	
Date Inspected:	18/01/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2021)
Parts:	M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG3477X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE	Bent	930.00 FL	*903.00 FL
2	1	*SET TAIL GATE WINDSCREEN MOULDING	Necessary	217.30 FL	*118.00 FL
3	1	*TAIL GATE POCKET HANDLE	Missing	65.00 FL	*65.00 FL
4	1	*TAIL GATE OUTER GARNISH	Not Necessary	327.50 FL	*- FL
5	2	*TAIL GATE CAR PLATE LAMP	Not Necessary	180.00 FL	*- FL
6	1	*TAIL GATE LOGO	Necessary	78.00 FL	*29.90 FL
7	1	*TAIL GATE EMBLEM (STREAM)	Necessary	98.00 FL	*31.60 FL
8	1	*TAIL GATE EMBLEM (RSZ)	Necessary	85.60 FL	*60.00 FL
9	1	*TAIL GATE LOCK	Bent	391.50 FL	*198.00 FL
10	1	*TAIL GATE CATCH	Repair	43.90 FL	*- FL
11	1	*TAIL GATE WEATHERSTRIP	Cut	262.15 FL	*121.60 FL
12	1	*TAIL GATE INNER TRIM	Not Necessary	358.70 FL	*- FL
13	1	*TAIL GATE DETECTORE SENSOR	Not Necessary	398.60 FL	*- FL
14	2	*TAIL GATE DAMPER	Not Necessary	596.60 FL	*- FL
15	2	*TAIL GATE HINGE	Not Necessary	224.00 FL	*- FL
16	1	*TAILLAMP	N/S Cracked / O/S NotNecessary	997.80 FL	*366.80 FL
17	2	*TAILLAMP LOWER GARNISH RETAINER	Not Necessary	100.00 FL	*- FL
18	1	*REAR BUMPER	Deformed	598.90 FL	*598.90 FL
19	1	*REAR BUMPER SIDE RETAINER	N/S Deformed /O/S NotNecessary	228.00 FL	*73.40 FL
20	1	*REAR BUMPER TOW HOOK COVER	Deformed	43.90 FL	*43.90 FL
21	1	*REAR BUMPER DIFFUSER	Deformed	258.90 FL	*258.90 FL
22	1	*REAR BUMPER REFLECTOR	N/S Cut / O/S Not Necessary	250.00 FL	*125.00 FL
23	1	*REAR BUMPER BRACKET (4PCS)	N/S Cracked / O/S NotNecessary	200.00 FL	*50.00 FL
24	1	*REAR BUMPER UNDER COVER	Torn	325.70 FL	*225.00 FL
25	1	*REAR FENDER INNER TRIM BOARD	N/S Deformed /O/S NotNecessary	935.60 FL	*232.00 FL
26	1	*REAR FENDER INNER COWLING	N/S Torn /O/S NotNecessary	354.60 FL	*88.20 FL
27	1	*REAR END PANEL (OUTER)	Bent	433.10 FL	*306.10 FL
28	1	*REAR END PANEL (INNER)	Repair	542.00 FL	*- FL
29	1	*REAR END PANEL TOP GARNISH	Deformed	489.00 FL	*165.40 FL
30	1	*REAR END PANEL VEHICLE JACK COVER	Not Necessary	156.00 FL	*- FL
31	1	*REAR FLOOR PANEL	Repair	1,062.70 FL	*- FL
32	2	*REAR FLOOR PANEL TOP SPONGE	Deformed	435.00 FL	*241.40 FL
33	1	*REAR FLOOR PANEL MAT	Not Necessary	366.00 FL	*- FL
34	1	*REAR FLOOR TOP BOARD (2PCS)	Deformed (1Pc Only)	560.00 FL	*280.00 FL
35	1	*REAR EXHAUST PIPE	Not Necessary	796.20 FL	*- FL
36	1	*REAR EXHAUST MOUNTING	Not Necessary	63.90 FL	*- FL
37	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
38	1	*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
39	1	*REAR BUMPER UNDER COVER CLIP	Necessary	40.00 FS	*10.00 FS
40	1	*TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
41	1	*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
42	1	*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
43	1	*TAILGATE OUTER MOULDING CLIPS	Necessary	50.00 FS	*10.00 FS
44	1	*TAIL GATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
45	1	*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*10.00 FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
48	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
49	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
50	1		*REVERSE SENSOR (4 EYE)	Not Working	450.00 FS	*200.00 FS
51	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,264.15	4,902.10
- List Item Discount on L Items 20.00/20.00% (\$)	2,690.83	916.42
Total Parts (\$)	12,573.32	3,985.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PAR6TS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	700.00
3	TUFF COAT	New	350.00	30.00
4	WIRING CHECK	New	150.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	550.00	60.00
6	REAR CHASSIS ALIGNMENT	New	650.00	0.00
7	TRANSFER TAILGATE MECHANISM	New	150.00	60.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	30.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	200.00	120.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	350.00	0.00
11	REMOVE AND INSTALL REAR VIEW CAMERA. ADJUST CAMERA ANGLE	New	150.00	30.00
12	REMOVE AND REPLACE REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			6,170.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >