

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21000705/QBA3Q2
Date: 28/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLL8229A	Insured Vehicle No :	SLZ6771P
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000208

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL8229A	Engine No:	L15Z14116772
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660HP000588
Reg. Date:	10/03/2017 (Man. Year: 2016)	Odometer:	92775 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,426.25	2,096.61	329.64	13.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,200.00	7,175.00	2,025.00	22.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,626.25	9,271.61	2,354.64	20.25
+ GST 7.00/7.00% (S\$)	813.84	649.01	164.83	20.25

Nett Amount (\$\$)	12,440.09	9,920.62	2,519.47	20.25
+ Car Rental (5.5 x S\$100.00/day + 7.00% GST) (\$\$)		588.50		
Nett Liability (\$\$)		10,509.12		

INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Kah Motor Co Sdn Bhd (HQ)
 6A MANDAI ESTATE, SINGAPORE 729903
 Singapore 729903

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2021)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL8229A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID COMPTRUNK	Crumpled	375.15 FS	*375.15 FS
2	1		*HINGE COMPR.TRUNK	Serviceable	57.30 FS	*- FS
3	1		*HINGE COMPL .TRUNK	Serviceable	57.30 FS	*- FS
4	1		*LOCK ASSYTRUNK	Jammed	75.82 FS	*75.82 FS
5	1		*WEATHERSTRIPTRUNK LID	Crumpled	60.45 FS	*60.45 FS
6	1		*GARNISH ASSYRR.LICENSE	Serviceable	52.27 FS	*- FS
7	1		*EMBLEM H	Necessary	9.22 FS	*9.22 FS
8	1		*NUT PUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
9	1		*EMBLEMRR.CITY	Necessary	9.52 FS	*9.52 FS
10	1		*EMBLEMRR.I-VTEC	Necessary	9.97 FS	*9.97 FS
11	1		*FACERR.BUMPER	Crumpled	347.77 FS	*347.77 FS
12	1		*SPACER R.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
13	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
14	1		*CLIP BUMPER	Necessary	1.72 FS	*1.72 FS
15	1		*TAILLIGHT ASSYR	Scratched	154.27 FS	*154.27 FS
16	1		*TAILLIGHT ASSYL	Cracked	154.27 FS	*154.27 FS
17	1		*LIGHT ASSY,R.LID	Scratched	61.42 FS	*61.42 FS
18	1		*LIGHT ASSYL.LID	Crumpled	61.42 FS	*61.42 FS
19	1		*PANEL COMPRR	Dented	273.37 FS	*273.37 FS
20	1		*ANTENNA ASSYL.F	Serviceable	45.60 FS	*- FS
21	1		*BUZZER ASSYSMART	Serviceable	47.17 FS	*- FS
22	1		*4PCS ACT RR .SENSOR	Shorted	320.00 FS	*320.00 FS
23	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
24	1		*LID COMPSPARE TIRE	Crumpled	36.90 FS	*36.90 FS
25	1		*LINING ASSYRR,PANEL	Crumpled	49.95 FS	*49.95 FS
26	1		*NUMBER PLATE WITH CASING -L	Scratched	45.00 FS	*45.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,426.25	2,096.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	150.00	120.00
2	REMOVE & RENEW REVERSE SENSORS	New	150.00	120.00
3	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
5	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	500.00	325.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	800.00	650.00
7	BODY JOINT SEALANT TRUNK	New	100.00	80.00
8	BODY JOINT SEALANT END PANEL	New	100.00	80.00
9	CUT OFF & RENEW RR PANEL STRAIGHTEN RR FENDER AN	New	3,500.00	2,600.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,000.00	2,500.00
Gross Labour Cost (S\$)			9,200.00	7,175.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >