

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000706/EQF3Q2

Date: 19/02/2021

REFERENCE

Insured/Claimant: TAN GUANSHENG DEXTER

Policy No: 2070040880

Date of Loss: 13/01/2021

Nature of Claim: OD

Claim No: 0029364334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS8076A**

Make & Model: KIA STONIC, 998cc (A)

Engine No: G3LCKP142067

Reg. Date: 16/03/2020 (Man. Year: 2019)

Chassis No: KNAD6811VL6369233

Colour: Yellow

Odometer: 12031 km

Engine Capacity: 998 cc

Market Value/New Car Price: S\$80,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15

Rear Tyre Size:

185/65R15

Front Left Side: Kumho 4 mm

Rear Left Side:

Kumho 4 mm

Front Right Side: Kumho 4 mm

Rear Right Side:

Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,456.00	1,588.80	3,867.20	70.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,880.00	400.00	17.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,736.00	3,468.80	4,267.20	55.16
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,436.00	3,168.80	4,267.20	57.39
+ GST 7.00/7.00% (S\$)	520.52	221.82	298.70	57.38
Nett Amount (S\$)	7,956.52	3,390.62	4,565.90	57.39

INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Dented	476.00 FL	*476.00 FL
2	1		*GRILLE-FRONT BUMPER	Cut	96.00 FL	*96.00 FL
3	1		*COVER-FR BUMPER,LWR	Not Necessary	367.00 FL	*- FL
4	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 FL	*61.00 FL
5	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	98.00 FL	*- FL
6	1		*STIFFNER-FR BPR LWR	Not Necessary	123.00 FL	*- FL
7	1		*COVER-RADIATOR GRILLE UPR	Broken	46.00 FL	*46.00 FL
8	1		*BRACKET-FR BUMPER SIDE,RH	Broken	13.00 FL	*13.00 FL
9	1		*BRACKET-FR BUMPER SIDE,LH	Broken	13.00 FL	*13.00 FL
10	1		*ORNAMENT-KIA NO 115	Necessary	32.00 FL	*32.00 FL
11	1		*LAMP ASSY-HEAD,RH	Not Necessary	1,845.00 FL	*- FL
12	1		*LAMP ASSY-HEAD,LH	Not Necessary	1,845.00 FL	*- FL
13	1		*BEAM COMPLETE-FR BUMPER	Dented	544.00 FL	*544.00 FL
14	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	556.00 FL	*- FL
15	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
16	1		*AIR GUIDE -INTERCOOLER (Supplementary)	Broken	32.00 FL	*32.00 FL
17	1		*CONDENSER ASSY-COOLER (Supplementary)	Bent	648.00 FL	*648.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,815.00	1,981.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,359.00	392.20
Total Parts (\$\$)	5,456.00	1,588.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,FRT SUPPORT PANEL,REPAIR BONNET	New	1,200.00	800.00
2	SPRAY PAINT FOR FRT BUMPER,BONNET	New	700.00	700.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
7	TOP UP AIRCON GAS	New	80.00	80.00
Gross Labour Cost (\$\$)			2,280.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >