

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000708/AGS3Q2
Date: 12/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700062440
Claimant Vehicle No :	GW634S	Insured Vehicle No :	SFM2323R
Date of Loss:	12/01/2021	Nature of Claim:	TP
		Claim No:	0869261219SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW634S	Engine No:	3C3966383
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR425004500
Reg. Date:	26/02/2003 (Man. Year: 2003)	Odometer:	318590 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,795.49	2,717.40	6,078.09	69.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,640.00	1,520.00	48.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,955.49	4,357.40	7,598.09	63.55
Approved Total (Overridden) (S\$)		3,450.00		

(S\$)	11,955.49	3,450.00	8,505.49	71.14
+ GST 7.00/7.00% (S\$)	836.88	241.50	595.38	71.14
Nett Amount (S\$)	12,792.37	3,691.50	9,100.87	71.14
+ Car Rental (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		4,051.50		

INSPECTION

Date of Assignment: 13/01/2020

Date Inspected: 13/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Lee Sheng Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	O/S Distorted	996.00 FL	*498.00 FL
2	1		*FRONT FENDER INNER SHIELD	O/S Torn	336.00 FL	*168.00 FL
3	12		*FRONT FENDER INNER SHIELD CLIP	Necessary	48.00 FL	*30.00 FL
4	1		*FRONT BUMPER SIDE RETAINER RH/LH	O/S Damaged	76.00 FL	*38.00 FL
5	1		*BONNET	Distorted	718.00 FL	*718.00 FL
6	2		*BONNET CLIP	Necessary	8.00 FL	*8.00 FL
7	2		*BONNET HINGES	Bent	114.00 FL	*114.00 FL
8	1		*BONNET LOCK LOWER	Damaged	78.00 FL	*78.00 FL
9	1		*HEADLAMP	O/S Smashed	312.00 FL	*156.00 FL
10	1		*SIDE LAMP	O/S Smashed	384.00 FL	*192.00 FL
11	2		*FENDER LAMP	Not Necessary	100.00 FL	*- FL
12	1		*GRILLE	Cracked	290.00 FL	*290.00 FL
13	2		*GRILLE EMBLEM	Necessary	150.00 FL	*45.00 FL
14	1		*FRONT BUMPER	Distorted	465.00 FL	*465.00 FL
15	1		*FRONT BUMPER BEAM	Bent	235.00 FL	*128.00 FL
16	1		*RADIATOR FAN BLADE	Not Necessary	179.40 FL	*- FL
17	1		*SUPPORT ASSY HOOD	Not Necessary	767.00 FL	*- FL
18	1		*HORN HIGH PITCHED	Not Necessary	85.00 FL	*- FL
19	1		*HORN LOW PITCHED	Not Necessary	85.00 FL	*- FL
20	1		*AIR CON CONDENSER ASSY	Not Necessary	1,575.00 FL	*- FL
21	1		*RADIATOR	Not Necessary	2,443.00 FL	*- FL
22	1		*RADIATOR FAN	Not Necessary	576.60 FL	*- FL
23	1		*RADIATOR FAN COWLING	Not Necessary	190.45 FL	*- FL
24	1		*TOP HOSE	Not Necessary	56.00 FL	*- FL
25	1		*LOWER HOSE	Not Necessary	58.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Distorted	695.20 FL	*695.20 FL
27	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
28	1		*TYRE	Not Necessary	200.00 FS	*- FS
29	1		*TYRE RIM	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,550.65	3,623.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,755.16	905.80
Total Parts (\$\$)	8,795.49	2,717.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	KNOCKING CUTTING JACKING WELDING ETC	New	1,200.00	850.00
2	SPRAY PAINTING	New	1,500.00	700.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	280.00	60.00
5	WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (S\$)			3,160.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >