

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000709/APS3Q2
Date: 07/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900003597
Claimant Vehicle No :	SFN5150Y	Insured Vehicle No :	SMH1631B
Date of Loss:	06/01/2021	Nature of Claim:	TP
		Claim No:	8156414681SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFN5150Y		
Make & Model:	NISSAN SYLPHY, 1.6 (A)	Engine No:	HR16940178C
Reg. Date:	26/03/2019 (Man. Year: 2019)	Chassis No:	MNTBBAB17Z0034678
Colour:	Blue	Odometer:	23093 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,616.04	694.17	1,921.87	73.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	970.00	1,800.00	64.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,386.04	1,664.17	3,721.87	69.10
Approved Total (Overridden) (S\$)		1,300.00		

(S\$)	5,386.04	1,300.00	4,086.04	75.86
+ GST 7.00/7.00% (S\$)	377.02	91.00	286.02	75.86
Nett Amount (S\$)	5,763.06	1,391.00	4,372.06	75.86
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		1,631.00		
Global Sum Settlement (S\$)		1,630.00		

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 13/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Lee Sheng Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	670.00 FN	*670.00 FN
2	1		*REAR BUMPER SIDE RETAINER LH	Necessary	36.30 FN	*36.30 FN
3	1		*REAR BUMPER REFLECTOR LH	Cracked	65.00 FN	*65.00 FN
4	1		*REAR BUMPER REFLECTOR RH	Not Necessary	65.00 FN	*- FN
5	1		*REAR FENDER LH	Repair	1,387.40 FN	*- FN
6	1		*TAILLAMP ASSY LHS	Not Necessary	371.90 FN	*- FN
7	1		*REAR BUMPER SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,875.60	771.30
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	259.56	77.13
Total Parts (\$\$)	2,616.04	694.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING ,JACKING ,REMOVE & REFIX	New	1,500.00	400.00
2	SPRAY PAINTING ON REAR BUMPER ,REAR FENDER REAR END PANEL ,BOOTLID ETC	New	850.00	500.00
3	WIRING	New	50.00	30.00
4	REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
5	TO APPLY ANTI RUST	New	250.00	40.00
Gross Labour Cost (S\$)			2,770.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >