

ASS. REC. BY: Pam

REF:

C04/FCI 21000710/Rira3

7460

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLU 3469 Jat Workshop m/s MOTOR IMAGEof 25, Leach Kell RdInsured: FCI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 65K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 3469 J Yr Regn: 2017, NSW

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki XV 1-6 I c.c. 1600Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 76428 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF19T3KCSJ6025199Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim orTyre Size: F: 225/60R17R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/10/2020 D.O.I. 22/01/2021Survey held at MOTOR IMAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Repair Int - 21K

Date/Time, File Pass to?



Prel. Report

Days Of Repair: _____

1)



Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.S. (\$ _____)

AGE ENTERPRISES PTE. LTD.
G KEE ROAD
APORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/0001/2021
DATE : 11-JAN-2021

AVIVA LTD
4 SHENTON WAY
#01-01 SGX CENTRE 2
S(068807)
TEL : 68279966
FAX :
WWW.AVIVA.COM.SG

OWNER'S NAME : DOMINIC WAN WAI SHEN
ADDRESS : BLK 134 JALAN BUKIT MERAH
#11-1420
S(160134)
TELEPHONE NO : 9237 2916

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 10949734
VEHICLE NO : SLU3469J
MODEL CODE : GT3BKGC
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT
ENGINE NO : FB16YB91476
CHASSIS NO : JF1GT3KC5JG025199
MILEAGE : 75611 KM
DATE IN : 11/01/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : CALVIN TAN CHONG ENG
ACCIDENT DATE : 25/10/2020

Print Date : 12/01/2021
Print Time : 11:33:50

ST FOR ACCIDENT VEHICLE REGN NO SLU3469J

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

ESTIMATE FOR VEHICLE REGN NO SLU3469J

LABOUR CHARGES 2620.00
SPARE PARTS CHARGES 357.12
GRAND TOTAL 2977.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : Rasul - Hp 90010068
SURVEYED DATE : 22/01/2021 @ 1200
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 3 days
LIABILITY : 0.00
REMARKS :

Resurvey after repair

email: rasul@lkkauto.com

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: