



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2108714
3 ANSON ROAD #16-00	INV Date	20/12/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21000711/Aea3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SFF 4442D
Insured Veh.	SBQ 8804G
Claim No.	SNM21D200266/C02
Policy No.	DMPCSNW00129422001
Accident Date	09/01/2021
Inspection Date	12/01/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21000711/Aea3q2 Date: 20/12/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBQ 8804G	Veh. Inspected	SFF 4442D
Policy No.	DMPCSNW00129422001	Coverage (\$)	0.00
Claim No.	SNM21D200266/C02	Excess (\$)	0.00
Assign From		Assign Date	12/01/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053BK4007025797	Colour	SILVER
Odometer	296881 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/01/2021	Inspection Date	12/01/2021
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFF 4442D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BOOT LID	DISTORTED	863.10	863.10
2	BOOT LID HINGE	BENT	271.60	271.60
1	BOOT LID LOGO	NECESSARY	66.80	66.80
1	BOOTLID 'CAMRY' EMBLEM	NECESSARY	49.90	49.90
1	BOOTLID '2.4' EMBLEM	NECESSARY	34.40	34.40
1	BOOT LID CHROME	CRACKED	363.10	363.10
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	113.80	-
1	BOOT LID KEY LOCK	NOT NECESSARY	268.20	-
1	BOOT LID LOCK	DAMAGED	360.20	360.20
1	BOOT LID LOCK CHECKER	BENT	36.80	36.80
1	BOOT LID RUBBER	CUT	188.80	188.80
1	BOOTLID TRIM	CRUMPLED	473.60	473.60
1	BOOT LID LAMP LH	CUT	352.10	352.10
1	BOOT LID LAMP RH	CRACKED	352.10	352.10
1	BOOT LID OPENER SWITCH	NOT NECESSARY	295.70	-
1	REAR LH FENDER	BUCKLED	991.40	991.40
1	REAR FENDER COWLING LH	NOT NECESSARY	157.40	-
1	REAR FENDER TRIM LH	NOT NECESSARY	361.60	-
1	REAR FENDER LH AIR DUCT COVER	NOT NECESSARY	184.70	-
1	REAR FENDER LH LOWER INNER PANEL	TO REPAIR SEE LABOUR	248.40	-
1	REAR DOOR LOCK LH	NOT NECESSARY	478.70	-
1	REAR DOOR RUBBER LH	NOT NECESSARY	151.60	-
1	REAR WINDSCREEN RUBBER	NECESSARY	127.20	127.20
1	REAR FENDER TRIM RH	NOT NECESSARY	361.60	-
1	SPARE TYRE PANEL	DISTORTED	925.10	925.10
1	REAR SPARE TYRE PANEL SIDE SPONGE LH	CRACKED	227.10	227.10
1	REAR SPARE TYRE TOP HARDBOARD	TORN	384.80	384.80
1	SPARE TYRE LH SCREW TRAY	DEFORMED	195.40	195.40
1	SPARE TYRE LOCK SCREW	BENT	48.40	48.40
1	REAR CHASSIS FRAME LH	DISTORTED	1,220.60	685.00

Report Ref No. CC6/CTI21000711/Aea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR PANEL	DISTORTED	682.10	682.10
1	REAR PANEL TRIM	DISTORTED	353.80	353.80
1	TAIL LAMP -RH	CRACKED	437.40	437.40
1	TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	143.10	-
1	TAIL LAMP LH	CRACKED	437.40	437.40
1	TAIL LAMP PANEL LH	DISTORTED	143.10	143.10
1	REAR BUMPER	DISTORTED	580.50	580.50
1	REAR BUMPER REINFORCEMENT	DISTORTED	420.70	420.70
2	REAR BUMPER SIDE RETAINER (LONG)	NECESSARY	154.20	154.20
2	REAR BUMPER REFLECTOR	N/S CRACKED	108.20	54.10
1	REAR PANEL ANTENNA SENSOR	CRACKED	166.70	166.70
2	REAR TOWING BRACKET	BENT	126.40	126.40
2	REAR BUMPER SCREW COVER	N/S MISSING	30.00	15.00
2	REAR BUMPER SIDE RETAINER (SHORT)	NECESSARY	95.80	95.80
1	EXHAUST PIPE	BENT	981.30	981.30
1	CENTRE EXHAUST PIPE	NOT NECESSARY	1,081.60	-
2	EXHAUST MOUNTING BRACKET	NOT NECESSARY	349.60	-
3	EXHAUST PIPE MOUNTING	NOT NECESSARY	90.90	-
1	REAR EXHAUST HEAT COVER	CRUMPLED	185.90	185.90
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	484.20	-
1	REAR KNUCKLE ARM LH	NOT NECESSARY	509.20	-
1	REAR WHEEL HUB LH	NOT NECESSARY	774.40	-
1	REAR LOWER ARM LH	NOT NECESSARY	369.60	-
1	BONNET	DENTED	1,190.30	1,190.30
1	BONNET LOCK	DAMAGED	188.90	188.90
1	BONNET LOCK BRACE PANEL	BENT	91.80	91.80
1	BONNET TRIM	NOT NECESSARY	469.20	-
2	BONNET HINGE	NOT NECESSARY	107.60	-
1	BONNET INNER RUBBER	CUT	61.90	61.90
1	BONNET OUTER RUBBER	CUT	48.60	48.60
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	905.50	-
1	FRT GRILLE	CRACKED	496.30	496.30

Report Ref No. CC6/CTI21000711/Aea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT GRILLE EMBLEM	NECESSARY	66.80	66.80
1	HEADLAMP LH	CRACKED	2,478.60	2,478.60
1	HEADLAMP RH	CRACKED	2,478.60	2,478.60
1	FRT BUMPER	DISTORTED	486.70	486.70
1	FRT BUMPER REINFORCEMENT	DISTORTED	427.10	427.10
1	FRT BUMPER SPONGE	CRACKED	197.20	197.20
2	FRT BUMPER CHROM	NECESSARY	203.80	203.80
1	FRT FOG LAMP RH	CRACKED	278.10	278.10
1	FRT FOG LAMP COVER RH	CRACKED	83.20	83.20
1	FRT FOG LAMP LH	CRACKED	278.10	278.10
1	FRT FOG LAMP COVER LH	CRACKED	83.20	83.20
2	FRT BUMPER SIDE RETAINER	NECESSARY	146.40	146.40
1	FRT TOWING COVER	NOT NECESSARY	43.20	-
1	FRT BUMPER GRILLE	DEFORMED	177.60	177.60
2	HORN	NOT NECESSARY	195.20	-
1	AIR CONDENSER	DENTED	1,436.30	1,436.30
1	AIR CONDENSER RECHARGE PIPE	NOT NECESSARY	450.20	-
2	FRT AIR CON CONDENSER SIDE GARNISH	DEFORMED	162.80	162.80
1	FRT POWER STEERING PIPE	BENT	456.40	456.40
1	RADIATOR	DENTED	1,888.30	1,888.30
1	RADIATOR LOWER LH COVER	NOT NECESSARY	156.70	-
1	RADIATOR LOWER RH COVER	NOT NECESSARY	153.60	-
	LESS 25% DISCOUNT		-8,687.13	-6,309.58
			<b>26,061.37</b>	<b>18,928.72</b>
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE CAMERA (SN)	DAMAGED	480.00	380.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET BOOTLID TRIM CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR LH FENDER COWLING CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET REAR FENDER TRIM CLIPS LH (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	60.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR FENDER TRIM CLIPS RH	NOT NECESSARY	50.00	-

Report Ref No. CC6/CTI21000711/Aea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR PANEL TRIM CLIPS (SN)	NECESSARY	40.00	10.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
1	EXHAUST CHROME PIPE COVER (SN)	NOT NECESSARY	150.00	-
1	SET BNNET TRIM CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET BONNET RUBBER CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET FRT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
1	SET FRT BUMPER GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRT NUMBER PLATE (SN)	BENT	50.00	50.00
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
			1,570.00	830.00
	<b>LABOUR</b>			
	TO CHECK WIRING .		50.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN .		120.00	120.00
	TO REMOVE AND REFIT SEAT CUSHION .		280.00	280.00
	TO REMOVE AND REFIT REVERSE CAMERA.		80.00	50.00
	TO REMOVE AND REFIT PETROL TANK .		150.00	80.00
	TO REMOVE AND REFIX REAR EXHAUST PIPE .		280.00	80.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	(REAR) TO SPRAY PAINTING.		2,000.00	1,400.00
	TO SPRAY UNDERSEAL.		200.00	150.00
	TO REMOVE AND RELACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS.INCLUSIVE OF THE REPAIR OF REAR FENDER LH LOWER INNER PANEL AND TAIL LAMP PANEL RH .		3,800.00	1,800.00
	TO REMOVE AND REFIT UNDERCARRIAGE.	NOT NECESSARY	280.00	-
	TO REMOVE AND REFIT REVERSE SENSOR .		80.00	50.00
	TO CHECK WIRING .		50.00	30.00
	TO REFILL AIRCON GAS.		120.00	120.00
	TO SPRAY UNDERSEAL.		150.00	60.00
	(FRONT) TO SPRAY PAINTING.		1,400.00	800.00

Report Ref No. CC6/CTI21000711/Aea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS.INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL .		1,500.00	600.00
			10,660.00	5,650.00
<b>GRAND TOTAL</b>			<b>38,291.37</b>	<b>25,408.72</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>19,000.00</b>

Report Ref No. CC6/CTI21000711/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFF 4442D

INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R












# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFF 4442D

RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFF 4442D

RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

