

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI21000713/KQF3Q2

**Date:** 05/02/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000510
<b>Claimant</b>		
<b>Vehicle No :</b> SHD9456T	<b>Insured Vehicle No :</b>	SMN2081A
Date of Loss: 09/01/2021	Nature of Claim: TP	Claim No: M2100215

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9456T</b>	
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No: 2ZR2C39826
Reg. Date:	01/08/2019 (Man. Year: 2018)	Chassis No: JTDKB3FU003082406
Colour:	Metallic Pearl White/Red	Odometer: 216113 km
Engine Capacity:	1798 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,958.75	5,836.89	7,121.86	54.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	2,210.00	1,380.00	38.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$)</b>	<b>16,548.75</b>	<b>8,046.89</b>	<b>8,501.86</b>	<b>51.37</b>
<b>+ GST 7.00/7.00% (\$)</b>	<b>1,158.41</b>	<b>563.28</b>	<b>595.13</b>	<b>51.37</b>
<b>Nett Amount (\$)</b>	<b>17,707.16</b>	<b>8,610.17</b>	<b>9,096.99</b>	<b>51.37</b>

### INSPECTION

Date of Assignment:	15/01/2021	
Date Inspected:	12/01/2021 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	7.0 days	

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$8,046.90

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2021)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9456T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,FRONT BUMPER	Buckled/Cut	516.00 FL	-	*516.00 FL
2	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	116.50 FL	-	*- FL
3	1		*UNIT,HEADLAMP,LH	Serviceable	1,781.10 FL	-	*- FL
4	1		*COMPUTER SUB-ASSY,HEADLAMP LH NO 1	Serviceable	960.50 FL	-	*- FL
5	1		*PANEL SUB-ASSY,FRONT DOOR,LH	Bent	1,300.70 FL	-	*1,300.70 FL
6	1		*HANDLE ASSY,FRONT DOOR OUTSIDE,LH	Serviceable	390.60 FL	-	*- FL
7	1		*WEATHERSTRIP,FRONT DOOR,LH	Serviceable	231.30 FL	-	*- FL
8	1		*HINGE ASSY,FRONT DOOR,LOWER LH	Repair	110.60 FL	-	*- FL
9	1		*HINGE ASSY,FRONT DOOR,UPPER LH	Repair	97.50 FL	-	*- FL
10	1		*TAPE,BLACK OUT,NO 1 FRT LH	Necessary	13.30 FL	-	*13.30 FL
11	1		*TAPE,BLACK OUT,NO 2 FRT LH	Necessary	43.50 FL	-	*43.50 FL
12	1		*TAPE,BLACK OUT,NO 3 FRT LH	Necessary	26.30 FL	-	*26.30 FL
13	1		*MOTOR ASSY,POWER WINDOW REGULATOR,FRT LH	Serviceable	926.00 FL	-	*- FL
14	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,LH	Serviceable	238.30 FL	-	*- FL
15	1		*PANEL SUB-ASSY,REAR DOOR,LH	Bent	1,294.90 FL	-	*1,294.90 FL
16	1		*HINGE ASSY,REAR DOOR,LOWER LH	Repair	87.10 FL	-	*- FL
17	1		*HINGE ASSY,REAR DOOR,UPPER LH	Repair	98.90 FL	-	*- FL
18	1		*TAPE,BLACK OUT,NO 1 REAR LH	Not Necessary	21.90 FL	-	*- FL
19	1		*TAPE,BLACK OUT,NO 2 REAR LH	Not Necessary	34.90 FL	-	*- FL
20	1		*TAPE,BLACK OUT,NO 3 REAR LH	Not Necessary	15.40 FL	-	*- FL
21	1		*MOTOR ASSY,POWER WINDOW REGULATOR,REAR LH	Bent	926.00 FL	-	*926.00 FL
22	1		*REGULATOR SUB-ASSY,REAR DOOR WINDOW,LH	Jammed	206.70 FL	-	*206.70 FL
23	1		*FENDER SUB-ASSY,FRONT LH	Repair	977.80 FL	-	*- FL
24	1		*EMBLEM,SIDE PANEL	Not Necessary	54.60 FL	-	*- FL
25	1		*LINER,FRONT FENDER,LH	Serviceable	202.50 FL	-	*- FL
26	1		*PANEL SUB-ASSY,QUARTER,LH	Bent	871.50 FL	-	*871.50 FL
27	1		*LINER,REAR WHEEL HOUSE,LH	Repair	139.80 FL	-	*- FL
28	1		*MOULDING ASSY,BODY ROCKER PANEL,LH	Dented/Distorted	594.80 FL	-	*594.80 FL
29	1		*REINFORCE SUB-ASSY,ROCKER,OUTER LH	Repair	583.40 FL	-	*- FL
30	1		*REINFORCEMENT SUB-ASSY,ROCKER PANEL,LH	Repair	343.40 FL	-	*- FL
31	1		*FENDER CLIP	Not Necessary	65.00 FS	-	*- FS
32	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	-	*- FS
33	1		*FRT BUMPER CLIP	Necessary	65.00 FS	-	*65.00 FS
34	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	65.00 FS	-	*- FS
35	1		*FRT DOOR STICKER	Necessary	100.00 FS	-	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
36	1		*TYRE (\$250.00)(80%)	Punctured	350.00 FS	-	*200.00 FS
37	1		*RIM COVER	Serviceable	400.00 FS	-	*- FS
38	1		*SET CLIP,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	-	*- FS
39	1		*RIM	Dented	1,879.40 F	-	*1,555.50 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>16,260.20</b>	<b>7,674.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	3,301.45	1,448.43
<b>- Nett Item Discount on N Items 0.00/25.00% (\$\$)</b>	0.00	388.88

<b>Total Parts (\$\$)</b>	<b>12,958.75</b>	<b>5,836.89</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	100.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,400.00	900.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	1,100.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	90.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>3,590.00</b>	<b>2,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >