

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000714/R1QD3N2**Date:** 06/09/2021**REFERENCE**

| | | | | |
|-------------------|------------------------|------------------|------------|------------------------|
| Insured/Claimant: | WEE GEK SUAN, MARGARET | Policy No: | 1800009264 | |
| Date of Loss: | 12/01/2021 | Nature of Claim: | OD | Claim No: 1636618878SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SME95X | Engine No: | CHZ417541 |
| Make & Model: | AUDI A3, 999cc TFSI S-TRONIC (A) | Chassis No: | WAUZZZ8VXJ1035770 |
| Reg. Date: | 05/02/2018 (Man. Year: 2017) | Odometer: | 35147 km |
| Colour: | Red | | |
| Engine Capacity: | 999 cc | | |
| Market Value/New Car Price: | S\$136,460.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 205/55R16 | Rear Tyre Size: | 205/55R16 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 62,627.00 | 40,745.40 | 21,881.60 | 34.94 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 33,504.00 | 23,074.00 | 10,430.00 | 31.13 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 96,131.00 | 63,819.40 | 32,311.60 | 33.61 |
| + GST 7.00/7.00% (S\$) | 6,729.17 | 4,467.36 | 2,261.81 | 33.61 |
| Nett Amount (S\$) | 102,860.17 | 68,286.76 | 34,573.41 | 33.61 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 15/01/2021 | | |
| Date Inspected: | 14/01/2021 | Inspected At: | 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd |
| Estimated Period of Repair: | 29.0 days | | |

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|--------------|--------------|
| 1 | 1 | | *FRONT REINFORCEMENT BEAM | Bent | 795.00 FS | *636.00 FS |
| 2 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Serviceable | 189.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER FOAM FILLER PIECE COVER | Serviceable | 122.00 FS | *- FS |
| 4 | 2 | | *FRONT FENDER-LH/RH | Bent | 1,702.00 FS | *1,360.80 FS |
| 5 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Necessary | 72.00 FS | *55.36 FS |
| 6 | 2 | | *FRONT FENDER OUTER BRACKET-LH/RH | Bent | 78.00 FS | *61.44 FS |
| 7 | 2 | | *FRONT FENDER INNER BRACKET-LH/RH | Bent | 56.00 FS | *43.68 FS |
| 8 | 2 | | *FRONT FENDER BRACE-LH/RH | Bent | 192.00 FS | *76.48 FS |
| 9 | 1 | | *RADIATOR GRILLE | Broken | 4,880.00 FS | *3,904.00 FS |
| 10 | 1 | | *RADIATOR GRILLE COVER | Serviceable | 184.00 FS | *- FS |
| 11 | 1 | | *RADIATOR GRILLE CLOSING ELEMENT | Cracked | 191.00 FS | *152.40 FS |
| 12 | 2 | | *RADIATOR GRILLE INNER COVER-LH/RH | Serviceable | 182.00 FS | *- FS |
| 13 | 1 | | *BONNET | Buckled | 3,134.00 FS | *2,507.20 FS |
| 14 | 1 | | *BONNET ATTACHMENT PARTS | Serviceable | 165.00 FS | *- FS |
| 15 | 2 | | *BONNET LID HINGE-LH/RH | Bent | 124.00 FS | *97.76 FS |
| 16 | 1 | | *BONNET GAS FILLED STRUT | Serviceable | 104.00 FS | *- FS |
| 17 | 1 | | *BONNET CATCH HOOK | Missing | 90.00 FS | *71.28 FS |
| 18 | 2 | | *BONNET STRIKER-LH/RH | Bent | 220.00 FS | *175.20 FS |
| 19 | 1 | | *BONNET EDGE PROTECTION | Missing | 28.00 FS | *22.00 FS |
| 20 | 2 | | *FRONT FENDER SIDE COVER-LH/RH | Serviceable | 82.00 FS | *- FS |
| 21 | 1 | | *BONNET CATCH HOOK | Bent | 63.00 FS | *50.32 FS |
| 22 | 2 | | *BONNET LID LOCK | Bent | 427.00 FS | *341.60 FS |
| 23 | 1 | | *BONNET BOWDEN CABLE-CENTRE | Cut | 58.00 FS | *46.00 FS |
| 24 | 1 | | *BONNET LID LOCK CABLE | Serviceable | 74.00 FS | *- FS |
| 25 | 1 | | *PLENUM CHAMBER COVER | Cut | 179.00 FS | *143.20 FS |
| 26 | 1 | | *BONNET SOUND ABSORBER | Deformed | 219.00 FS | *175.20 FS |
| 27 | 1 | | *SIGNAL HORN RETAINER-LH HIGH TONE | Serviceable | 200.00 FS | *- FS |
| 28 | 1 | | *SIGNAL HORN RETAINER-RH LOW TONE | Serviceable | 200.00 FS | *- FS |
| 29 | 2 | | *WHEEL HOUSING LINER-LH/RH | Serviceable | 338.00 FS | *- FS |
| 30 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 89.00 FS | *- FS |
| 31 | 2 | | *LED HEADLIGHT-LH/RH | Broken | 10,910.00 FS | *8,728.00 FS |
| 32 | 2 | | *MAIN LIGHT ELECTRONICS POWER MODULE-LH/RH | Broken | 1,516.00 FS | *1,212.80 FS |
| 33 | 2 | | *LED WITH HEAT SINK-LH/RH | Cracked | 1,466.00 FS | *1,172.80 FS |
| 34 | 2 | | *LIGH CONTROL SYSTEM CONTROL UNIT | Shorted | 1,114.00 FS | *891.20 FS |
| 35 | 2 | | *HEADLIGHT HOSE-LH/RH | Serviceable | 80.00 FS | *- FS |
| 36 | 2 | | *LIFT CYLINDER-LH/RH | Serviceable | 284.00 FS | *- FS |
| 37 | 1 | | *LIFT CYLINDER HOSE | Serviceable | 68.00 FS | *- FS |
| 38 | 1 | | *LOCK CARRIER | Cracked | 727.00 FS | *581.60 FS |
| 39 | 1 | | *AIRCON CONDENSER | Bent | 529.00 FS | *422.80 FS |
| 40 | 1 | | *RADIATOR | Bent | 951.00 FS | *760.40 FS |
| 41 | 1 | | *ADDITIONAL RADIATOR | Bent | 859.00 FS | *686.80 FS |
| 42 | 1 | | *READY MIX COOLANT | Necessary | 95.00 FS | *75.52 FS |
| 43 | 1 | | *RADIATOR FAN | Serviceable | 1,265.00 FS | *- FS |
| 44 | 2 | | *RADIATOR AIR GUIDE-LH/RH | Cut | 50.00 FS | *38.88 FS |
| 45 | 1 | | *RADIATOR AIR GUIDE-UPPER CENTRE | Cut | 12.00 FS | *9.44 FS |
| 46 | 1 | | *AIR INTAKE AIR DUCT COVER | Scratched | 29.00 FS | *22.72 FS |
| 47 | 1 | | *AIR INTAKE AIR INLET | Cracked | 56.00 FS | *44.48 FS |
| 48 | 1 | | *AIR INTAKE AIR GUIDE | Cracked | 20.00 FS | *15.36 FS |
| 49 | 1 | | *AIR INTAKE WATER DRAINAGE HOSE | Serviceable | 33.00 FS | *- FS |
| 50 | 1 | | *AIR INTAKE INLET DUCT | Cracked | 66.00 FS | *52.32 FS |
| 51 | 1 | | *INTER COOLER GASKET | Not Necessary | 14.00 FS | *- FS |
| 52 | 1 | | *AIR INTAKE AIR FILTER | Scratched | 272.00 FS | *217.20 FS |
| 53 | 1 | | *AIR INTAKE MANIFOLD-OUTER | Serviceable | 139.00 FS | *- FS |
| 54 | 1 | | *AIR INTAKE MANIFOLD-INNER | Serviceable | 666.00 FS | *- FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|--------------------------|-------------|--------------|
| 55 | 1 | | *AIR INTAKE MANIFOLD INNER SEAL | Not Necessary | 14.00 FS | *- FS |
| 56 | 1 | | *CHARGE AIR COOLER | Serviceable | 752.00 FS | *- FS |
| 57 | 1 | | *CHARGE AIR COOLER SEAL | Not Necessary | 14.00 FS | *- FS |
| 58 | 1 | | *CHARGE AIR COOLER SEAL | Not Necessary | 14.00 FS | *- FS |
| 59 | 1 | | *THROTTLE VALVE CONTROL ELEMENT | Serviceable | 754.00 FS | *- FS |
| 60 | 1 | | *THROTTLE VALVE SEAL | Not Necessary | 17.00 FS | *- FS |
| 61 | 1 | | *FUSE BOX COVER | Deformed | 48.00 FS | *38.24 FS |
| 62 | 1 | | *CENTAL ELECTRICAL SYSTEM HOUSING | Serviceable | 83.00 FS | *- FS |
| 63 | 1 | | *FUSE AND RELAY BOX | Serviceable | 357.00 FS | *- FS |
| 64 | 1 | | *REFRIGERANT LINE | Serviceable | 619.00 FS | *- FS |
| 65 | 1 | | *REFRIGERANT LINE | Serviceable | 475.00 FS | *- FS |
| 66 | 1 | | *WINDSCREEN | Cracked | 1,072.00 FS | *857.60 FS |
| 67 | 1 | | *RAIN SENSOR GEL FOIL | Necessary | 137.00 FS | *109.20 FS |
| 68 | 1 | | *INTERIOR MIRROR SPRING CLIP | Not Necessary | 21.00 FS | *- FS |
| 69 | 1 | | *REAR BUMPER | Deformed | 2,070.00 FS | *1,656.00 FS |
| 70 | 2 | | *REAR BUMPER LOCKING MECHANISM-LH/RH | Serviceable | 28.00 FS | *- FS |
| 71 | 2 | | *WHEEL HOUSING LINER ADAPTER-LH/RH | Serviceable | 76.00 FS | *- FS |
| 72 | 2 | | *REAR LIGHT LIGHT REFLECTOR-LH/RH | Serviceable | 82.00 FS | *- FS |
| 73 | 1 | | *REAR REINFORCEMENT BEAM | Bent | 603.00 FS | *482.00 FS |
| 74 | 1 | | *REAR BUMPER BRACKET-LH | Cracked | 27.00 FS | *21.44 FS |
| 75 | 1 | | *REAR BUMPER BRACKET-RH | Cracked | 29.00 FS | *22.48 FS |
| 76 | 2 | | *REAR BUMPER GUIDE SECTION-LH/RH | Serviceable | 134.00 FS | *- FS |
| 77 | 1 | | *REAR PARKING AID SENSOR-INNER/OUTER 3 Pcs | Not Working (2 Pcs only) | 726.00 FS | *387.20 FS |
| 78 | 4 | | *REAR PARKING AID SEAL RING | Necessary | 14.00 FS | *11.20 FS |
| 79 | 1 | | *REAR BUMPER WIRING SET | Serviceable | 515.00 FS | *- FS |
| 80 | 1 | | *REAR LID | Bent | 3,404.00 FS | *2,723.20 FS |
| 81 | 1 | | *REAR LID ATTACHMENT PARTS | Not Necessary | 295.00 FS | *- FS |
| 82 | 2 | | *REAR LID HINGE-LH/RH | Serviceable | 512.00 FS | *- FS |
| 83 | 1 | | *REAR LID FLAP GASKET | Necessary | 205.00 FS | *164.00 FS |
| 84 | 1 | | *REAR LID LOCK STRIKER | Serviceable | 50.00 FS | *- FS |
| 85 | 1 | | *REAR LID LOCK | Serviceable | 189.00 FS | *- FS |
| 86 | 1 | | *PACKING ADHESIVE | Necessary | 19.00 FS | *14.88 FS |
| 87 | 1 | | *AUDI EMBLEM | Necessary | 138.00 FS | *110.00 FS |
| 88 | 1 | | *A3 INSCRIPTION | Necessary | 99.00 FS | *79.04 FS |
| 89 | 1 | | *TFSI INSCRIPTION | Necessary | 99.00 FS | *79.04 FS |
| 90 | 1 | | *REAR CROSS PANEL TRIM | Serviceable | 155.00 FS | *- FS |
| 91 | 1 | | *REAR SILENCER | Bent | 720.00 FS | *576.00 FS |
| 92 | 1 | | *REAR SILENCER DUAL CLIP | Necessary | 59.00 FS | *46.96 FS |
| 93 | 2 | | *EXHAUST SYSTEM RETAINER | Necessary | 83.00 FS | *65.92 FS |
| 94 | 1 | | *FRONT SILENCER | Bent | 489.00 FS | *390.80 FS |
| 95 | 2 | | *FRONT SILENCER DUAL CLIP-LH/RH | Necessary | 118.00 FS | *93.92 FS |
| 96 | 1 | | *EXHAUST SYSTEM RETAINER | Serviceable | 38.00 FS | *- FS |
| 97 | 1 | | *REAR CROSS PANEL | Bent | 360.00 FS | *287.60 FS |
| 98 | 1 | | *CROSS PANEL REINFORCEMENT | Bent | 733.00 FS | *586.40 FS |
| 99 | 2 | | *REAR CROSS PANEL CONNECTING PLATE-LH/RH | Necessary | 290.00 FS | *231.20 FS |
| 100 | 2 | | *LED TAIL LIGHT-LH/RH | Serviceable | 1,754.00 FS | *- FS |
| 101 | 2 | | *LED LICENSE PLATE LIGHT | Serviceable | 202.00 FS | *- FS |
| 102 | 1 | | *REAR EXHAUST SILENCER CHROME TIPS | Bent | 528.00 FS | *528.00 FS |
| 103 | 1 | | *REAR BUMPER LOWER DIFFUSER | Cracked | 1,584.00 FS | *1,584.00 FS |
| 104 | 1 | | *FRONT BUMPER | Deformed | 1,452.00 FS | *1,452.00 FS |
| 105 | 1 | | *FRONT WINDSCREEN SEALANT | Necessary | 200.00 FS | *200.00 FS |
| 106 | 1 | | *FRONT NO PLATE | Cracked | 80.00 FS | *80.00 FS |
| 107 | 1 | | *REAR NO PLATE | Serviceable | 80.00 FS | *- FS |
| 108 | 1 | | *METAL FILLER POWDER | Necessary | 280.00 FS | *280.00 FS |
| 109 | 1 | | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |
| 110 | 1 | | *CAVITY WAX | Necessary | 140.00 FS | *140.00 FS |
| 111 | 1 | | *ACRYLIC SEALANT | Necessary | 180.00 FS | *180.00 FS |
| 112 | 1 | | *SUNDRIES | Necessary | 400.00 FS | *83.92 FS |

Report was unsubmitted during this print-out.

9/6/21, 9:47 AM

Adjuster Report

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|--|-----------|-------------------|---------------------|
| 113 | 2 | | *FRONT FENDER TOP SUPPORT CLOSING ELEMENT-LH/RH (Supplementary) | Bent | 148.00 FS | *116.56 FS |
| 114 | 2 | | *FRONT FENDER SUPPORT CONNECTING PLATE-LH/RH (Supplementary) | Bent | 658.00 FS | *525.28 FS |
| 115 | 2 | | *RADIATOR BRACKET-LH/RH (Supplementary) | Necessary | 82.00 FS | *65.28 FS |
| 116 | 2 | | *RADIATOR LOWER BUSH-LH/RH (Supplementary) | Necessary | 19.00 FS | *15.04 FS |
| 117 | 1 | | *WASH WATER RESERVOIR (Supplementary) | Deformed | 206.00 FS | *164.40 FS |
| 118 | 1 | | *ALUMINIUM RIM-RH FRONT (Supplementary) | Scratched | 1,166.00 FS | *932.80 FS |
| 119 | 1 | | *TYRE-RH FRONT (Supplementary) | Scratched | 300.00 FS | *285.00 FS |
| 120 | 1 | | *FRONT NUMBER PLATE HOLDER (Supplementary) | Cracked | 594.00 FS | *46.56 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| | | | | | Total Parts (S\$) | 62,627.00 40,745.40 |
| Report was unsubmitted during this print-out. | | | | | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|------------------|------------------|
| Labour Items | | | | |
| 1 | TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND RENEW AIRCON CONDENSER,RADIATOR AND ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS | New | 1,200.00 | 1,200.00 |
| 3 | TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE | New | 700.00 | 500.00 |
| 4 | TO RENEW FRONT WINDSCREEN | New | 480.00 | 480.00 |
| 5 | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN | New | 400.00 | 400.00 |
| 6 | TO REMOVE AND RENEW FRONT WINDSCREEN FOIL AND RESET SYSTEM | New | 300.00 | 300.00 |
| 7 | TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN | New | 200.00 | 200.00 |
| 8 | TO DISMANTLE AND RENEW FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND BOTH HEADLIGHTS | New | 5,600.00 | 3,250.00 |
| 9 | TO RESPRAY FRONT BUMPER,BOTH FRONT FENDERS,BONNET,HINGES AND BOTH UPPER A-PILLARS | New | 5,400.00 | 2,400.00 |
| 10 | TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE | New | 280.00 | 280.00 |
| 11 | TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS | New | 280.00 | 280.00 |
| 12 | TO DISLODGE AND TRANSFER REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT | New | 480.00 | 480.00 |
| 13 | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND WELD REAR END PANELLING.RE-ORGINISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 4,200.00 | 3,000.00 |
| 14 | TO RESPRAY REAR BUMPER,REAR LID,HINGES AND REAR END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS | New | 3,100.00 | 2,200.00 |
| 15 | TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE | New | 280.00 | 0.00 |
| 16 | TO RENEW REAR EXHAUST SILENCER AND CENTRE SILENCER | New | 480.00 | 480.00 |
| 17 | TO CARRY OUT PRE AND POST DISGNOSTIC CHECK | New | 384.00 | 384.00 |
| 18 | TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER (Supplementary) | New | 800.00 | 800.00 |
| 19 | TO PLACE AND SET UP VEHICLE ON CAR-O-LINER TO FACILITATE REPAIR (Supplementary) | New | 1,800.00 | 1,800.00 |
| 20 | TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORTS.TO REPAIR SPARE WHEEL HOUSING AND RE-ALIGN REAR CHASSIS FRAMES BACK TO ORIGIN SPECIFICATION (Supplementary) | New | 3,500.00 | 2,500.00 |
| 21 | TO RESPRAY BOTH FRONT FENDER TOP SUPPORTS SPARE WHEEL HOUSING AND BOTH REAR CHASSIS FRAMES (Supplementary) | New | 3,000.00 | 1,500.00 |
| 22 | TO RENEW RHS FRONT RIM WITH TYRE AND CARRY OUT WHEEL ALIGNMENT (Supplementary) | New | 280.00 | 280.00 |
| Gross Labour Cost (\$\$) | | | 33,504.00 | 23,074.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >