

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III16016434/KPA3Q2-1

Date: 09/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKG9109U	Insured Vehicle No :	SHD6601K
Date of Loss: 27/08/2016	Nature of Claim: TP	Claim No: MCT16081191

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG9109U		
Make & Model:	MERCEDES-BENZ C180 COUPE BLUE EFFICIENCY, 1.6 (A)	Engine No:	HIDDEN
Reg. Date:	01/10/2012 (Man. Year: 2012)	Chassis No:	WDD2043312F944888
Colour:	Metallic Dark Blue	Odometer:	72699 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,883.92	2,886.66	3,997.26	58.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	845.00	1,245.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,973.92	3,731.66	5,242.26	58.42
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	8,973.92	2,800.00	6,173.92	68.80
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
		(S\$)		
		3,040.00		
Liabie Amount (50.00%) (S\$)		1,520.00		
Global Sum Settlement (S\$)		1,520.00		

INSPECTION

Date of Assignment:	01/09/2016	
Date Inspected:	07/09/2016 Inspected At:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2021)
Parts:	M1-COUPE	MERCEDES-BENZ C180 COUPE BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG9109U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,368.70 FL	*1,368.70 FL
2	1		*FRONT PARKING SENSOR	Serviceable	286.30 FL	*- FL
3	1		*FRONT FENDER (ALUMINIUM)	Bent	875.90 FL	*875.90 FL
4	1		*FRONT FENDER DUST COVER	Serviceable	293.20 FL	*- FL
5	1		*FRONT HEADLAMP	Serviceable	1,183.70 FL	*- FL
6	1		*STEERING TIE ROD	Serviceable	238.50 FL	*- FL
7	1		*STEERING TIE ROD END	Serviceable	197.30 FL	*- FL
8	1		*LOWER ARM	Serviceable	438.10 FL	*- FL
9	1		*TRUST ARM	Serviceable	365.30 FL	*- FL
10	1		*KNUCKLE ARM	Serviceable	638.70 FL	*- FL
11	1		*FRONT SHOCK ABSORBER	Serviceable	613.80 FL	*- FL
12	1		*WHEEL BEARING	Serviceable	186.50 FL	*- FL
13	1		*ALLOY RIM	Dented	962.80 FL	*962.80 FL
					Sub Total (\$)	7,648.80
					- List Item Discount on L Items 10.00/10.00% (\$)	764.88
					Total Parts (\$)	6,883.92
						3,207.40
						2,886.66

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS.	New	600.00	350.00
2	TO CHECK WIRING SYSTEM.	New	50.00	15.00
3	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.	New	600.00	400.00
4	TO REMOVE & INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR.	New	220.00	0.00
5	TO REPLACE ALLOY RIM(S) & PERFORM WHEEL BALANCING.	New	80.00	20.00
6	TO MACHINE PRESS WHEEL BEARING.	New	80.00	0.00
7	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT.	New	100.00	60.00
8	DIAGNOSTIC & RESETTNG THE STEERING RACK.	New	360.00	0.00
Gross Labour Cost (\$\$)			2,090.00	845.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >