

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21000720/R1VF3Q2  
**Date:** 10/03/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00001962000
Claimant Vehicle No :	SMG5828E	Insured Vehicle No :	SMJ5098D
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200199/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG5828E	Engine No:	CZC897350
Make & Model:	VOLKSWAGEN GOLF, 1.2 (A7) TSI (A)	Chassis No:	WVWZZZAUZJW120341
Reg. Date:	26/12/2018 (Man. Year: 2017)	Odometer:	33339 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,551.34	0.00	2,551.34	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,231.34</b>	<b>2,120.00</b>	<b>6,111.34</b>	<b>74.24</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>576.19</b>	<b>148.40</b>	<b>427.79</b>	<b>74.24</b>
<b>Nett Amount (S\$)</b>	<b>8,807.53</b>	<b>2,268.40</b>	<b>6,539.13</b>	<b>74.24</b>

### INSPECTION

Date of Assignment:	15/01/2021	
Date Inspected:	20/01/2021	Inspected At: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



3/10/2021

Adjuster Report

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 08 Mar 2021)

**Parts:** 144      VOLKSWAGEN GOLF 1.2 (A7) TSI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMG5828E)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Repair	1,251.35 FS	*- FS
2	1		*REAR DIFFUSOR SATIN BLACK	Not Necessary	329.43 FS	*- FS
3	4		*RIVET	Not Necessary	4.56 FS	*- FS
4	1		*SENSOR BRACKET	Not Necessary	12.39 FS	*- FS
5	1		*SENSOR BRACKET	Not Necessary	12.39 FS	*- FS
6	1		*SENSOR BRACKET	Not Necessary	12.86 FS	*- FS
7	1		*SENSOR BRACKET	Not Necessary	12.39 FS	*- FS
8	1		*2K-PLASTIC ADHESIVE	Not Necessary	78.91 FS	*- FS
9	1		*BONDING AGENT FOR PLASTIC	Not Necessary	62.81 FS	*- FS
10	1		*ATTACHMENT STRIP RR CTR BRACKET	Not Necessary	67.89 FS	*- FS
11	1		*BUMPER REINFORCEMENT	Not Necessary	626.36 FS	*- FS
12	1		*NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **2,551.34**      **0.00**

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
3	SPRAY PAINTING	New	2,400.00	800.00
4	LABOUR	New	2,520.00	840.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >