Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000723/QTD3Q2

Date: 01/03/2021

Odometer:

**REFERENCE** 

China Taiping Insurance Policy No: Handling Insurer:

(Singapore) Pte. Ltd.

DMHCSNA00008932000

Claimant Vehicle No:

SMU9583K

Insured Vehicle No : SJQ1720R

Date of Loss: 12/01/2021 Nature of

Claim:

Claim SNM21D200226/C02/THAMYL

57862 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMU9583K Reg No:

Make & Model: BMW 116D, 1.6 (A) Engine No: 31399905B37D15A Reg. Date: 28/06/2017 (Man. Year: 2017) Chassis No: WBA1V720705G86701

Colour: Blue

**Engine Capacity:** 1496 cc Market Value/New Car

Price:

N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40R18 225/40R18 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,594.67	2,948.51	1,646.16	35.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,160.00	940.00	44.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,694.67	4,108.51	2,586.16	38.63
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,694.67	3,300.00	3,394.67	50.71
+ GST 7.00/7.00% (S\$)	468.63	231.00	237.63	50.71
Nett Amount (S\$)	7.163.30	3.531.00	3.632.30	50.71

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 15/01/2021 Inspected At: 39 WOODLANDS CLOSE

#01-34 MEGA@WOODLANDS

SINGAPORE 737856

REPAIRER: FORZA AUTOHAUS

PTE. LTD

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2021)

Parts: 144 BMW 116D 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU9583K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR CHROME TRIM	Necessary	107.00 FL	*107.00 FL	
2	1		*FRONT DOOR CHECKER	Serviceable	71.75 FL	*- FL	
3	1		*FRONT DOOR HANDLE	Serviceable	120.30 FL	*- FL	
4	2		*FRONT DOOR HINGE UPPER/LOWER	Serviceable	221.40 FL	*- FL	
5	1		*FRONT DOOR INNER TRIMBOARD	Scratched	1,040.80 FL	*970.00 FL	
6	1		*FRONT DOOR LH	Crumpled	1,088.25 FL	*1,088.25 FL	
7	1		*FRONT DOOR LOCK	Jammed	185.40 FL	*185.40 FL	
8	1		*FRONT DOOR RUBBER WEATHER STRIP	Necessary	152.80 FL	*152.80 FL	
9	1		*FRONT FENDER LH	Crumpled	600.25 FL	*600.25 FL	
10	1		*FRONT FENDER RETAINER LH	Serviceable	160.30 FL	*- FL	
11	1		*REAR DOOR LH	Repair	1,088.25 FL	*- FL	
F=Fra	anchise	part. L=ListIt	emDisc.	-			
				Sub Total (S\$)	4,836.50	3,103.70	
			- List Item Discount on L Items	s 5.00/5.00% (S\$)	241.83	155.19	
				Total Parts (S\$)	4,594.67	2,948.51	
	Report was unsubmitted during this print-out						

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	Labour Items								
1	TO REMOVE, REINSTALL FRONT DOOR WINDOW GLASS (TO FR)	New	100.00	60.00					
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00					
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00					
	Gross Labour Cost (S\$)		2,100.00	1,160.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >