LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000725/UTF3E2

Date: 29/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700057292

Claimant Vehicle
SLY82LL

F77774H

No: Insured Vehicle No: EZ7774H

Date of Loss: 20/11/2020 Nature of Claim: TP Claim No: 1328734318SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX82U

 Make & Model:
 BMW 328I, 2.0 (A)
 Engine No:
 B1620443N20B20A

 Reg. Date:
 12/06/2013 (Man. Year: 2013)
 Chassis No:
 WBA3A56080NR04614

Colour: Grey Odometer: 99268 km

Engine Capacity: 1997 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/30Z R20 Rear Tyre Size: 275/30Z R20
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/01/2021

Mask Spray Works Pte Ltd (HQ)

Date Inspected: 15/01/2021 Inspected At: 25 Kaki Bukit Road 4 #06-43, Synergy @ KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER SPORT	Cracked	0.00 F	*-F
2	1		*REAR BUMPER REFLECTOR O/S	Missing	0.00 F	*- F
3	1		*REAR BUMPER PDC SENSOR O/S	Shorted	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REAR BUMPER TOP RETAINER	Twisted	0.00 F	*- F
6	1		*REAR BUMPER INNER PLATE	Cracked	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR BUMPER DIFFUSER	Deformed	0.00 F	*- F
F=Fra	nchise	part.				
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >