

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000731/EVF3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant:	NG KAI WEN	Policy No:	1900104759	Claim No:	1917203648SG
Date of Loss:	09/01/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK1888K	Engine No:	G3LCKP029988
Make & Model:	KIA STONIC, 998cc (A)	Chassis No:	KNAD6811VK6296660
Reg. Date:	11/06/2019 (Man. Year: 2019)	Odometer:	24762 km
Colour:	Grey		
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,875.00	690.40	1,184.60	63.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,220.00	1,420.00	53.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,515.00	1,910.40	2,604.60	57.69
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	4,215.00	1,610.40	2,604.60	61.79
+ GST 7.00/7.00% (S\$)	295.05	112.73	182.32	61.79
Nett Amount (S\$)	4,510.05	1,723.13	2,786.92	61.79

INSPECTION

Date of Assignment:	15/01/2021		
Date Inspected:	15/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*MOULDING ASSY-SIDE SILL, RH	Cut	248.00 F	*248.00 FL
3	1		*GARNISH-QTR SIDE RH	Cut	50.00 F	*50.00 FL
4	1		*GARNISH ASSY-RR DR SIDE, RH	Cut	92.00 F	*92.00 FL
5	1		*GARNISH ASSY-FR DR SIDE, RH	Cut	82.00 F	*82.00 FL
6	1		*WHEEL ASSY-ALUMINIUM	Not Necessary	659.00 F	*- FL
7	1		*COVER-RR BUMPER LWR	Cut	366.00 F	*366.00 FL
8	1		*HUB ASSY-RR WHEEL	Not Necessary	358.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,875.00	858.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	167.60
Total Parts (\$)	1,875.00	690.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR REAR DOOR RH, REAR BUMPER RH, RENEW REAR BUMPER	New	800.00	600.00
2	SPRAY PAINT FOR REAR DOOR RH, REAR BUMPER	New	700.00	350.00
3	TRANSFER REAR RIGHT RIM	New	30.00	0.00
4	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	320.00	120.00
7	RENEW REAR UNDER CARRIAGE	New	640.00	0.00
Gross Labour Cost (\$\$)			2,640.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >