



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG KAI WEN (HUANG KAIWEN) BLK 469C SENGKANG WEST WAY #26-622 SINGAPORE 793469 Contact No	Cust No/Name	LCV10120/NG KAI WEN (HUANG KAIWEN)
	Reg No/Reg Date	SKK1888K / 11/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VK6296660
	Engine No	G3LCKP029988
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV10120	CRDVCH	15/01/2021/ 10:19	TLC	442 / CocoLu	27083			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800.00
REPAIR REAR DOOR RH, REAR BUMPER RH, RENEW REAR BUMPER								
E PNT98000								700.00
SPRAY PAINT FOR REAR DOOR RH, REAR BUMPER								
M SUNDRY								30.00
TRANSFER REAR RIGHT RIM								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								320.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A 90000001								640.00
RENEW REAR UNDER CARRIAGE								
M SUNDRY								20.00
Sundry								
M	MOULDING ASSY-SIDE SILL,RH				1.00	248.00	00.00	248.00
M	GARNISH-QTR SIDE RH				1.00	50.00	00.00	50.00
M	GARNISH ASSY-RR DR SIDE,RH				1.00	92.00	00.00	92.00
M	GARNISH ASSY-FR DR SIDE RH				1.00	82.00	00.00	82.00
M	WHEEL ASSY-ALUMINIUM				1.00	659.00	00.00	659.00
M	HUB ASSY-RR WHEEL				1.00	358.00	00.00	358.00
M	COVER-RR BUMPER LWR				1.00	366.00	00.00	366.00

Confirm & accepted by

Nett	4,515.00
7% GST on	4515.00
Total Payable	4,831.05

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.