



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 09.01.2021
Emailed : 22.01.2021, 5.15pm
Date Survey : 15.01.2021

VEHICLE NO : SKK 1888 K
MODEL : KIA STONIC 1.0 A
WIP : 27083

Material	:	\$	<u>670.40</u>
Labour	:	\$	<u>1,240.00</u>
Sub-Total	:	\$	<u>1,910.40</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>1,610.40</u>
GST 7%	:	\$	<u>112.73</u>
Grand Total	:	\$	<u>1,723.13</u>
Finalise By/Date	:	<u>LOI / 22/01/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK _____ WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 15/01/2021	Cust No/Name	LCV10120/NG KAI WEN (HUANG KAIWEN)
	Reg No/Reg Date	SKK1888K / 11/06/2019
	Date In/Mileage	15/01/2021/ 19852
	Chassis/Package	KNAD6811VK629666C /KC17P
	Engine No	G3LCKP029988
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	22/01/2021/ 16:51	BLC	260 / AiTing	27083		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR RH REAR DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							✓ 600.00
E PNT98000 RESPRAY ON RH REAR DOOR, REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓ 350.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							✓ 120.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE							✓ 120.00
M SUNDRY SUNDRIES							✓ 20.00
X EXC EXCESS FOR OWN DAMAGE CLAIM							-300.00
X MOULDING ASSY-SIDE SILL,RH				1.00	✓ 248.00	20.00	198.40
X GARNISH-QTR SIDE RH				1.00	✓ 50.00	20.00	40.00
X GARNISH ASSY-RR DR SIDE,RH				1.00	✓ 92.00	20.00	73.60
X GARNISH ASSY-FR DR SIDE RH				1.00	✓ 82.00	20.00	65.60
X COVER-RR BUMPER LWR				1.00	✓ 366.00	20.00	292.80
Z TEXT AIG OD CLAIM, UIL CLAIM SJP3315U DOA : 09.01.21 SURVEYOR STEVE LKK 15.01.21 POLICY NO : 1900104759							

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	670.40	Nett	1,610.40
Labour	1,220.00	7% GST on	112.73
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	1,723.13
Diagnostics Job	0.00		
Sundry/Others	-280.00		
Total(w/o GST)	1,610.40		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

Work Order: R001320
License: skk 1888 k
Technician: kfs 810119
Mileage: 24763
Date 21.1.21 10:20

Kia : Stonic : 2021- (YB CUV) : Rest of World

Front : Left

Actual	Before	Specified Range
-0°38'	-0°38'	-0°54' 0°06'
3°52'*	3°52'*	4°02' 5°02'
0°06'	-0°03'*	-0°02' 0°11'
9°06'*	9°06'*	12°30' 13°30'
8°28'*	8°28'*	11°36' 13°36'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°45'	-0°44'	-0°54' 0°06'
4°33'	4°33'	4°02' 5°02'
0°05'	-0°01'	-0°02' 0°11'
8°17'*	8°15'*	12°30' 13°30'
7°32'*	7°32'*	11°36' 13°36'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°07'	0°06'	
-0°41'	-0°41'	
0°49'	0°50'	
0°11'	-0°05'*	-0°03' 0°21'

Rear : Left

Actual	Before	Specified Range
-1°07'	-1°07'	-2°00' -1°00'
0°11'	0°11'	-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°40'	-1°40'	-2°00' -1°00'
0°07'	0°07'	-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°33'	0°33'	
0°18'	0°18'	-0°05' 0°31'
0°02'	0°02'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



STONIC(YB CU../2019/G 1.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



BCM



CLU



SMK

10/10

System

Status

Result

ENGINE

No Current DTC

Good

AT

No Current DTC

Good

ABSESC

No Current DTC

Good

AIRBAG

No Current DTC

Good

EPS

No Current DTC

Good

i-TPMS

No Current DTC

Good

System

DTC

Description

State

No Current DTC

S/W Ver.

M-E-K-01-00-0237

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0178

OS Ver.

Android 10