

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000738/KBS3Q2

Date: 30/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900114552
Claimant Vehicle No :	GBB9718U	Insured Vehicle No :	SMM4804Z
Date of Loss:	12/01/2021	Nature of Claim:	TP
		Claim No:	1240675915SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBB9718U</b>		
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No:	1KD2049486
Reg. Date:	11/11/2010 (Man. Year: 2010)	Chassis No:	JTFHT02PX00065188
Colour:	Silver	Odometer:	354123 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,218.85	2,876.40	2,342.45	44.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,780.00	970.00	35.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,968.85</b>	<b>4,656.40</b>	<b>3,312.45</b>	<b>41.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,968.85</b>	<b>3,700.00</b>	<b>4,268.85</b>	<b>53.57</b>
<b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b>		420.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,127.45</b>		

### INSPECTION

Date of Assignment:	15/01/2021	
Date Inspected:	19/01/2021 Inspected At:	LH Express Motor Trading (HQ) BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 Singapore 569541
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Bent	2,800.00 FL	*1,862.00 FL
2	1		*FENDER CENTER SLIDING GUIDE LH	Serviceable	213.00 FL	*- FL
3	1		*REAR FENDER INNER SHIELD LH	Serviceable	126.00 FL	*- FL
4	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FL	*- FL
5	1		*SLIDING DOOR LH	Bent	1,630.00 FL	*1,455.10 FL
6	1		*SLIDING DOOR LOWER GUIDE LH	Serviceable	103.30 FL	*- FL
7	1		*SLIDING DOOR WEATHER STRIP LH	Serviceable	289.30 FL	*- FL
8	1		*SLIDING DOOR LOCK LH	Repair	215.00 FL	*- FL
9	1		*REAR BUMPER	Cut	653.00 FL	*488.10 FL
10	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	35.00 FL	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
12	1		*REAR ABSORBER LH	Serviceable	280.00 FL	*- FL
13	1		*REAR TAIL LAMP LH	Serviceable	277.20 FL	*- FL
14	1		*REAR TYRE	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,891.80	3,835.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,672.95	958.80
Total Parts (\$\$)	5,218.85	2,876.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS	New	1,000.00	800.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS .TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,200.00	800.00
3	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS	New	50.00	20.00
4	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS	New	100.00	60.00
5	TO REMOVE AND REFIT ROOF LINING TO FACILITATE REPAIR	New	200.00	100.00
6	TO REMOVE /REPLACE REAR LH UNDER CARRIAGE	New	200.00	0.00
Gross Labour Cost (\$\$)			<b>2,750.00</b>	<b>1,780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >