

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000744/UBS3Q2
Date: 30/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100497065
Claimant Vehicle No :	SKH1091H	Insured Vehicle No :	SCX220U
Date of Loss:	26/12/2020	Nature of Claim:	TP
		Claim No:	4605846944SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH1091H		
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Engine No:	CDN245834
Reg. Date:	31/01/2012 (Man. Year: 2011)	Chassis No:	WAUZZZ4G3CN096669
Colour:	Brown	Odometer:	92615 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,422.12	1,971.55	450.57	18.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	420.00	500.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,342.12	2,391.55	950.57	28.44
Approved Total (Overridden) (S\$)		1,900.00		

(S\$)	3,342.12	1,900.00	1,442.12	43.15
+ GST 7.00/7.00% (S\$)	233.95	133.00	100.95	43.15
Nett Amount (S\$)	3,576.07	2,033.00	1,543.07	43.15
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
(S\$)		2,233.00		
Liabe Amount (50.00%) (S\$)		1,116.50		
Global Sum Settlement (S\$)		1,050.00		

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 2.0 days

Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. L=ListItemDisc.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=982844&extid=353767&CFID=85734985&CFTOKEN=90012f37543bed87-742F795C-FD20-CB16-2F1CDDA... 3/4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	440.00	220.00
2	LABOUR CHARGE	New	400.00	150.00
3	TO REMOVE AND RENEW SENSOR	New	80.00	50.00
Gross Labour Cost (\$\$)			920.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >