



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT   |  |                           |   |                         |
|--|--|---------------------------|---|-------------------------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |  |                           | Ref: CS/AGI21000746/Qtd3n2<br>Date: 26/03/2021<br><br>Code: AGI |                         |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                           |   |                         |
|  | Insured Veh.   | SMC 8618Y                 | Veh. Inspected  | SMN 1323J               |
|  | Policy No.   |                           | Coverage (\$)   | 0.00                    |
|  | Claim No.  | C10008710/KY              | Excess (\$)   | 0.00                    |
|  | Assign From  | IVY RATILLA               | Assign Date   | 15/01/2021              |
| 2. Vehicle Particulars & Condition   |  |                           |   |                         |
|  | Make & Model   | TOYOTA VIOS 1.5 E         | c.c   | 1496                    |
|  | Engine No.   | HIDDEN                    | Year of Reg.  | 2019                    |
|  | Chassis No.  | MR2B23F3801181454         | Colour  | SILVER                  |
|  | Odometer   | 90510 KM                  | Steering  | IN ORDER                |
|  | Brakes   | IN ORDER                  | Modification  | SPORTS RIM              |
|  | General  | FAIR                      |   |                         |
| 3. Conditions of Tyres   |  |                           |   |                         |
|  |  | Size                      | Make  | Balance                 |
|  | R/H Front Tyre   | 185/60 R15                | DUNLOP  | 6 mm                    |
|  | L/H Front Tyre   | 185/60 R15                | DUNLOP  | 6 mm                    |
|  | R/H Rear Tyre  | 185/60 R15                | DUNLOP  | 6 mm                    |
|  | L/H Rear Tyre  | 185/60 R15                | DUNLOP  | 6 mm                    |
| 4. Description of Damages  |  |                           |   |                         |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS.   |                           |   |                         |
| 5. General Information   |  |                           |   |                         |
|  | Accident Date  | 13/01/2021                | Inspect Date / Time   | 15/01/2021 ( 03:24 PM ) |
|  | Survey held at   | 60 JALAN LAM HUAT, #05-21 |   |                         |
|  | Repairer   | MY CAR CONSULTANT PTE LTD |   |                         |
| 5a. Remarks  |  |                           |   |                         |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                           |   |                         |
| 5b. Estimate Days of Repair  |  |                           |   |                         |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |                           | 3 Working Days  |                         |

Report Ref No. CS/AGI21000746/Qtd3n2

Inspected By

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.