



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 898X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	TO REPAIR SEE LABOUR	1,950.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	100.00	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	100.00	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	150.00	-
1	BONNET MERCEDES LOGO	SERVICEABLE	82.00	-
1	HEADLAMP LH	SERVICEABLE	3,500.00	-
1	HEADLAMP RH	SERVICEABLE	3,500.00	-
1	FRONT RADIATOR GRILLE	DENTED	1,500.00	1,260.00
1	FRONT RADIATOR MERCEDES LOGO	NECESSARY	160.00	118.00
1	FRONT BUMPER	BUCKLED / DENTED	1,700.00	1,530.00
1	FRONT BUMPER SPONGE	SERVICEABLE	165.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	622.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	17.00	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	17.00	-
1	FRONT BUMPER TOWING COVER LH	SERVICEABLE	60.00	-
1	FRONT BUMPER TOWING COVER RH	SERVICEABLE	60.00	-
1	FRONT BUMPER CENTER GRILLE	SERVICEABLE	450.00	-
1	FRONT BUMPER SIDE GRILLE LH	SERVICEABLE	93.00	-
1	FRONT BUMPER SIDE GRILLE RH	SERVICEABLE	93.00	-
1	FRONT BUMPER LOWER CHROME STRIP	SERVICEABLE	250.00	-
1	FRONT BUMPER LOWER SPOILER	SERVICEABLE	130.00	-
4	FRONT BUMPER SENSOR	SERVICEABLE	1,000.00	-
10	FRONT BUMPER CLIP	NECESSARY	80.00	80.00
1	FRONT BUMPER SIDE COVER LH	SERVICEABLE	140.00	-
1	FRONT BUMPER SIDE COVER RH	SERVICEABLE	140.00	-
	LESS 10% DISCOUNT		-1,605.90	-298.80
			14,453.10	2,689.20

Report Ref No. CS/AGI21000747/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE & HOLDER (SN)	DENTED	80.00	45.00
1	BODY SEALANT (SN)	NOT NECESSARY	50.00	-
1	CERAMIC COATING ON FRONT BUMPER AND BONNET (SN)	NECESSARY	1,600.00	400.00
			1,730.00	445.00
LABOUR				
TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK AND FRONT BUMPER REINFORCEMENT.			1,600.00	300.00
TO CHECK & RECONNECT ALL NECESSARY WIRING.			150.00	15.00
TO REMOVE & REFIT ALL SENSOR.			100.00	60.00
TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC).			150.00	-
TO SPRAY PAINT ON THE AFFECTED AREAS.			1,200.00	300.00
			3,200.00	675.00
GRAND TOTAL			19,383.10	3,809.20
RECOMMENDED COST OF REPAIRS				3,809.20

Report Ref No. CS/AGI21000747/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.