

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000755/KPS3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900004855

Claimant
Vehicle No : SKB9566J **Insured Vehicle No :** SMH6227C

Date of Loss: 07/01/2021 Nature of Claim: TP Claim No: 1375410311SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB9566J		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGBU278730
Reg. Date:	13/07/2011 (Man. Year: 2011)	Chassis No:	KMHDH41CMCU215363
Colour:	Metallic Grey	Odometer:	128484 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,045.92	957.20	2,088.72	68.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	520.00	1,020.00	66.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,585.92	1,477.20	3,108.72	67.79
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	4,585.92	1,150.00	3,435.92	74.92
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,457.49		

INSPECTION

Date of Assignment: 15/01/2021

Date Inspected: 18/01/2021 Inspected At:

Excel Motor (HQ)
BLK 5032 Ang Mo Kio Industrial Park
2, #01-297
Singapore 569535

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Distorted	769.50 FL	*458.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	Distorted	44.80 FL	*44.80 FL
3	1		*FRONT LH FENDER	Repair	1,227.70 FL	*- FL
4	1		*FRONT LH HEADLAMP	Mtg Cracked	1,765.40 FL	*693.70 FL
					Sub Total (S\$)	3,807.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	761.48
					Total Parts (S\$)	3,045.92

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR PANEL	New	800.00	250.00
2	SPRAY PAINT	New	600.00	250.00
3	TO APPLY RUST PROOFING	New	80.00	0.00
4	TO CHECK WIRING	New	60.00	20.00
Gross Labour Cost (\$\$)			1,540.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >