


ASS. REC. BY: Steve

REP: AIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 1900254192
 Claims No. 1296027204SG
 Sum Insured: _____ Excess: 3600
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SMA 83120 Yr Regn: 4/12/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
 Make: KIA NIRO c.c. 1580
 Colour: Blue A/C: Insured / Std / NI / N
 Sp. Reading: 15013 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: KNACC 81CVL5338365
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>13/1/21</u>	D.O.I. <u>15/1/21</u>

 Survey held at cycle & carriage
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or undercarriage
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>M/V - 105K New Car Price - 141K</u>
	<u>Confirm \$64,684.80, 35days before GST and Excess \$3600. (RED: 19722.4;23%)</u>

Date/Time, File, Pass to? : Prell. Report
 : Final Report
 Date/Time, File Return to? _____
 Prop. Formed: _____
 Lump Sum / L.B.I. Fee: _____

Days Of Repair: 35
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, FRT BOTH ² FENDER, SUPPORT ¹ PANEL, FRT LH ¹ DOOR, FRT LH BODY CHASSIS, FRT LH BODY FRAME & AFFECTED AREA REPAIR ON FRT RH DOOR & ROOF, TOP	490 X 7			2800 4800.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH ² FRT FENDER, BOTH FRT ² DOOR, (LH) BOTH SIDE ¹ ROCKER PANEL, ROOF ¹ TOP, FRT LH CHASSIS, FRT LH WHEEL HOUSIN & BOTH FRT A-PILLAR ²	350 X 10			3500 4550.00
E PNT88000 REPLACE REAR ¹ BUMPER, REAR LH ² FENDER, REAR LH ¹ DOOR & AFFECTED AREA	490 X 4			1600 2000.00
E PNT98000 PAINT WORK ON REAR ¹ BUMPER, REAR LH FENDER & REAR LH DOOR				1050.00
E PNT88000 REMOVE & INSTALL FRT RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00
M SUNDRY TO TOP UP AIRCON GAS			(photo)	? 400.00
A 11900199 REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR			(photo)	? 400.00
E PNT88000 REMOVE & INSTALL REAR HYBRID BATTERY FOR FACILITATE REPAIR				120.00
E PNT88000 TO TANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL				120.00
E PNT88000 TO TANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL			(photo)	? 4000.00
A 52900099 REMOVE & INSTALL DASH BOARD FOR FACILITATE REPAIR			(photo)	? 200.00
A 52900099 TO REMOVE & INSTALL FRT UNDER CARPET FOR FACILITATE REPAIR			(photo)	? 400.00
A 13900099 REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR			(photo)	? 240.00
E PNT88000 REMOVE & INSTALL SUN ROOF FOR FACILITATE REPAIR				180.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TO REMOVE & INSTALL REAR LH QUARTER GLASS FOR FACILITATE REPAIR				50.00
M SUNDRY				
TO APPLY REAR QUARTER GLASS SEALANT				120.00
E PNT88000				
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
E PNT88000				
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				400.00
A 33900099				
REPLACE FRT UNDERCARRIAGE				400.00
A 34900099				
REPLACE REAR UNDERCARRIAGE				120.00
A WHEELALIGNMENTBP				
To Conduct Computerize Full Wheel Alignment				150.00
M SUNDRY				
TO TANSFER RIM INCLUDING BALANCING				400.00
A 52900099				
REPLACE ROOF LINING				400.00
A 16000010				
REPLACE LH CURTAIN AIRBAG				200.00
A 52900099				
REPLACE FRT LH SEAT AIRBAG				200.00
A 52900099				
REPLACE AIR BAG CONTROL UNIT				30.00
A 54900099				
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00
A 10028901				
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				
USING HI-SCAN PRO TEST				900.00
M SUNDRY				
REPLACE ALL TYRES (Front LH & Rear LH)				50.00
M SUNDRY				
SUNDRIES				
M LAMP ASSY-HEAD,LH / BR	1.00	2102.00	20.00	1681.60

Estimate

(photo)
(photo)
(photo)
(photo)

90

600

30

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for RAKESH KUMAR BHARDWAJ.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX00000, Credit, 15/01/2021/ 14:09, BLK, 282 / Kevin Leong, 27417

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like LAMP ASSY-HEAD, RH, HORN ASSY, etc. with handwritten notes like 'X', 'MIS', and 'CRU'.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			Amount
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	COVER-DAYTIME RUNNING LIGHT,LH	/ MIS			1.00	46.00	20.00	36.80
M	COVER-DAYTIME RUNNING LIGHT,RH	/ CUT			1.00	46.00	20.00	36.80
M	LAMP ASSY-DAY RUNNING LIGHT,LH	/ BR			1.00	619.00	20.00	495.20
M	LAMP ASSY-DAY RUNNING LIGHT,RH	/ BR			1.00	619.00	20.00	495.20
M	LAMP ASSY-FRONT FOG,LH	/ MIS			1.00	223.00	20.00	178.40
M	LAMP ASSY-FRONT FOG,RH	/ MIS			1.00	223.00	20.00	178.40
M	FLAP ASSY-ACTIVE AIR,LWR	/ BR			1.00	481.00	20.00	384.80
M	DUCT ASSY-ACTIVE AIR	/ BR			1.00	64.00	20.00	51.20
M	WIRING HARNESS-FR BUMPER	/ BR			1.00	189.00	20.00	151.20
M	STIFFNER-FR BPR LWR	/ MIS			1.00	116.00	20.00	92.80
M	BRACKET-FR BUMPER SIDE,LH	/ BR			1.00	12.00	20.00	9.60
M	BRACKET-FR BUMPER SIDE,RH	/ BR			1.00	12.00	20.00	9.60
M	GUARD ASSY-FRONT WHEEL,LH	/ MIS			1.00	126.00	20.00	100.80
M	GUARD ASSY-FRONT MUD,LH	/ CUT			1.00	17.00	20.00	13.60
M	GUARD ASSY-REAR WHEEL,LH	/ CUT			1.00	158.00	20.00	126.40
M	SAB MODULE ASSY-FR,LH (Air bag)	/ BR			1.00	357.00	20.00	285.60
M	CUSHION ASSY-FR SEAT,LH	/ TN			1.00	1136.00	20.00	908.80
M	S/BELT ASSY-FR RH	/ Jammed			1.00	347.00	20.00	277.60
P	BUCKLE ASSY-FR S/BELT,LH	/ ?			2.00	82.00	20.00	131.20
M	S/BELT ASSY-FR LH	/ Jammed			1.00	347.00	20.00	277.60
M	ADJUSTER ASSY-HEIGHT	/ ?			2.00	43.00	20.00	68.80
M	TAPE-FR DR BLACK FRAME RR LH	/ NPC			1.00	14.00	20.00	11.20
M	TAPE-RR DR BLACK FRAME FR,LH	/ NPC			1.00	11.00	20.00	8.80
M	FILM-ANTI CHIPPG LH	/ NPC			1.00	15.00	20.00	12.00
M	TAPE-RR DR BLACK RR,LH	/ NPC			1.00	9.00	20.00	7.20
P	COVER-RR BUMPER,UPR	/ BR			1.00	486.00	20.00	388.80
M	COVER-RR BUMPER LWR	/ CUT			1.00	392.00	20.00	313.60
M	SKID PLATE-RR BUMPER	/ ?			1.00	98.00	20.00	78.40
M	COVER-RR BUMPER SIDE UNDER,LH	/ MIS			1.00	12.00	20.00	9.60
M	MOULDING ASSY-RR BUMPER SIDE,L	/ MIS			1.00	15.00	20.00	12.00
M	MOULDING ASSY-RR BUMPER SIDE,R	/ X			1.00	15.00	20.00	12.00
M	COVER- RR REFLECTOR, LH	/ CUT			1.00	51.00	20.00	40.80
M	LAMP ASSY-REAR FOG & R/REFL,LH	/ ?			1.00	364.00	20.00	291.20

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000		Cust No/Name	/RAKESH KUMAR BHARDWAJ
		Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
		Date In/Mileage	14/01/2021/ 0
		Chassis No	KNACCB1CVL5338365
		Engine No	G4LEKS562188
		Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
		Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET-RR BEAM UPR MTG, LH X	1.00	5.00	20.00	4.00
M BRACKET-RR BEAM LWR MTG, LH X	1.00	5.00	20.00	4.00
M BRACKET-RR RAIL LWR MTG X	1.00	5.00	20.00	4.00
M BRACKET-RR BEAM UPR MTG, RH X	2.00	5.00	20.00	8.00
M BRACKET-RR BEAM LWR MTG, LH X	1.00	261.00	20.00	208.80
M BEAM-RR BUMPER X	1.00	39.00	20.00	31.20
M ANTENNA ASSY-SMARTKEY X	1.00	67.00	20.00	53.60
M STAY-RR BUMPER LH X	1.00	67.00	20.00	53.60
M STAY-RR BUMPER RH X	1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BUMPER SIDE, LH BR	1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BUMPER SIDE, RH BR	1.00	368.00	20.00	294.40
M GLASS & MOULDING ASSY-QUARTER X	1.00	1222.00	20.00	977.60
M PANEL ASSY-HOOD DD	1.00	385.00	20.00	308.00
M PANEL-FENDER, LH DD	1.00	385.00	20.00	308.00
M PANEL-FENDER, RH DD	1.00	46.00	20.00	36.80
M INSULATOR-FENDER LH CRU	1.00	46.00	20.00	36.80
M INSULATOR-FENDER RH X	1.00	661.00	20.00	528.80
M BEAM COMPLETE-FR BUMPER DD	1.00	675.00	20.00	540.00
M CARRIER ASSY-FRONT END MODULE BR	1.00	30.00	20.00	24.00
M BRACKET ASSY-FENDER MTG FR, LH MIS	1.00	810.00	20.00	648.00
M CROSSMEMBER COMPL BT	1.00	22.00	20.00	17.60
M STAY LH X	1.00	22.00	20.00	17.60
M STAY RH X	1.00	286.00	20.00	228.80
M ARM COMPLETE-FR LWR, LH BT	1.00	286.00	20.00	228.80
M ARM COMPLETE-FR LWR, RH BT	1.00	1466.00	20.00	1172.80
M PANEL ASSY-FRONT DOOR, LH DD	1.00	1542.00	20.00	1233.60
M PANEL ASSY-REAR DOOR, LH DD	1.00	33.00	20.00	26.40
M HINGE ASSY-REAR DOOR UPPER, LH ?	1.00	26.00	20.00	20.80
M HINGE ASSY-DOOR UPPER, LH	1.00	1207.00	20.00	965.60
M PANEL ASSY-QUARTER OUTER, LH DD	1.00	649.00	20.00	519.20
M PANEL-SIDE SILL OUTER, LH ?	1.00	832.00	20.00	665.60
M GEAR ASSY-STEERING BT	1.00	584.00	20.00	467.20
M BRAKE ASSY-FR, LH TN	1.00			

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACCB1CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
L4100000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417				
Description of Goods / Services									
M		KNUCKLE-FRONT AXLE, LH	BT	?		1.00	350.00	20.00	280.00
M		COVER-FR BRAKE DISC DUST LH				1.00	29.00	20.00	23.20
M		HUB ASSY-FR WHEEL	BR			1.00	436.00	20.00	348.80
M		DISC-FRONT WHEEL BRAKE	?			1.00	241.00	20.00	192.80
M		SENSOR ASSY-FR ABS, LH	TN			1.00	279.00	20.00	223.20
M		HOSE-BRAKE FRONT, LH	TN			1.00	84.00	20.00	67.20
M		HOSE-BRAKE REAR, LH	X			1.00	59.00	20.00	47.20
M		BAR ASSY-FR STABILIZER	?			1.00	238.00	20.00	190.40
M		LINK-STABILIZER	(CRH & LH) - BT			2.00	72.00	20.00	115.20
M		STRUT ASSY-FR, LH	BT			1.00	277.00	20.00	221.60
M		BUMPER-RUBBER	?			1.00	50.00	20.00	40.00
M		COVER-FR SUSPENSION STRUT DUST	BT			1.00	28.00	20.00	22.40
M		STRUT ASSY-FR, RH	BT			1.00	277.00	20.00	221.60
M		PAD-FRONT SPRING, LWR	X			1.00	23.00	20.00	18.40
M		SPRING-FR	X			1.00	141.00	20.00	112.80
M		BEARING-STRUT	?			1.00	86.00	20.00	68.80
M		INSULATOR ASSY-STRUT	?			1.00	85.00	20.00	68.00
M		COVER-INSULATOR DUST	?			1.00	5.00	20.00	4.00
M		CROSSMEMBER-RR	?			1.00	637.00	20.00	509.60
M		ARM ASSY-RR ASSIST	?			1.00	90.00	20.00	72.00
M		ARM COMPLETE-RR LWR, LH	?			1.00	379.00	20.00	303.20
M		BAR ASSY-RR STABILIZER	?			1.00	216.00	20.00	172.80
M		ARM & BUSH ASSY-SUSP UPR, LH	?			1.00	108.00	20.00	86.40
M		ARM ASSY-RR TRAILING ARM, LH	?			1.00	117.00	20.00	93.60
M		PAD-REAR SPRING, UPR	?			1.00	22.00	20.00	17.60
M		SHOCK ABSORBER ASSY-REAR	?			1.00	274.00	20.00	219.20
M		BUMPER-RUBBER	?			1.00	39.00	20.00	31.20
M		BRACKET-SHOCK ABSORBER MTG	?			1.00	60.00	20.00	48.00
M		BRAKE ASSY-RR WHEEL, LH	?			1.00	584.00	20.00	467.20
M		CARRIER ASSY-REAR AXLE, LH	?			1.00	373.00	20.00	298.40
M		HUB & BEARING ASSY-RR	OR			1.00	437.00	20.00	349.60
M		COVER-DUST RR, LH	BT			1.00	27.00	20.00	21.60
M		DISC-REAR BRAKE	MIS			1.00	210.00	20.00	168.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / RAKESH KUMAR BHARDWAJ Reg No/Reg Date SMQ8312D*ECB1/ 04/12/201 Date In/Mileage 14/01/2021/ 0 Chassis No KNACC81CVL5338365 Engine No G4LEKS562188 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M WHEEL ASSY-ALUMINIUM (Front RH & LH, Rear LH) - GR	3.00	629.00	20.00	1509.60
M SHAFT ASSY-DRIVE, LH - GR	1.00	751.00	20.00	600.80
M BOOT KIT-FR AXLE WHEEL SIDE	1.00	90.00	20.00	72.00
M BOOT KIT-FR AXLE DIFF SIDE, LH	1.00	78.00	20.00	62.40
M SHAFT ASSY-DRIVE, RH	1.00	1133.00	20.00	906.40
M TRANSMISSION ASSY-DCT - CUT	1.00	14258.00	20.00	11406.40
M ACTUATOR ASSY-CLUTCH(1) - GR	1.00	2356.00	20.00	1884.80
M CONDENSER ASSY-COOLER - OT	1.00	639.00	20.00	511.20
M RADIATOR ASSY-COOLER	1.00	768.00	20.00	614.40
M RADIATOR ASSY-INVERTER	1.00	492.00	20.00	393.60
M RADIATOR ASSY	1.00	29.00	20.00	23.20
M GUARD-AIR, LH	1.00	546.00	20.00	436.80
M BLOWER ASSY	1.00	296.00	20.00	236.80
M PANEL ASSY-UNDER COVER	1.00	1492.00	20.00	1193.60
M T/M CONTROL UNIT	1.00	1501.00	20.00	1200.80
M ELECTRONIC CONTROL UNIT	1.00	123.00	20.00	98.40
M GARNISH ASSY-FNDR SIDE, LH - MIS	1.00	123.00	20.00	98.40
M GARNISH ASSY-FNDR SIDE, RH	1.00	171.00	20.00	136.80
M MOULDING ASSY-FRT DR W/LINE, LH - MIS	1.00	113.00	20.00	90.40
M MOULDING ASSY-RR DR W/LINE, LH	1.00	144.00	20.00	115.20
M GARNISH ASSY-QTR SIDE, LH - MIS	1.00	201.00	20.00	160.80
M MOULDING ASSY-SIDE SILL, LH - CUT	1.00	201.00	20.00	160.80
M MOULDING ASSY-SIDE SILL, RH	1.00	201.00	20.00	160.80
M SENSOR ASSY-PRESS SIDE IMPACT - NEC	1.00	110.00	20.00	88.00
M SENSOR ASSY-SIDE IMPACT - NEC	1.00	83.00	20.00	66.40
M MODULE ASSY-AIR BAG CONTROL - NEC	1.00	860.00	20.00	688.00
M NIRO HYBRID EMBLEM - MIS	2.00	30.00	20.00	48.00

Estimate

Steve CLKK)
 OO- Nm AnL
 Excess - ?
 15/1/20, 4.90pm
 P/P
 By B/L sm
 23 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To resurvey (damaged parts) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett	73,996.80
7% GST on	5179.78
Total Payable	79,176.58

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.