



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 REPLACE FRT BUMPER, BONNET, FRT BOTH FENDER, SUPPORT PANEL, FRT LH DOOR, FRT LH BODY CHASSIS, FRT LH BODY FRAME & AFFECTED AREA REPAIR ON FRT RH DOOR & ROOF TOP				4800.00	
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, BOTH FRT DOOR, BOTH SIDE ROCKER PANEL, ROOF TOP, FRT LH CHASSIS, FRT LH WHEEL HOUSIN & BOTH FRT A-PILLAR				4550.00	
E PNT88000 REPLACE REAR BUMPER, REAR LH FENDER, REAR LH DOOR & AFFECTED AREA				2000.00	
E PNT98000 PAINT WORK ON REAR BUMPER, REAR LH FENDER & REAR LH DOOR				1050.00	
E PNT88000 REMOVE & INSTALL FRT RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00	
M SUNDRY TO TOP UP AIRCON GAS				80.00	
A 11900199 REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR				400.00	
E PNT88000 REMOVE & INSTALL REAR HYBRID BATTERY FOR FACILITATE REPAIR				400.00	
E PNT88000 TO TANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL				120.00	
E PNT88000 TO TANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL				120.00	
A 52900099 REMOVE & INSTALL DASH BOARD FOR FACILITATE REPAIR				4000.00	
A 52900099 TO REMOVE & INSTALL FRT UNDER CARPET FOR FACILITATE REPAIR				200.00	
A 13900099 REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR				400.00	
E PNT88000 REMOVE & INSTALL SUN ROOF FOR FACILITATE REPAIR				240.00	
E PNT88000				180.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY TO REMOVE & INSTALL REAR LH QUARTER GLASS FOR FACILITATE REPAIR				50.00
E PNT88000 TO APPLY REAR QUARTER GLASS SEALANT				120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
A 33900099 REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				400.00
A 34900099 REPLACE FRT UNDERCARRIAGE				400.00
A WHEELALIGNMENTBP REPLACE REAR UNDERCARRIAGE				120.00
M SUNDRY To Conduct Computerize Full Wheel Alignment				150.00
A 52900099 TO TANSFER RIM INCLUDING BALANCING				400.00
A 16000010 REPLACE ROOF LINING				400.00
A 52900099 REPLACE LH CURTAIN AIRBAG				200.00
A 52900099 REPLACE FRT LH SEAT AIRBAG				200.00
A 54900099 REPLACE AIR BAG CONTROL UNIT				30.00
A 10028901 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00
M SUNDRY TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				900.00
M SUNDRY USING HI-SCAN PRO TEST				50.00
M SUNDRY REPLACE ALL TYRES				1681.60
M SUNDRY SUNDRIES				
M LAMP ASSY-HEAD,LH	1.00	2102.00	20.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M LAMP ASSY-HEAD,RH	1.00	2102.00	20.00	1681.60	
M LAMP ASSY-REAR COMB INSIDE,LH	1.00	636.00	20.00	508.80	
M LAMP ASSY-REAR COMB OUTSIDE,LH	1.00	775.00	20.00	620.00	
M HORN ASSY-LOW PITCH	1.00	79.00	20.00	63.20	
M HORN ASSY-HIGH PITCH	1.00	79.00	20.00	63.20	
M PAD-HOOD INSULATING	1.00	213.00	20.00	170.40	
M MOULDING ASSY-FRONT FRAME,LH	1.00	48.00	20.00	38.40	
M W/STRIP ASSY-FR DR BELT O/S LH	1.00	54.00	20.00	43.20	
M W/STRIP ASSY-FR DR SIDE LH	1.00	111.00	20.00	88.80	
M W/STRIP-FR DR BODY SIDE LH	1.00	109.00	20.00	87.20	
M HANDLE ASSY-DOOR OUTSIDE	1.00	66.00	20.00	52.80	
M COVER-FR DR O/S HDL	1.00	24.00	20.00	19.20	
M MOULDING ASSY-RR DR FRAME,LH	1.00	33.00	20.00	26.40	
M W/STRIP ASSY-RR DR BELT O/S LH	1.00	50.00	20.00	40.00	
M W/STRIP ASSY-RR DR SIDE LH	1.00	122.00	20.00	97.60	
M HANDLE ASSY-DOOR OUTSIDE	1.00	42.00	20.00	33.60	
M COVER-FR DR O/S HDL,PASSENGER	1.00	24.00	20.00	19.20	
M DOOR ASSY-FUEL FILLER	1.00	48.00	20.00	38.40	
M TRIM ASSY-LUGGAGE SIDE LH	1.00	330.00	20.00	264.00	
M HEADLINING ASSY	1.00	1563.00	20.00	1250.40	
M TRIM ASSY-CTR PILLAR UPR LH	1.00	70.00	20.00	56.00	
M UNDER COVER ASSY,LH	1.00	191.00	20.00	152.80	
P COVER-FR BUMPER UPR	1.00	637.00	20.00	509.60	
M STRIP ASSY-FR BUMPER UPR	1.00	28.00	20.00	22.40	
M COVER-FR BUMPER,LWR	1.00	373.00	20.00	298.40	
M LIP ASSY-FRONT BUMPER	1.00	38.00	20.00	30.40	
M SKID PLATE-FR BUMPER	1.00	60.00	20.00	48.00	
M PIECE-FRT BUMPER GUARD LWR,LH	1.00	16.00	20.00	12.80	
M PIECE-FRT BUMPER GUARD LWR,RH	1.00	16.00	20.00	12.80	
M COVER ASSY-RADIATOR GRILLE UPR	1.00	40.00	20.00	32.00	
M GRILLE ASSY-RADIATOR	1.00	441.00	20.00	352.80	
M ABSORBER-FRONT BUMPER ENERGY	1.00	68.00	20.00	54.40	
M GRILLE-FRONT BUMPER	1.00	131.00	20.00	104.80	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M COVER-DAYTIME RUNNING LIGHT,LH		1.00	46.00	20.00	36.80
M COVER-DAYTIME RUNNING LIGHT,RH		1.00	46.00	20.00	36.80
M LAMP ASSY-DAY RUNNING LIGHT,LH		1.00	619.00	20.00	495.20
M LAMP ASSY-DAY RUNNING LIGHT,RH		1.00	619.00	20.00	495.20
M LAMP ASSY-FRONT FOG,LH		1.00	223.00	20.00	178.40
M LAMP ASSY-FRONT FOG,RH		1.00	223.00	20.00	178.40
M FLAP ASSY-ACTIVE AIR,LWR		1.00	481.00	20.00	384.80
M DUCT ASSY-ACTIVE AIR		1.00	64.00	20.00	51.20
M WIRING HARNESS-FR BUMPER		1.00	189.00	20.00	151.20
M STIFFNER-FR BPR LWR		1.00	116.00	20.00	92.80
M BRACKET-FR BUMPER SIDE,LH		1.00	12.00	20.00	9.60
M BRACKET-FR BUMPER SIDE,RH		1.00	12.00	20.00	9.60
M GUARD ASSY-FRONT WHEEL,LH		1.00	126.00	20.00	100.80
M GUARD ASSY-FRONT MUD,LH		1.00	17.00	20.00	13.60
M GUARD ASSY-REAR WHEEL,LH		1.00	158.00	20.00	126.40
M SAB MODULE ASSY-FR,LH		1.00	357.00	20.00	285.60
M CUSHION ASSY-FR SEAT,LH		1.00	1136.00	20.00	908.80
M S/BELT ASSY-FR RH		1.00	347.00	20.00	277.60
P BUCKLE ASSY-FR S/BELT,LH		2.00	82.00	20.00	131.20
M S/BELT ASSY-FR LH		1.00	347.00	20.00	277.60
M ADJUSTER ASSY-HEIGHT		2.00	43.00	20.00	68.80
M TAPE-FR DR BLACK FRAME RR LH		1.00	14.00	20.00	11.20
M TAPE-RR DR BLACK FRAME FR,LH		1.00	11.00	20.00	8.80
M FILM-ANTI CHIPPG LH		1.00	15.00	20.00	12.00
M TAPE-RR DR BLACK RR,LH		1.00	9.00	20.00	7.20
P COVER-RR BUMPER,UPR		1.00	486.00	20.00	388.80
M COVER-RR BUMPER LWR		1.00	392.00	20.00	313.60
M SKID PLATE-RR BUMPER		1.00	98.00	20.00	78.40
M COVER-RR BUMPER SIDE UNDER,LH		1.00	12.00	20.00	9.60
M MOULDING ASSY-RR BUMPER SIDE,L		1.00	15.00	20.00	12.00
M MOULDING ASSY-RR BUMPER SIDE,R		1.00	15.00	20.00	12.00
M COVER- RR REFLECTOR, LH		1.00	51.00	20.00	40.80
M LAMP ASSY-REAR FOG & R/REFL,LH		1.00	364.00	20.00	291.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET-RR BEAM UPR MTG,LH	1.00	5.00	20.00	4.00
M BRACKET-RR BEAM LWR MTG,LH	1.00	5.00	20.00	4.00
M BRACKET-RR RAIL LWR MTG	1.00	5.00	20.00	4.00
M BRACKET-RR BEAM UPR MTG,RH	1.00	5.00	20.00	4.00
M BRACKET-RR BEAM LWR MTG,LH	2.00	5.00	20.00	8.00
M BEAM-RR BUMPER	1.00	261.00	20.00	208.80
M ANTENNA ASSY-SMARTKEY	1.00	39.00	20.00	31.20
M STAY-RR BUMPER LH	1.00	67.00	20.00	53.60
M STAY-RR BUMPER RH	1.00	67.00	20.00	53.60
M BRACKET ASSY-RR BUMPER SIDE,LH	1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BUMPER SIDE,RH	1.00	25.00	20.00	20.00
M GLASS & MOULDING ASSY-QUARTER	1.00	368.00	20.00	294.40
M PANEL ASSY-HOOD	1.00	1222.00	20.00	977.60
M PANEL-FENDER,LH	1.00	385.00	20.00	308.00
M PANEL-FENDER,RH	1.00	385.00	20.00	308.00
M INSULATOR-FENDER LH	1.00	46.00	20.00	36.80
M INSULATOR-FENDER RH	1.00	46.00	20.00	36.80
M BEAM COMPLETE-FR BUMPER	1.00	661.00	20.00	528.80
M CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00
M BRACKET ASSY-FENDER MTG FR,LH	1.00	30.00	20.00	24.00
M CROSSMEMBER COMPL	1.00	810.00	20.00	648.00
M STAY LH	1.00	22.00	20.00	17.60
M STAY RH	1.00	22.00	20.00	17.60
M ARM COMPLETE-FR LWR,LH	1.00	286.00	20.00	228.80
M ARM COMPLETE-FR LWR,RH	1.00	286.00	20.00	228.80
M PANEL ASSY-FRONT DOOR,LH	1.00	1466.00	20.00	1172.80
M PANEL ASSY-REAR DOOR,LH	1.00	1542.00	20.00	1233.60
M HINGE ASSY-REAR DOOR UPPER,LH	1.00	33.00	20.00	26.40
M HINGE ASSY-DOOR UPPER,LH	1.00	26.00	20.00	20.80
M PANEL ASSY-QUARTER OUTER,LH	1.00	1207.00	20.00	965.60
M PANEL-SIDE SILL OUTRER,LH	1.00	649.00	20.00	519.20
M GEAR ASSY-STEERING	1.00	832.00	20.00	665.60
M BRAKE ASSY-FR,LH	1.00	584.00	20.00	467.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M KNUCKLE-FRONT AXLE,LH	1.00	350.00	20.00	280.00	
M COVER-FR BRAKE DISC DUST LH	1.00	29.00	20.00	23.20	
M HUB ASSY-FR WHEEL	1.00	436.00	20.00	348.80	
M DISC-FRONT WHEEL BRAKE	1.00	241.00	20.00	192.80	
M SENSOR ASSY-FR ABS,LH	1.00	279.00	20.00	223.20	
M HOSE-BRAKE FRONT,LH	1.00	84.00	20.00	67.20	
M HOSE-BRAKE REAR,LH	1.00	59.00	20.00	47.20	
M BAR ASSY-FR STABILIZER	1.00	238.00	20.00	190.40	
M LINK-STABILIZER	2.00	72.00	20.00	115.20	
M STRUT ASSY-FR,LH	1.00	277.00	20.00	221.60	
M BUMPER-RUBBER	1.00	50.00	20.00	40.00	
M COVER-FR SUSPENSION STRUT DUST	1.00	28.00	20.00	22.40	
M STRUT ASSY-FR,RH	1.00	277.00	20.00	221.60	
M PAD-FRONT SPRING,LWR	1.00	23.00	20.00	18.40	
M SPRING-FR	1.00	141.00	20.00	112.80	
M BEARING-STRUT	1.00	86.00	20.00	68.80	
M INSULATOR ASSY-STRUT	1.00	85.00	20.00	68.00	
M COVER-INSULATOR DUST	1.00	5.00	20.00	4.00	
M CROSSMEMBER-RR	1.00	637.00	20.00	509.60	
M ARM ASSY-RR ASSIST	1.00	90.00	20.00	72.00	
M ARM COMPLETE-RR LWR,LH	1.00	379.00	20.00	303.20	
M BAR ASSY-RR STABILIZER	1.00	216.00	20.00	172.80	
M ARM & BUSH ASSY-SUSP UPR,LH	1.00	108.00	20.00	86.40	
M ARM ASSY-RR TRAILING ARM,LH	1.00	117.00	20.00	93.60	
M PAD-REAR SPRING,UPR	1.00	22.00	20.00	17.60	
M SHOCK ABSORBER ASSY-REAR	1.00	274.00	20.00	219.20	
M BUMPER-RUBBER	1.00	39.00	20.00	31.20	
M BRACKET-SHOCK ABSORBER MTG	1.00	60.00	20.00	48.00	
M BRAKE ASSY-RR WHEEL,LH	1.00	584.00	20.00	467.20	
M CARRIER ASSY-REAR AXLE,LH	1.00	373.00	20.00	298.40	
M HUB & BEARING ASSY-RR	1.00	437.00	20.00	349.60	
M COVER-DUST RR,LH	1.00	27.00	20.00	21.60	
M DISC-REAR BRAKE	1.00	210.00	20.00	168.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M WHEEL ASSY-ALUMINIUM	3.00	629.00	20.00	1509.60
M SHAFT ASSY-DRIVE,LH	1.00	751.00	20.00	600.80
M BOOT KIT-FR AXLE WHEEL SIDE	1.00	90.00	20.00	72.00
M BOOT KIT-FR AXLE DIFF SIDE,LH	1.00	78.00	20.00	62.40
M SHAFT ASSY-DRIVE,RH	1.00	1133.00	20.00	906.40
M TRANSMISSION ASSY-DCT	1.00	14258.00	20.00	11406.40
M ACTUATOR ASSY-CLUTCH(1)	1.00	2356.00	20.00	1884.80
M CONDENSER ASSY-COOLER	1.00	639.00	20.00	511.20
M RADIATOR ASSY-INVERTER	1.00	768.00	20.00	614.40
M RADIATOR ASSY	1.00	492.00	20.00	393.60
M GUARD-AIR,LH	1.00	29.00	20.00	23.20
M BLOWER ASSY	1.00	546.00	20.00	436.80
M PANEL ASSY-UNDER COVER	1.00	296.00	20.00	236.80
M T/M CONTROL UNIT	1.00	1492.00	20.00	1193.60
M ELECTRONIC CONTROL UNIT	1.00	1501.00	20.00	1200.80
M GARNISH ASSY-FNDR SIDE,LH	1.00	123.00	20.00	98.40
M GARNISH ASSY-FNDR SIDE,RH	1.00	123.00	20.00	98.40
M MOULDING ASSY-FRT DR W/LINE,LH	1.00	171.00	20.00	136.80
M MOULDING ASSY-RR DR W/LINE,LH	1.00	113.00	20.00	90.40
M GARNISH ASSY-QTR SIDE,LH	1.00	144.00	20.00	115.20
M MOULDING ASSY-SIDE SILL,LH	1.00	201.00	20.00	160.80
M MOULDING ASSY-SIDE SILL,RH	1.00	201.00	20.00	160.80
M SENSOR ASSY-PRESS SIDE IMPACT	1.00	110.00	20.00	88.00
M SENSOR ASSY-SIDE IMPACT	1.00	83.00	20.00	66.40
M MODULE ASSY-AIR BAG CONTROL	1.00	860.00	20.00	688.00
M NIRO HYBRID EMBLEM	2.00	30.00	20.00	48.00

Confirm & accepted by

Nett	73,996.80
7% GST on	73996.80
Total Payable	79,176.58

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.