

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000764/QQF3E2

Date: 04/02/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900083554		
Claimant Vehicle No :	SDS316S	Insured Vehicle No :	SMK4652E		
Date of Loss:	13/01/2021	Nature of Claim:	TP	Claim No:	1426702540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS316S	Engine No:	27091030753501
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)	Chassis No:	WDC1569422J166236
Reg. Date:	21/01/2016 (Man. Year: 2015)	Odometer:	102884 km
Colour:	Purple		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/01/2021	Toh Painting & Services Pte Ltd (HQ)
Date Inspected:	18/01/2021 Inspected At:	BLK 3 WOODLANDS ROAD, UNIT 391C&G YEW
		TEE INDUSTRIAL ESTATE
		Singapore 677966
Estimated Period of Repair:	6.0 days	

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	0.00 F	*- F
2	1		*REAR BUMPER UPPER (BLACK)	Crushed	0.00 F	*- F
3	1		*REAR BUMPER LOWER (SILVER)	Crushed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*REAR BUMPER MOULDING UPPER	Necessary	0.00 F	*- F
7	2		*REVERSE SENSOR LH	Shorted	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Crushed	0.00 F	*- F
9	1		*REAR LH TAILLAMP PANEL	Crushed	0.00 F	*- F
10	1		*TAILGATE	Dented	0.00 F	*- F
11	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
12	1		*TAILGATE LAMP	Crushed	0.00 F	*- F
13	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
14	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
15	1		*TAILGATE RUBBER	Crushed	0.00 F	*- F
16	1		*REAR EXHAUST CHROME PIPE LH	Scratched	0.00 F	*- F
17	1		*REAR LH FENDER	Crushed	0.00 F	*- F
18	1		*REAR LH FENDER PROTECTOR GARNISH	Crushed	0.00 F	*- F
19	1		*REAR LH DOOR	Repair	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >