

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000783/UVD3Q2

Date: 02/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001555398

Claimant
Vehicle No : GBG8949A

Insured Vehicle No : GBJ2870R

Date of Loss: 13/01/2021

Nature of Claim: TP

Claim No: 252184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG8949A**

Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT
GLAZE (M)

Engine No: 263A50008124166

Reg. Date: 28/11/2017 (Man. Year: 2017)

Chassis No: ZFA26300006H12639

Colour: White

Odometer: 134907 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16

Rear Tyre Size:

195/60R16

Front Left Side: Lassa 6 mm

Rear Left Side:

Lassa 6 mm

Front Right Side: Lassa 6 mm

Rear Right Side:

Lassa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	59,250.90	20,800.90	38,450.00	64.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,450.00	4,000.00	3,450.00	46.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,700.90	24,800.90	41,900.00	62.82
Approved Total (Overridden) (S\$)		15,000.00		
Nett Amount (S\$)	66,700.90	15,000.00	51,700.90	77.51

INSPECTION

Date of Assignment: 15/01/2021

Date Inspected: 18/01/2021 Inspected At:

Liu's Brother Auto Engineering
Workshop (HQ)

BLK 1 KAKI BUKIT AVE 6, #01-01

AUTO BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2021)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8949A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,170.00 F	*1,067.55 FL
2	2		*FRONT BONNET HINGES	Repair	270.00 F	*- FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	97.30 F	*- FL
4	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
5	2		*FRONT BONNET RUBBER BEADING	Not Necessary	196.80 F	*- FL
6	1		*FRONT BONNET INNER LOCK	Twisted	145.00 F	*145.00 FL
7	1		*FRONT BONNET SPONGE	No such part	241.80 F	*- FL
8	1		*FRONT FENDER	O/s Buckled/N/s Repair	1,560.00 F	*780.00 FL
9	2		*FRONT FENDER COWLING	Not Necessary	932.00 F	*- FL
10	2		*FRONT FENDER COVER BLACK	Not Necessary	1,280.00 F	*- FL
11	2		*FRONT HEAD LAMP	Holder Cracked	1,724.80 F	*1,724.80 FL
12	2		*FRONT HEAD LAMP PANEL	Repair	1,977.40 F	*- FL
13	1		*FRONT SUPPORT PANEL CENTRE	Bent/Twisted	790.00 F	*650.00 FL
14	1		*FRONT BUMPER	Distorted	1,245.50 F	*898.08 FL
15	1		*SET FRONT BUMPER CLIPS	Necessary	58.00 F	*50.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Repair	752.00 F	*- FL
17	1		*FRONT BUMPER LOWER GRILLE	Twisted	685.00 F	*481.20 FL
18	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	65.00 F	*- FL
19	2		*FRONT BUMPER BRACKET	Not Necessary	343.60 F	*- FL
20	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	395.20 F	*- FL
21	1		*FRONT BUMPER SPONGE	Torn	117.60 F	*117.60 FL
22	1		*FRONT BUMPER TOWING COVER	Not Necessary	105.00 F	*- FL
23	1		*FRONT GRILLE	Cracked	484.70 F	*317.80 FL
24	1		*FRONT GRILLE FIAT LOGO MOTIF	Serviceable	142.10 F	*- FL
25	1		*FRONT DIESEL PUMP	Not Necessary	1,370.00 F	*- FL
26	1		*FRONT CORPORATE ADVERTISEMENT & ARTWORK	Not fitted	300.00 F	*- FL
27	1		*FRONT WIPER TANK	Not Necessary	280.00 F	*- FL
28	1		*FRONT INTER COOLER	Not Necessary	3,640.00 F	*- FL
29	1		*FRONT INTER COOLER COWLING	Not Necessary	435.00 F	*- FL
30	1		*FRONT AIRCON CONDENSER	Bent/Punctured	1,278.00 F	*1,278.00 FL
31	1		*FRONT AIRCON CONDENSER COWLING	No such part	285.00 F	*- FL
32	1		*FRONT BATTERY	Not Necessary	280.00 F	*- FL
33	1		*FRONT BATTERY BASE	Not Necessary	385.00 F	*- FL
34	1		*FRONT AIR CLEANER COMPLETED	Not Necessary	955.90 F	*- FL
35	1		*FRONT AIR CLEANER HOSE	Not Necessary	361.80 F	*- FL
36	1		*FRONT HORN UNIT	Not Necessary	182.10 F	*- FL
37	1		*FRONT RADIATOR	Punctured/Bent	854.30 F	*854.30 FL
38	1		*FRONT RADIATOR FAN COWLING COMPLETED	Cracked	1,175.60 F	*850.00 FL
39	1		*FRONT RADIATOR TOP HOSE	Not Necessary	2,017.80 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT RADIATOR SPARE TANK	Not Necessary	773.50 F	*- FL
41	1		*FRONT RADIATOR HOSE TOP	Not Necessary	142.80 F	*- FL
42	1		*FRONT RADIATOR HOSE LOWER	Not Necessary	195.70 F	*- FL
43	1		*FRONT ABS MASTER PUMP	Not Necessary	4,270.00 F	*- FL
44	1		*FRONT TURBO	Cracked/Damaged	4,856.30 F	*3,880.00 FL
45	1		*FRONT ENGINE LOWER COVER	Not Necessary	975.00 F	*- FL
46	1		*SET FRONT ENGINE TOP COVER	Not Necessary	890.00 F	*- FL
47	1		*SET FRONT ENGINE MOUNTING	Not Necessary	1,790.00 F	*- FL
48	1		*FRONT NUMBER PLATE GARNISH	Deformed	387.00 F	*115.00 FL
49	1		*FRONT EXHAUST SENSOR	Not Necessary	610.00 F	*- FL
50	1		*FRONT EXHAUST HEAT SHIELD	Not Necessary	365.80 F	*- FL
51	1		*FRONT EXHAUST HEATER	Not Necessary	317.20 F	*- FL
52	1		*REAR LH TAILGATE	Badly Dented	2,395.00 F	*2,156.30 FL
53	1		*REAR LH TAILGATE WEATHERSTRIP	Serviceable	344.50 F	*- FL
54	1		*REAR LH TAILGATE OUTER GARNISH	Cracked	279.00 F	*279.00 FL
55	1		*REAR LH TAILGATE LOCK	Twisted/Jammed	331.00 F	*245.50 FL
56	1		*REAR LH TAILGATE INNER TRIM BOARD	Deformed/Cracked	384.90 F	*384.90 FL
57	1		*SET REAR LH TAILGATE INNER TRIM BOARD CLIPS	Necessary	164.50 F	*50.00 FL
58	1		*REAR LH TAILGATE WIPER MOTOR	Cracked/Jammed	428.00 F	*428.00 FL
59	1		*REAR LH TAILGATE WIPER LINK	Serviceable	165.30 F	*- FL
60	1		*REAR LH TAILGATE WIPER RUBBER	Not Necessary	98.00 F	*- FL
61	1		*REAR LH TAILGATE WINDSCREEN GLASS	Shattered	841.50 F	*841.50 FL
62	1		*REAR LH TAILGATE DOBLO EMBLEM	Not fitted	118.00 F	*- FL
63	1		*REAR LH TAILGATE MAXI EMBLEM	Not fitted	86.00 F	*- FL
64	1		*REAR LH MUDFLAT	Not Necessary	276.00 F	*- FL
65	1		*REAR LH TAIL LAMP	Cracked	462.70 F	*366.20 FL
66	1		*REAR RH TAILGATE	Dented/Bent	1,895.90 F	*1,895.90 FL
67	1		*REAR RH TAILGATE LOCK TOP	Not Necessary	189.30 F	*- FL
68	1		*REAR RH TAILGATE LOCK LOWER	Twisted	192.90 F	*145.50 FL
69	1		*REAR RH TAILGATE OUTER GARNISH	Not Necessary	321.80 F	*- FL
70	1		*REAR RH TAILGATE WEATHERSTRIP	Twisted	297.00 F	*282.30 FL
71	1		*REAR RH TAILGATE FIAT EMBLEM	Not fitted	87.80 F	*- FL
72	1		*REAR RH TAILGATE PROFESSIONAL EMBLEM	Necessary	163.50 F	*105.00 FL
73	1		*REAR RH TAILGATE INNER TRIM BOARD	Deformed/Cracked	364.90 F	*364.90 FL
74	1		*SET REAR RH TAILGATE INNER TRIM BOARD CLIPS	Necessary	127.20 F	*50.00 FL
75	1		*REAR BUMPER	Distorted	745.00 F	*627.00 FL
76	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
77	1		*REAR BUMPER REINFORCEMENT	Bent	475.30 F	*475.30 FL
78	2		*REAR REFLECTOR	Not Necessary	197.20 F	*- FL
79	1		*REAR BUMPER SIDE BRACKET	Not Necessary	71.20 F	*- FL
80	1		*REAR END PANEL OUTER	Badly Dented	430.00 F	*430.00 FL
81	1		*REAR END PANEL INNER	Repair	295.00 F	*- FL
82	1		*REAR END PANEL GARNISH TOP	Distorted	1,379.80 F	*347.70 FL
83	1		*SET FRONT BONNET SPONGE CLIPS	No such part	80.00 FS	*- FS
84	1		*SET FRONT INTER COOLER CLIPS	Not Necessary	35.00 FS	*- FS
85	1		*FRONT RADIATOR FAN MOTOR COMPLETED	Not Necessary	378.00 FS	*- FS
86	1		*BOTTLE FRONT RADIATOR COOLANT	Not Necessary	45.00 FS	*- FS
87	1		*FRONT NUMBER PLATE AND BASE	Bent	48.00 FS	*40.00 FS
88	1		*REAR LH TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
89	1		*REAR LH TAILGATE MULTIJET EMBLEM	Not fitted	119.60 FS	*- FS
90	1		*REAR LH TAILGATE 90 EMBLEM	Not fitted	97.50 FS	*- FS
91	1		*REAR LH TAILGATE 70KM/H STICKER	Necessary	12.00 FS	*10.00 FS
92	1		*REAR LH NUMBER PLATE AND BASE	Serviceable	48.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*REAR RH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
94	1		*REAR RH TAILGATE 6PAX STICKER	Necessary	12.00 FS	*10.00 FS
95	1		*REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
96	2		*SETS FRONT FENDER COWLING CLIPS LH & RH	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	59,250.90	23,074.33
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	2,273.43
Total Parts (S\$)	59,250.90	20,800.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	180.00	30.00
2	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHANISM	New	160.00	100.00
3	REMOVE AND REFIX 2 TAILGATE WINDSCREEN GLASS	New	240.00	200.00
4	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
5	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	100.00	0.00
6	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES }	New	250.00	100.00
7	TO REMOVE & REPLACE RADIATOR AND CONDUCT PRESSURE TEST & BLEED SYSTEM }	New	250.00	0.00
8	TO REMOVE AND REFIX ENGINE LABOR CHARGE	New	350.00	0.00
9	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS }	New	3,500.00	1,800.00
10	REMOVE AND REFIX FENDER,PANEL & ETCS }	New	100.00	0.00
11	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	2,000.00	1,600.00
12	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	220.00	120.00
Gross Labour Cost (\$\$)			7,450.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >