

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000784/EVD3Q2

Date: 08/02/2021

REFERENCE

Insured/Claimant:	LEE LAI WEI	Policy No:	1900067184	
Date of Loss:	15/01/2021	Nature of Claim:	OD	Claim No: 6852343896SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG811Y		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11AC3741
Reg. Date:	20/03/2019 (Man. Year: 2018)	Chassis No:	GF7W0600602
Colour:	Blue	Odometer:	33207 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$94,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,135.15	10,843.88	1,291.27	10.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,670.00	5,160.00	510.00	8.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,805.15	16,003.88	1,801.27	10.12
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	17,505.15	15,703.88	1,801.27	10.29
+ GST 7.00/7.00% (S\$)	1,225.36	1,099.27	126.09	10.29
Nett Amount (S\$)	18,730.51	16,803.15	1,927.36	10.29

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PNL,HEADLAMP SUPT,UPR RH	Bent	58.00 FL	*58.00 FL
2	1		*PANEL,HEADLAMP SUPPORT,UPR	Bent	182.00 FL	*182.00 FL
3	1		*PNL,HEADLAMP SUPT,UPR LH	Bent	58.00 FL	*58.00 FL
4	1		*PANEL,HEADLAMP SUPPORT,LWR	Not Necessary	107.00 FL	*- FL
5	1		*CONDENSER ASSY,A/C REFRIGE	Bent	857.00 FL	*857.00 FL
6	1		*HOSE,A/C COMPR DISCHARGE	Not Necessary	191.00 FL	*- FL
7	1		*RADIATOR ASSY	Broken	1,091.00 FL	*1,091.00 FL
8	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL
9	1		*FAN,COOLING,LH	Cut	78.00 FL	*78.00 FL
10	1		*FAN,COOLING,LH	Not Necessary	78.00 FL	*- FL
11	1		*SHROUD,COOLING FAN	Not Necessary	258.00 FL	*- FL
12	1		*MOTOR,COOLING FAN,LH (120W)	Jammed	479.00 FL	*479.00 FL
13	1		*MOTOR,COOLING FAN,LH (120W)	Not Necessary	479.00 FL	*- FL
14	1		*COVER,HEADLAMP SUPT PANEL	Crushed	50.00 FL	*50.00 FL
15	1		*COVER-FR BUMPER	Not Necessary	25.00 FL	*- FL
16	10		*CLIP,RR BUMPER	Necessary	30.00 FL	*30.00 FL
17	1		*GRILLE ASSY,RADIATOR	Broken	548.00 FL	*548.00 FL
18	1		*HEADLAMP ASSY,LH	Broken	1,938.00 FL	*1,938.00 FL
19	1		*HEADLAMP ASSY,RH	Broken	1,938.00 FL	*1,938.00 FL
20	1		*HOOD	Dented	975.00 FL	*975.00 FL
21	1		*HINGE,HOOD,LH	Not Necessary	68.00 FL	*- FL
22	1		*HINGE,HOOD,RH	Not Necessary	68.00 FL	*- FL
23	1		*INSULATOR,HOOD	Crushed	133.00 FL	*133.00 FL
24	8		*CLIP,HOOD INSULATOR	Necessary	24.00 FL	*24.00 FL
25	1		*WEATHERSTRIP HOOD	Not Necessary	40.00 FL	*- FL
26	1		*WEATHERSTRIP HOOD	Not Necessary	41.00 FL	*- FL
27	1		*LATCH,HOOD	Necessary	76.00 FL	*76.00 FL
28	1		*ENGINE HOOD EMBLEM	Necessary	80.00 FL	*80.00 FL
29	1		*BRACKET,FR BUMPER SIDE,LH	Broken	18.00 FL	*18.00 FL
30	1		*BRACKET,FR BUMPER SIDE,RH	Broken	18.00 FL	*18.00 FL
31	1		*FACE,FR BUMPER	Broken	859.00 FL	*859.00 FL
32	1		*COVER,FR BUMPER	Cut	359.00 FL	*359.00 FL
33	1		*EXTENSION,FR BUMPER	Broken	515.00 FL	*515.00 FL
34	1		*GARNISH,FR BUMPER,LH	Not Necessary	48.00 FL	*- FL
35	1		*GARNISH,FR BUMPER,RH	Missing	48.00 FL	*48.00 FL
36	10		*CLIP,RNG ROOM COVER	Necessary	20.00 FL	*20.00 FL
37	1		*LH GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
38	1		*RH GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
39	1		*LH GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
40	1		*RH GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
41	1		*LH GARNISH,FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
42	1		*RH GARNISH,FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
43	1		*REINF,FR BUMPER SIDE,RH	Bent	69.00 FL	*69.00 FL
44	1		*REINFORCEMENT,FR BMPR SIDE	Not Necessary	22.00 FL	*- FL
45	1		*REINF,FR BUMPER SIDE,LH	Bent	60.00 FL	*60.00 FL
46	1		*REINFORCEMENT,FR BUMPER	Bent	134.00 FL	*134.00 FL
47	1		*BAR,FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
48	1		*REINFORCEMENT,FR BUMPER	Bent	490.00 FL	*490.00 FL
49	1		*GARNISH,FR LICENSE PLATE	Crushed	23.00 FL	*23.00 FL
50	1		*FENDER,FR RH	Dented	688.00 FL	*688.00 FL
51	1		*FENDER,FR LH	Dented	688.00 FL	*688.00 FL
52	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
53	1			Bent	58.00 FL	*58.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*PANEL,HEADLAMP SUPPORT,LH (Supplementary)			
54	1		*PANEL,HEADLAMP SUPPORT,RH (Supplementary)	Bent	58.00 FL	*58.00 FL
55	1		*PIPE,A/C CONDENSER OUTLET (Supplementary)	Bent	262.00 FL	*262.00 FL
56	1		*INSULATOR,RDTR SUPPORT,PRE (Supplementary)	Torn	9.00 FL	*9.00 FL
57	1		*RIVET,FR BUMPER (Supplementary)	Necessary	5.00 FL	*5.00 FL
58	1		*MOULDING,FR WHEEL ARCH,LH (Supplementary)	Necessary	160.00 FL	*160.00 FL
59	1		*MOULDING,FR WHEEL ARCH,RH (Supplementary)	Necessary	160.00 FL	*160.00 FL
60	1		*DAMPER,HOOD (Supplementary)	Missing	3.00 FL	*3.00 FL
61	10		*CLIPS (Supplementary)	Necessary	30.00 FL	*30.00 FL
62	5		*RIVET (Supplementary)	Necessary	25.00 FL	*25.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,745.00	14,074.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	3,609.85	3,230.12
Total Parts (\$\$)	12,135.15	10,843.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL,FRONT BONNET,RH FRONT FENDER,FRONT BUMPER FACE,LH FRONT FENDER REPAIR RH FRONT DOOR,REPAIR LH FRONT DOOR	New	2,250.00	2,250.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
3	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	PAINT WORK SPRAY FRONT SUPPORT PANEL,FRONT BONNET,RH FRONT DOOR,RH FRONT FENDER,LH FRONT DOOR,LH FRONT FENDER,FRONT BUMPER AND AFFECTED PORTION	New	2,800.00	2,450.00
5	APPLY BODY SEALANT	New	120.00	40.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	120.00	40.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
Gross Labour Cost (\$\$)			5,670.00	5,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >