

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20000861/KGA3Q2-1

Date: 25/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994047

Claimant
Vehicle No : SHD5426G **Insured Vehicle No :** SLR5759A

Date of Loss: 05/01/2020 Nature of Claim: TP Claim No: 4706334906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5426G		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B49188
Reg. Date:	26/10/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU503073670
Colour:	Metallic Pearl White/Red	Odometer:	130301 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,101.17	0.00	15,101.17	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,930.00	60.00	14,870.00	99.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	30,031.17	60.00	29,971.17	99.80
+ GST 7.00/7.00% (\$\$)	2,102.18	4.20	2,097.98	99.80
Nett Amount (\$\$)	32,133.35	64.20	32,069.15	99.80
+ Loss of Use (0.5 x S\$50.00/day) (\$\$)		25.00		
+ Car Rental (0.5 x S\$112.35/day) (\$\$)		56.18		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		152.83		
Global Sum Settlement (\$\$)		150.00		

INSPECTION

Date of Assignment: 13/01/2020

Date Inspected: 13/01/2020 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 0.5 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	516.00 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	80.10 FL	*- FL
3	1		*REINFORCEMENT ,FRONT BUMPER	Serviceable	716.60 FL	*- FL
4	1		*REINFORCEMENT ,FRONT BUMPER ,NO.2	Serviceable	246.10 FL	*- FL
5	1		*ABSORBER ,FRONT BUMPER ,LOWER	Serviceable	132.70 FL	*- FL
6	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
7	1		*COVER SUB-ASSY ,ENGINE ,NO.1	Serviceable	472.40 FL	*- FL
8	1		*COVER SUB-ASSY ,ENGINE UNDER .NO.2	Serviceable	241.90 FL	*- FL
9	1		*EXTENSION FRONT BUMPER ,RH	Serviceable	120.10 FL	*- FL
10	1		*FRONT LED LAMP (LOWER) RH	Serviceable	951.40 FL	*- FL
11	1		*FRONT HEADLAMP RH	Serviceable	2,637.60 FL	*- FL
12	1		*COMPUTER SUB -ASSY ,HEADLAMP ,RH NO.1	Serviceable	960.50 FL	*- FL
13	1		*MOTOR ,HEADLAMP LEVELING ,RH	Serviceable	487.50 FL	*- FL
14	1		*FRONT FENDER RH	Serviceable	977.80 FL	*- FL
15	1		*LINER ,FRONT FENDER ,RH	Serviceable	206.70 FL	*- FL
16	1		*COVER SUB ASSY ,FRONT PILLAR ,UPPER RH	Serviceable	100.40 FL	*- FL
17	1		*FRONT FENDER EMBLEM RH	Serviceable	54.60 FL	*- FL
18	1		*PAD ,FRONT WHEEL OPENING EXTENSION ,RH	Serviceable	59.60 FL	*- FL
19	1		*PROTECTOR ,FRONT FENDER SIDE PANEL , RH	Serviceable	93.90 FL	*- FL
20	1		*FRONT BONNET	Serviceable	983.10 FL	*- FL
21	1		*HINGE ASSY ,HOOD, RH	Serviceable	58.90 FL	*- FL
22	1		*RIGHT SIDE VIEW MIRROR	Serviceable	1,436.60 FL	*- FL
23	1		*MOULDING ASSY ,BODY ROCKER PANEL RH	Serviceable	594.80 FL	*- FL
24	1		*SHAFT ASSY ,FRONT DRIVE ,RH	Serviceable	1,251.70 FL	*- FL
25	1		*ARM SUB-ASSY ,FRONT SUSPENSION ,LOWER NO.1 RH	Serviceable	760.10 FL	*- FL
26	1		*KNUCKLE STEERING RH	Serviceable	663.40 FL	*- FL
27	1		*FRONT SHOCK ABSORBER	Serviceable	438.30 FL	*- FL
28	1		*SUPPORT SUB -ASSY ,FRONT SUSPENSION ,RH	Serviceable	236.40 FL	*- FL
29	1		*EMBLEM ASSY ,RADIATOR GRILLE	Serviceable	90.80 FL	*- FL
30	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
31	1		*GRILLE ,RADIATOR ,LOWER NO.1	Serviceable	170.10 FL	*- FL
32	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	*- FS
33	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
34	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
35	1		*CLIP ,FRONT FENDER LINER	Serviceable	35.00 FS	*- FS
36	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
37	1		*BUMPER CLIP FRT	Serviceable	66.00 FS	*- FS
38	1		*FRONT DOOR STICKER TRANS-CAB	Serviceable	100.00 FS	*- FS
39	1		*SET FRONT BUMPER RETAINER CLIP	Serviceable	35.00 FS	*- FS
40	1		*SET ROCKER PANEL MOULDING CLIP	Serviceable	30.00 FS	*- FS
41	1		*SET FRONT FENDER LINER RETAINER	Serviceable	35.00 FS	*- FS
42	1		*SET FRONT FENDER LINER SCREW	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,142.60	0.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,041.43	0.00
Total Parts (\$\$)	15,101.17	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	50.00
3	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO CHECK ABS AND BRAKE EFFCIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
7	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
8	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
9	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
12	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
14	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
Gross Labour Cost (\$\$)			14,930.00	60.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >