

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG21000787/EVF3Q2**Date:** 08/02/2021REFERENCE

Insured/Claimant:	NG KIAT HOE	Policy No:	1800122640
Date of Loss:	14/01/2021	Nature of Claim:	OD
		Claim No:	7145180679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV9678P	Engine No:	G4FGJH703637
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5019638
Reg. Date:	29/10/2018 (Man. Year: 2018)	Odometer:	44284 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,178.00	1,148.00	30.00	2.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,920.00	200.00	9.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,298.00	3,068.00	230.00	6.97
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	2,698.00	2,468.00	230.00	8.52
+ GST 7.00/7.00% (S\$)	188.86	172.76	16.10	8.52
Nett Amount (S\$)	2,886.86	2,640.76	246.10	8.52

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL-FENDER,LH	Dented	430.00 FL	*430.00 FL
2	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
3	1		*WHEEL ASSY-ALUMINIUM	Cut	926.00 FL	*926.00 FL
4	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
5	1		*ORNANMENT-KIA NO.115 (Supplementary)	Necessary	32.00 FL	*32.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,460.00	1,430.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	282.00	282.00
Total Parts (\$\$)	1,178.00	1,148.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON LH FRONT FENDER REPAIR FRONT BUMPER	New	800.00	600.00
2	PAINT WORK SPRAY FRONT BUMPER,LH FRONT FENDER AND AFFECTED PORTION	New	960.00	960.00
3	REMOVE AND INSTALL FRONT PARKING ASSIST	New	60.00	60.00
4	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	LABOUR RENEW LH FRONT SPORT RIM INCLUDING BALANCING	New	30.00	30.00
Gross Labour Cost (\$\$)			2,120.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >