

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI21000788/UTF3E2
Date: 11/03/2021

REFERENCE

Handling Insurer: EQ Insurance Company Ltd Policy No:
Claimant Vehicle No : SBN9604B **Insured Vehicle No :** SLW4255S
 Date of Loss: 15/01/2021 Nature of Claim: TP Claim No: DM21HO00084/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBN9604B**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZR453170
 Reg. Date: 10/11/2014 (Man. Year: 2014) Chassis No: MR053REH104517702
 Colour: Red Odometer: 110799 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,667.10	4,232.80	2,434.30	36.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	2,340.00	1,320.00	36.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,327.10	6,572.80	3,754.30	36.35
Approved Total (Overridden) (\$\$)		5,250.00		
(\$\$)	10,327.10	5,250.00	5,077.10	49.16
+ GST 7.00/7.00% (\$\$)	722.90	367.50	355.40	49.16
Nett Amount (\$\$)	11,050.00	5,617.50	5,432.50	49.16

INSPECTION

Date of Assignment: 18/01/2021 Present Location: SME Motor Pte Ltd (Kaki Bukit)
 Date Inspected: 18/01/2021 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBN9604B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR (WCP)	Badly Dented	490.00 F	*490.00 F
2	1		*FRT LH DOOR OUTER MOULDING (WCP)	Not Necessary	70.00 F	*- F
3	1		*FRT LH DOOR OUTER HANDLE (WCP)	Twisted	110.00 F	*110.00 F
4	1		*FRT LH DOOR OUTER HANDLE KNOB (WCP)	Not Necessary	30.00 F	*- F
5	1		*FRT LH DOOR LOCK (WCP)	Jammed	235.00 F	*235.00 F
6	1		*FRT LH DOOR INNER RUBBER (WCP)	Torn	85.00 F	*85.00 F
7	1		*FRT LH DOOR GLASS GEAR (WCP)	Bent	120.00 F	*120.00 F
8	1		*FRT LH DOOR POWER WINDOW MOTOR (WCP)	Jammed	240.00 F	*240.00 F
9	1		*FRT LH DOOR INNER TRIM BOARD (WCP)	Deformed / Twisted	850.00 F	*850.00 F
10	1		*INNER TRIM BOARD CLIPS (1 SET)(WCP)	Necessary	30.00 F	*30.00 F
11	1		*FRT LH DOOR STICKER (WCP)	Necessary	45.00 F	*45.00 F
12	1		*REAR LH DOOR (WCP)	Badly Dented	490.00 F	*490.00 F
13	1		*REAR LH DOOR OUTER MOULDING (WCP)	Not Necessary	70.00 F	*- F
14	1		*REAR LH DOOR TOP HINGE (WCP)	Not Necessary	48.00 F	*- F
15	1		*REAR LH DOOR LOWER HINGE (WCP)	Bent	48.00 F	*48.00 F
16	1		*REAR LH DOOR CENTRE STOPPER (WCP)	Twisted	85.00 F	*85.00 F
17	1		*REAR LH DOOR INNER RUBBER (WCP)	Torn	85.00 F	*85.00 F
18	1		*REAR LH DOOR GLASS GEAR (WCP)	Bent	120.00 F	*120.00 F
19	1		*REAR LH DOOR POWER WINDOW MOTOR (WCP)	Jammed	240.00 F	*240.00 F
20	1		*REAR LH DOOR LOCK (WCP)	Not Necessary	250.00 F	*- F
21	1		*REAR LH DOOR INNER TRIM BOARD (WCP)	Not Necessary	850.00 F	*- F
22	15		*INNER TRIMBOARD CLIPS (WCP)	Not Necessary	30.00 F	*- F
23	1		*LH CENTRE PILLAR (WCP)	Badly Dented	225.00 F	*225.00 F
24	1		*LH CENTRE PILLAR INNER (WCP)	Not Necessary	255.00 F	*- F
25	1		*ROCKER PANEL LH (WCP)	Badly Dented	350.00 F	*350.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRT LH STEP GARNISH (WCP)	Not Necessary	180.00 F	*- F
27	1		*REAR LH STEP GARNISH (WCP)	Not Necessary	180.00 F	*- F
28	1		*FRT LH SAFETY BELT LOWER GARNISH (WCP)	Not Necessary	250.00 F	*- F

F=Franchise part.

Sub Total (\$)	6,061.00	3,848.00
+ Margin on L,N Items 10.00/10.00% (\$)	606.10	384.80
Total Parts (\$)	6,667.10	4,232.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	TRANSFER 2 DOOR COMPONENT FROM OLD TO NEW	New	150.00	100.00
3	REMOVE & REFIX CUSHION AND SEATS }	New	180.00	120.00
4	REMOVE & REFIX REAR FLOOR CARPET }	New	100.00	0.00
5	REMOVE & REFIX FRT LH SAFETY BELT }	New	100.00	0.00
6	LABOUR CHARGE	New	1,600.00	1,100.00
7	SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			3,660.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >