Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/AIG21000790/EVF3Q2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16 09/03/2021

Date: Singapore 079120

REFERENCE

Policy No: 1900150447 Insured/Claimant: Lee Yan Jie

Date of Loss: 15/01/2021 Nature of Claim: OD Claim No: 0257811078SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN6008L

Make & Model: KIA CERATO, 1.6 (A) G4FGKH746535 Engine No: 20/08/2019 (Man. Year: 2019) KNAF5416MK5050977 Reg. Date: Chassis No:

Colour: Red Odometer: 23162 km

Engine Capacity: 1591 cc Market Value/New Car

S\$85,000.00

Price: Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17 Nexen 5 mm Rear Left Side: Front Left Side: Nexen 5 mm Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 7,556.00 | 4,667.20 | 2,888.80 | 38.23 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 9,380.00 | 6,650.00 | 2,730.00 | 29.10 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 16,936.00 | 11,317.20 | 5,618.80 | 33.18 |
| + GST 7.00/7.00% (S\$) | 1,185.52 | 792.20 | 393.32 | 33.18 |
| Nett Amount (S\$) | 18,121.52 | 12,109.40 | 6,012.12 | 33.18 |

INSPECTION

Date of Assignment: 18/01/2021

Cycle & Carriage KIA Pte Ltd (Pandan Date Inspected: 18/01/2021 Inspected At:

Gardens)

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 13.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--|--------------|--|-------------------|-------------|--------------|
| 1 | 1 | | *PANEL ASSY-REAR DOOR,LH | Dented | 1,377.00 FL | *1,377.00 FL |
| 2 | 1 | | *HINGE ASSY-REAR DOOR UPPER,LH | Not Necessary | 33.00 FL | *- FL |
| 3 | 1 | | *HINGE ASSY-DOOR UPPER,LH | Not Necessary | 26.00 FL | *- FL |
| 4 | 1 | | *MOULDING ASSY-RR DR DELTA,LH | Not Necessary | 19.00 FL | *- FL |
| 5 | 1 | | *MOULDING ASSY-RR DR FRAME,LH | Necessary | 50.00 FL | *50.00 FL |
| 6 | 1 | | *W/STRIP ASSY-RR DR BELT O/S LH | Not Necessary | 75.00 FL | *- FL |
| 7 | 1 | | *W/STRIP ASSY-RR DR SIDE LH | Torn | 102.00 FL | *102.00 FL |
| 8 | 1 | | *W/STRIP-RR DR BODY SIDE LH | Crushed | 112.00 FL | *112.00 FL |
| 9 | 1 | | *PANEL ASSY-REAR DOOR MODULE,LH | Not Necessary | 215.00 FL | *- FL |
| 10 | 1 | | *MOTOR ASSY-POWER WDO REG RR,LH | Not Necessary | 111.00 FL | *-FL |
| 11 | 1 | | *GLASS ASSY-REAR DOOR,LH | Not Necessary | 181.00 FL | *- FL |
| 12 | 1 | | *RUN-RR DR WINDOW GLASS,LH | Not Necessary | 135.00 FL | *- FL |
| 13 | 1 | | *MOULDING ASSY-SIDE SILL,LH | Broken | 279.00 FL | *279.00 FL |
| 14 | 1 | | *PANEL ASSY-FRONT DOOR,LH | Repair | 1,277.00 FL | *-FL |
| 15 | 1 | | *MOULDING ASSY-FRT DR FRAME,LH | Not Necessary | 72.00 FL | *- FL |
| 16 | 1 | | *W/STRIP ASSY-FR DR BELT O/S LH | Not Necessary | 80.00 FL | *- FL |
| 17 | 1 | | *W/STRIP ASSY-FR DR SIDE LH | Not Necessary | 102.00 FL | *- FL |
| 18 | 1 | | *WHEEL ASSY-ALUMINIUM | Cut | 926.00 FL | *926.00 FL |
| 19 | 1 | | *TORSION AXLE COMPLETE | Not Necessary | 1,031.00 FL | *- FL |
| 20 | 1 | | *BLACK TAPE-FR DR RR,LH | Necessary | 13.00 FL | *13.00 FL |
| 21 | 1 | | *BLACK TAPE-RR DR,FR,LH | Not Necessary | 13.00 FL | *- FL |
| 22 | 1 | | *BLACK TAPE-RR DR FRAME RR OTR | Necessary | 8.00 FL | *8.00 FL |
| 23 | 1 | | *COVER-RR BUMPER LWR | Not Necessary | 241.00 FL | *- FL |
| 24 | 1 | | *GLASS & MOULDING ASSY-QUARTER (Supplementary) | Necessary | 252.00 FL | *252.00 FL |
| 25 | 1 | | *PANEL ASSY-QUARTER OUTER ,LH (Supplementary) | Dented | 1,349.00 FL | *1,349.00 FL |
| 26 | 1 | | *GUARD-REAR WHEEL,LH (Supplementary) | Crushed | 75.00 FL | *75.00 FL |
| 27 | 10 | | *PAD-WINDSHIELD GLASS (Supplementary) | Necessary | 20.00 FL | *20.00 FL |
| 28 | 1 | | *TRIM-RR STEP PLATE LH (Supplementary) | Broken | 12.00 FL | *12.00 FL |
| 29 | 1 | | *HINGE ASSY-DOOR UPPER,RH (Supplementary) | Bent | 26.00 FL | *26.00 FL |
| 30 | 1 | | *PANEL-SIDE SILL OUTER,LH (Supplementary) | Dented | 1,208.00 FL | *1,208.00 FL |
| 31 | 1 | | *SUNDRIES | Necessary | 20.00 FS | *20.00 FS |
| F=Fra | anchise | part. S=SpcI | Nett. L=ListItemDisc. | , | | |
| | | | | Sub Total (S\$) | 9,440.00 | 5,829.00 |
| | - List Item Discount on L Items 20.00/20.00% (S\$) | | | 1,884.00 | 1,161.80 | |
| | | | | Total Parts (S\$) | 7,556.00 | 4,667.20 |
| | Report was unsubmitted during this print-out. | | | | | |

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

| No | Qty | Particulars | | Repairer's | Amount |
|-----|-------|-----------------------|-----------------|------------|--------|
| Mis | cella | neous Items | | | - |
| 1 | 1 | *OD/TP Case (Insurer) | _ | - | 0.00 |
| | | | Sub Total (S\$) | 0.00 | 0.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|--------------|------------|----------|
| Lab | our Items | | | |
| 1 | RENEW ACCIDENT DAMAGED PARTS ON LH REAR DOOR,LH FRONT DOOR,MOULDING ASSY-SIDE SILL,LH,REPAIR LH REAR FENDER,REPAIR REAR BUMPER FACE,REPLACE COVER-RR BUMPER LWR | New | 2,000.00 | 800.00 |
| 2 | LABOUR TRANSFER LH REAR DOOR GLASS,DOOR MECHANISM,DOOR TRIM AND OTHERS ATTACHMENT TO NEW PANEL | New | 120.00 | 120.00 |
| 3 | LABOUR TRANSFER LH FRONT DOOR GLASS,DOOR MECHANISM,DOOR TRIM AND OTHERS ATTACHMENT TO NEW PANEL | New | 120.00 | 0.00 |
| 4 | REMOVE AND INSTALL REAR PARKING SENSOR TO FACILITATE REPAIR WORK | New | 60.00 | 60.00 |
| 5 | PAINT WORK SPRAY LH FRONT DOOR,LH REAR DOOR,MOULDING ASSY SIDE SILL,LH REAR FENDER,REAR BUMPER AND AFFECTED PORTION | New | 2,880.00 | 2,400.00 |
| 6 | APPLY BODY SEALANT | New | 120.00 | 40.00 |
| 7 | CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 8 | PERFORM RUST PREVENTION | New | 80.00 | 40.00 |
| 9 | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | New | 120.00 | 120.00 |
| 10 | SUPPLY AND RENEW LH REAR TIRE-BURST DUE TO ACCIDENT | New | 380.00 | 0.00 |
| 11 | LABOUR RENEW LH REAR SPORT RIM INCLUDING BALANCING | New | 30.00 | 0.00 |
| 12 | TO RENEW REAR U/CARRIAGE DAMAGES | New | 400.00 | 0.00 |
| 13 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 120.00 | 120.00 |
| 14 | LABOUR RENEW LH REAR FENDER & LH SILL PANEL (Supplementary) | New | 1,400.00 | 1,400.00 |
| 15 | R & I REAR WINDSCREEN (Supplementary) | New | 240.00 | 240.00 |
| 16 | SUPPLY REAR WINDSCREEN SEALANT (Supplementary) | New | 80.00 | 80.00 |
| 17 | R & I INTERIOR & CUSHION (Supplementary) | New | 400.00 | 400.00 |
| 18 | R & I REAR COMPARTMENT (Supplementary) | New | 120.00 | 120.00 |
| 19 | R & I FUEL TANK (Supplementary) | New | 200.00 | 200.00 |
| 20 | PAINT WORK SIDE SILL PANEL (Supplementary) | New | 480.00 | 480.00 |
| | Gross Labou | r Cost (S\$) | 9,380.00 | 6,650.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >