



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 276D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	2,429.70	2,429.70
1	REAR BUMPER CENTER GUIDE BRACKET (CONSISTENT)	NOT NECESSARY	196.50	-
1	REAR BUMPER LOWER LID GARNISH (CONSISTENT)	DEFORMED	473.00	473.00
1	REAR BUMPER LOWER SPOILER (CONSISTENT)	DEFORMED	1,100.00	1,100.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	1,045.00	1,045.00
2	REAR BUMPER REVERSE SENSOR @\$249.90 (CONSISTENT)	DAMAGED	499.80	499.80
2	REAR BUMPER REVERSE SENSOR 'O' RING @\$6.50 (CONSISTENT)	NECESSARY	13.00	13.00
4	REAR BUMPER REVERSE SENSOR HOLDER BRACKET @\$23.10 (CONSISTENT)	NOT NECESSARY	92.40	-
2	REAR BUMPER SIDE BRACKET L/R @\$501.00 (CONSISTENT)	NOT NECESSARY	1,002.00	-
2	REAR BUMPER SIDE RETAINER L/R @\$97.70 (CONSISTENT)	NOT NECESSARY	195.40	-
1	REAR BUMPER TOW HOOK COVER (CONSISTENT)	NOT NECESSARY	42.00	-
1	REAR BUMPER UNDER COVER (CONSISTENT)	NOT NECESSARY	456.00	-
	LESS 5% DISCOUNT		-377.24	-
	LESS 10% DISCOUNT		-	-556.05
			7,167.56	5,004.45
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	50.00
			80.00	50.00
<b><u>LABOUR</u></b>				
	TO RESET SYSTEM AFTER REPAIR WORKS.		280.00	80.00
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR .		60.00	60.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT, TRIM GARNISH ,TRIM LINER CARPET (TO FR).	NOT NECESSARY	100.00	-
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT .		600.00	300.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .		500.00	250.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	50.00	-
			1,590.00	690.00
GRAND TOTAL			8,837.56	5,744.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/ASM21000792/Aps3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.