

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Not Authair

Policy No: Third Party

UTRy 82550

Heavy After Paint

Date: 14.01.2021

Accident Date : 13.01.2021

ised in Car Painting, Welding,  
Beating and Insurance Claim.

## ESTIMATE

4 days

承接汽车烧焊喷漆及  
代理各种车辆赔偿

| 量<br>ity | 货 名<br>DESCRIPTION                                                                                       | 单 价<br>Unit Price | 銀 Amount 額<br>\$ cts.          |
|----------|----------------------------------------------------------------------------------------------------------|-------------------|--------------------------------|
|          | Estimate Cost of Repair "Honda Fit" Reg. No. SJE8584J<br>Claiming Against Your Insured Veh. No. FBC2575E |                   |                                |
|          | Tailgate <i>FFI-00</i>                                                                                   |                   | <i>813.00</i> ✓                |
|          | Tailgate Glass Moulding Top                                                                              |                   | <i>110.00</i> —                |
|          | Tailgate Glass Moulding Lower                                                                            |                   | <i>75.00</i> —                 |
|          | Tailgate Badge "Fit"                                                                                     | <i>50.75 SN</i>   | <i>38.50</i> —                 |
|          | Tailgate Weatherstrip                                                                                    |                   | <i>101.50</i> <i>x509</i>      |
|          | Tailgate Trim Board Clips                                                                                | 3.80              | <i>38.00</i> X                 |
|          | Rear Bumper Clips                                                                                        | 3.80              | <i>38.00</i> —                 |
|          | Rear Bumper Brackets                                                                                     | 16.00             | <i>32.00</i> X                 |
|          | Less 20%                                                                                                 |                   | 1,246.00                       |
|          |                                                                                                          |                   | 249.20                         |
|          |                                                                                                          |                   | 996.80                         |
|          | Tailgate Glass Sealant                                                                                   |                   | <i>50.00</i> SN <i>40 SN</i>   |
|          | Tailgate Glass Fastener                                                                                  |                   | <i>50.00</i> SN <i>20 SN</i>   |
|          | Tailgate Badge "RS"                                                                                      |                   | <i>75.00</i> SN —              |
|          | Rear Bumper (RS) <i>P-1 890.80 → 2208</i>                                                                |                   | <i>950.00</i> SN ✓             |
|          | Rear Bumper Lower Diffuser Cover                                                                         |                   | <i>250.00</i> SN —             |
|          | Rear Bumper Reverse Sensor                                                                               |                   | <i>280.00</i> SN <i>200 SN</i> |
|          | Rear Exhaust (HKS)                                                                                       |                   | <i>1,850.00</i> SN X           |
|          | To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories                                        |                   | <i>150.00</i> <i>60</i>        |
|          | To Conduct Electrical Check, replace Reverse Sensors, Module, Rewiring etc                               |                   | <i>120.00</i> <i>50</i>        |
|          | To Dismantle / Refit Tailgate Glass                                                                      |                   | <i>120</i><br><i>160.00</i>    |
|          | To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel              |                   | <i>60.00</i> <i>30</i>         |
|          | Labour Charge - Panel Beating, Repairing Of End Panel, Lower Floor Panel and Parts Replacement           |                   | <i>500.00</i><br><i>400</i>    |
|          | To Respray Affected Areas                                                                                |                   | <i>680.00</i><br><i>400</i>    |
|          | Total :                                                                                                  |                   | 6,171.80                       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

280.00  
150.00

*Hand X*