

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000794/KTF3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: MSD/VMT/20-506571-WTT	
Claimant Vehicle No : SJE8584J	Insured Vehicle No : FBC2575E	
Date of Loss: 13/01/2021	Nature of Claim: TP	Claim No: MSC/V/21-000027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE8584J		
Make & Model: HONDA FIT, 1.5 RS (A)	Engine No: L15A1562627	
Reg. Date: 10/05/2008 (Man. Year: 2008)	Chassis No: GE81011524	
Colour: Metallic Black	Odometer: 303894 km	
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45ZR16	Rear Tyre Size: 205/45ZR16	
Front Left Side: Kumho 6 mm	Rear Left Side: Kumho 4 mm	
Front Right Side: Kumho 6 mm	Rear Right Side: Kumho 4 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,501.80	2,174.39	2,327.41	51.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,060.00	610.00	36.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,171.80	3,234.39	2,937.41	47.59
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	6,171.80	2,550.00	3,621.80	58.68
+ GST 7.00/7.00% (S\$)	432.03	178.50	253.53	58.68
Nett Amount (S\$)	6,603.83	2,728.50	3,875.33	58.68

INSPECTION

Date of Assignment: 18/01/2021		
Date Inspected: 18/01/2021 Inspected At:		Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair: 4.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	144	HONDA FIT 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE8584J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	813.00 FL	*771.00 FL
2	1		*TAILGATE GLASS MOULDING TOP	Necessary	110.00 FL	*110.00 FL
3	1		*TAILGATE GLASS MOULDING LOWER	Necessary	75.00 FL	*75.00 FL
4	1		*TAILGATE BADGE FIT	Necessary	38.50 FL	*38.50 FL
5	10		*TAILGATE TRIM BOARD CLIPS	Not Necessary	38.00 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
7	2		*REAR BUMPER BRACKETS	Repair	32.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP (50%)	Cut	81.20 FS	*50.75 FS
9	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
10	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*20.00 FS
11	1		*TAILGATE BADGE RS	Necessary	75.00 FS	*75.00 FS
12	1		*REAR BUMPER LOWER DIFFUSER COVER	Dented/Cut	250.00 FS	*250.00 FS
13	1		*REAR BUMPER REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
14	1		*REAR EXHAUST (HKS)	Repair	1,850.00 FS	*- FS
15	1		*REAR BUMPER (RS)	Dented/Buckled	950.00 F	*890.80 FN
					Sub Total (\$\$)	4,730.70 2,559.05
					- List Item Discount on L Items 20.00/20.00% (\$\$)	228.90 206.50
					- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00 178.16
					Total Parts (\$\$)	4,501.80 2,174.39

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE/TRANSFER TAILGATE FITTINGS/ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE,REWIRING ETC	New	120.00	50.00
3	TO DISMANTLE/REFIT TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	60.00	30.00
5	LABOUR CHARGE-PANEL BEATING,REPAIRING OF END PANEL,LOWER FLOOR PANEL AND PARTS REPLACEMENT	New	500.00	400.00
6	TO RESPRAY AFFECTED AREAS	New	680.00	400.00
Gross Labour Cost (S\$)			1,670.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >