

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000797/ABA3Q2
Date: 16/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070129701
Claimant Vehicle No :	SMR3781K	Insured Vehicle No :	SMU9505L
Date of Loss:	12/01/2021	Nature of Claim:	TP
		Claim No:	1949746231SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3781K	Engine No:	1ZRX529079
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104538054
Reg. Date:	19/10/2015 (Man. Year: 2015)	Odometer:	95921 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,957.55	2,811.01	2,146.54	43.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,800.00	500.00	21.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,257.55	4,611.01	2,646.54	36.47
Approved Total (Overridden) (S\$)		3,700.00		

Nett Amount (S\$)	7,257.55	3,700.00	3,557.55	49.02
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,307.45		

INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021

Estimated Period of Repair: 6.0 days

Inspected At: Fong Motors - Kaki Bukit (HQ)
1 KAKI BUKIT AVE 6 #01-27/01-45
Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Buckled	780.20 F	*780.20 FL
2	1		*TAIL GATE EMBLEM	Necessary	49.30 F	*49.30 FL
3	1		*TOYOTA ALTIS EMBLEM	Necessary	52.20 F	*52.20 FL
4	1		*TAIL GATE WEATHERSTRIP	Not Necessary	163.80 F	*- FL
5	1		*TAIL GATE LOCK	Not Necessary	370.40 F	*- FL
6	1		*END PANEL	Dented	659.70 F	*659.70 FL
7	1		*END PANEL ELECTRICAL ANTENNA SWTICH	Damaged	182.65 F	*182.65 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	321.40 F	*321.40 FL
9	1		*TAIL LAMP LH/RH	N/S Cracked	764.60 F	*382.30 FL
10	2		*TAIL LAMP LOWER BRACKET	Not Necessary	131.20 F	*- FL
11	1		*TAIL LAMP GASKET	N/S Necessary	56.00 F	*28.00 FL
12	1		*REAR BUMPER	Deformed	652.40 F	*581.90 FL
13	1		*END PANEL GARNISH	Deformed	283.70 F	*283.70 FL
14	5		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
15	5		*END PANEL GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
16	1		*SET REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
17	1		*BOOTLID CHROME ACCESSORY	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,957.55	3,641.35
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	830.34
Total Parts (\$)	4,957.55	2,811.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REFIT AND KNOCK ALL AFFECTED PARTS (REAR PORTION)	New	900.00	800.00
2	SPRAY PAINTING OF AFFECTED PARTS	New	1,000.00	800.00
3	TO REMOVE /REFIT REVERSE SENSORS AND ANTENNA SWITCH	New	120.00	50.00
4	TUFF KOTE	New	100.00	60.00
5	TO TRANSFER UPHOLSTERY	New	100.00	60.00
6	TO CHECK WIRING	New	80.00	30.00
Gross Labour Cost (\$\$)			2,300.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >