

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000799/EQD3Q2**Date:** 08/02/2021**REFERENCE**

Insured/Claimant: HO NGAI CHI Policy No: 2070109576
Date of Loss: 15/01/2021 Nature of Claim: OD Claim No: 2568004832SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT9237R**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH754845
Reg. Date: 24/07/2020 (Man. Year: 2020) Chassis No: KNAF5416ML5087295
Colour: Red Odometer: 11029 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Nexen 4 mm Rear Left Side: Nexen 4 mm
Front Right Side: Nexen 4 mm Rear Right Side: Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,368.00	4,408.00	960.00	17.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	3,690.00	440.00	10.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,498.00	8,098.00	1,400.00	14.74
+ GST 7.00/7.00% (S\$)	664.86	566.86	98.00	14.74
Nett Amount (S\$)	10,162.86	8,664.86	1,498.00	14.74

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Dented	651.00 FL	*651.00 FL
2	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
3	1		*COVER-RR BUMPER FOG LAMP,RH	Cut	19.00 FL	*19.00 FL
4	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Not Necessary	181.00 FL	*- FL
5	1		*BRACKET-RR BEAM UPR MTG,RH	Not Necessary	9.00 FL	*- FL
6	1		*BRACKET-RR BEAM UPR MTG,LH	Not Necessary	9.00 FL	*- FL
7	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 FL	*- FL
8	2		*BRACKET-RR BEAM LWR MTG	Broken	12.00 FL	*6.00 FL
9	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
10	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
11	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
12	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
13	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Not Necessary	25.00 FL	*- FL
14	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Not Necessary	31.00 FL	*- FL
15	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
16	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
17	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
18	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
19	1		*EMBLEM-GT LINE	Necessary	45.00 FL	*45.00 FL
20	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
21	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 FL	*- FL
22	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FL	*- FL
23	1		*LAMP ASSY-REAR COMB INSIDE,RH	Cut	608.00 FL	*608.00 FL
24	1		*LAMP ASSY-REAR COMB OUTSIDE,RH	Cut	675.00 FL	*675.00 FL
25	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL
26	1		*LAMP ASSY-LUGGAGE & GLOVE	Not Necessary	19.00 FL	*- FL
27	1		*SUNDRY	Necessary	40.00 FS	*20.00 FS
28	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
29	1		*HINGE ASSY-TRUNK LID, LH (Supplementary)	Bent	97.00 FL	*97.00 FL
30	1		*HINGE ASSY-TRUNK LID, RH (Supplementary)	Bent	97.00 FL	*97.00 FL
31	10		*CLIPS (Supplementary)	Necessary	10.00 FL	*10.00 FL
32	1		*MUFFLER ASSY-REAR (Supplementary)	Bent	757.00 FL	*757.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,690.00	5,495.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,322.00	1,087.00
Total Parts (\$)	5,368.00	4,408.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW REAR BUMPER,BOOTLID,REAR END PANEL,REAR SPOILER	New	2,000.00	1,600.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	200.00	200.00
4	SPRAY PAINT FOR REAR BUMPER,REAR END PANEL,BOOTLID	New	1,440.00	1,440.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	40.00
8	REMOVE & REPLACE REAR EXHAUST MUFFLER (Supplementary)	New	200.00	200.00
Gross Labour Cost (\$\$)			4,130.00	3,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >