

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4745Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | BUMPER REAR (DISC 25%) | CRUMPLED | 458.60 | 343.95 |
| 10 | BUMPER CLIPS @\$2.10 (DISC 25%) | NECESSARY | 21.00 | 15.75 |
| 1 | BUMPER LIP REAR (DISC 25%) | CRUMPLED | 228.90 | 171.68 |
| 1 | BUMPER SIDE RETANER RR/LH (DISC 25%) | CRACKED | 94.80 | 71.10 |
| 1 | ANTENNA, ELECTRICAL LOWER REAR (DISC 10%) | CRUMPLED | 157.40 | 141.66 |
| 2 | PIXEL STICKER @\$60.00 (SN) | NECESSARY | 120.00 | 120.00 |
| 1 | SENSOR REVERSE (SN) | SHORTED | 180.00 | 180.00 |
| 1 | ADVERTISEMENT STICKER (SN) | NECESSARY | 296.88 | 296.88 |
| 1 | BUMPER REINFORCEMENT REAR | SERVICEABLE | 205.70 | - |
| 1 | ARM SUB-ASSY, RR BUMPER RH | SERVICEABLE | 139.60 | - |
| 1 | ARM SUB-ASSY, RR BUMPER LH | SERVICEABLE | 139.60 | - |
| 1 | ANTENNA, ELECTRICAL LOWER REAR | SERVICEABLE | 157.40 | - |
| 1 | BUMPER SIDE RETAINER RR/LH | SERVICEABLE | 94.80 | - |
| 1 | BUMPER SIDE RETAINER RR/RH | SERVICEABLE | 94.80 | - |
| 1 | BUMPER LIP COVER RR/LH | SERVICEABLE | 72.20 | - |
| 1 | BUMPER LIP COVER RR/RH | SERVICEABLE | 118.10 | - |
| 1 | UNDER COVER SUB-ASSY, RR FLOOR | SERVICEABLE | 514.50 | - |
| 1 | UNDER COVER RR SHIELD | SERVICEABLE | 63.90 | - |
| 1 | END PANEL | SERVICEABLE | 602.10 | - |
| | | | 3,760.28 | 1,341.02 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING & BODY WORK. | | 507.00 | 200.00 |
| | SPRAY PAINT. | | 738.00 | 200.00 |
| | TO TEST AND REFIX REVERSE SENSOR SYSTEM. | | 120.00 | 20.00 |
| | TO REPLACE SUNDRY PARTS. | NOT NECESSARY | 100.00 | - |
| | TO CHECK WIRING AND SYSTEM FUNCTION. | | 80.00 | 20.00 |
| | TO WASH AND VACUUM. | NOT NECESSARY | 60.00 | - |
| | | | 1,605.00 | 440.00 |
| | GRAND TOTAL | | 5,365.28 | 1,781.02 |

Report Ref No. NS/INC21000802/Qqd3e2





Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 1,400.00 |
|---|----------|
| (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | |

Report Ref No. NS/INC21000802/Qqd3e2

Ja

OI SUN PIN

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser