

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000803/APA3Q2**Date:** 02/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100495836
Claimant Vehicle No :	SMV1335H	Insured Vehicle No :	SLJ8697S
Date of Loss:	10/01/2021	Nature of Claim:	TP
		Claim No:	2425837124SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV1335H	Engine No:	N219324XHXXKX0874
Make & Model:	OPEL ASTRA, 1.3 HB (A)	Chassis No:	W0VBE6ETXLG053354
Reg. Date:	17/09/2020 (Man. Year: 2020)	Odometer:	3976 km
Colour:	Silver		
Engine Capacity:	1341 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,817.80	4,541.30	3,276.50	41.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	3,365.00	1,015.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,197.80	7,906.30	4,291.50	35.18
+ GST 7.00/7.00% (S\$)	853.85	553.44	300.41	35.18
Nett Amount (S\$)	13,051.65	8,459.74	4,591.91	35.18
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
		Nett Liability (S\$)	8,887.74	
		Global Sum Settlement (S\$)	8,880.00	

INSPECTION

Date of Assignment:	15/01/2021	
Date Inspected:	15/01/2021	Inspected At: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Deformed	1,680.00 FL	*1,680.00 FL
2	1		*REAR BUMPER LOWER	Not Necessary	658.00 FL	*- FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	34.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR RH	Not Necessary	63.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR LH	Not Necessary	63.00 FL	*- FL
6	1		*REAR END PANEL	Repair	487.00 FL	*- FL
7	1		*REINFORCEMENT ,RR END PANEL	Bent	970.00 FL	*970.00 FL
8	1		*REAR BUMPER GUIDE LH	Cracked	87.00 FL	*87.00 FL
9	1		*REAR BUMPER GUIDE RH	Cracked	87.00 FL	*87.00 FL
10	1		*REAR BUMPER GUIDE CENTER	Cracked	95.00 FL	*95.00 FL
11	1		*REAR TAILGATE	Repair	2,280.00 FL	*- FL
12	1		*REAR OPEL EMBLEM	Necessary	120.00 FL	*120.00 FL
13	1		*LETTERING ASTRA	Necessary	110.00 FL	*110.00 FL
14	1		*SEALANT	Not Necessary	50.00 FS	*- FS
15	1		*REAR NUMBER PLATE	Necessary	40.00 FS	*40.00 FS
16	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
17	1		*REVERSE CAMERA	Cracked	318.00 FL	*318.00 FL
18	1		*RR NUMBER PLATE LAMP	Cracked	132.00 FL	*132.00 FL
19	1		*RR END PANEL AIR DUCT	Cracked	232.00 FL	*232.00 FL
20	1		*RR BUMPER BRACKET RH	Cracked	96.00 FL	*96.00 FL
21	1		*RR BUMPER BRACKET LH	Cracked	86.00 FL	*86.00 FL
22	1		*RR END PANEL TOP GARNISH	Deformed	280.00 FL	*280.00 FL
23	1		*RR KEYLESS REVERSE SENSOR	Cracked	274.00 FL	*274.00 FL
24	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Damaged	390.00 FL	*390.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,672.00	5,037.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	854.20	495.70
Total Parts (\$\$)	7,817.80	4,541.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,200.00	1,625.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (REAR TAILGATE ,REAR BUMPER ,REAR END PANEL)	New	1,900.00	1,650.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	150.00	30.00
4	REMOVE AND REFIT REVERSE SENSOR (LABOUR)	New	130.00	60.00
Gross Labour Cost (\$\$)			4,380.00	3,365.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >