

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21000805/QKvf3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND Date: 29/01/2021 **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJE 3338L **SCY 652B** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. CMTD2100178/SYH Excess (\$) 0.00 **GRACE TEO Assign Date** 18/01/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA COROLLA ALTIS 1496 Make & Model c.c HIDDEN 2009 Engine No. Year of Reg. MR053ZEE106115681 SILVER Chassis No. Colour 162769 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 YOKOHAMA 6 mm 195/65 R15 YOKOHAMA L/H Front Tyre 6 mm 195/65 R15 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195/65 R15 6 mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. 5. **General Information** 15/01/2021 18/01/2021 (02:38 PM) Inspect Date / Time Accident Date **ENG SOON PAINTING SVC** Survey held at BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/SMO21000805/QKvf3e2

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

NEOD Anto Ornanticut OAE Lineard American

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

3 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser