



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 2892A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RAD PNL COMPL RPR (N)	SERVICEABLE	360.00	-
1	FRT FENDER RH (N)	TO REPAIR SEE LABOUR	270.00	-
1	FRT FENDER LH (N)	BENT	270.00	270.00
1	HOOD F CPL (N)	BENT	882.00	882.00
1	BRKT CORNER F RH (N)	NECESSARY	36.00	36.00
1	BRKT CORNER F LH (N)	NECESSARY	36.00	36.00
1	BUMPER COVER FRT (FOR HL/W) (N)	DEFORMED	594.00	594.00
1	BACK BEAM CPL F (N)	BENT	288.00	288.00
1	ENERGY ABSOR F (N)	BENT	126.00	126.00
1	COVER HOOK F SP (N)	CRACKED	5.40	5.40
1	COVER FOG F SP RH (N)	SERVICEABLE	43.20	-
1	COVER FOR F SP LH (N)	SERVICEABLE	43.20	-
1	COVER SD F SP RH (N)	MISSING	12.60	12.60
1	COVER SD F SP LH (N)	SERVICEABLE	12.60	-
1	LAMP ASSY HEAD E0F RIGHT SIDE (N)	SERVICEABLE	2,380.00	-
1	LAMP ASSY HEAD E0F LH (N)	CRACKED	2,380.00	2,380.00
1	FOG LAMP ASSY F (N)	SERVICEABLE	544.00	-
1	BRKT F FOG ASSY RH (N)	SERVICEABLE	19.80	-
1	BRKT F FOG ASSY LH (N)	SERVICEABLE	19.80	-
1	NOZZLE H L WASHERRH (N)	CRACKED	79.20	79.20
1	NOZZLE H L WASHERLH (N)	SERVICEABLE	79.20	-
1	NOZZLE COVER ASSYRH (N)	MISSING	54.00	54.00
1	NOZZLE COVER ASSYLH (N)	MISSING	54.00	54.00
1	BRKT GRILLE LWR NA (N)	CUT	21.60	21.60
1	ORNAMENT F (N)	NECESSARY	68.40	68.40
1	FRONT GRILLE (N)	SCRATCHED	1,200.00	1,200.00
1	FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS) (N)	CRACKED	1,396.00	1,396.00
	LESS 20% DISCOUNT		-2,255.00	-1,500.64
			9,020.00	6,002.56

Report Ref No. CS/UOI21000806/R1tf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	FRONT LICENSE PLATE WITH CASING (SN)	BENT	55.00	55.00
			105.00	75.00
	<b><u>LABOUR</u></b>			
	TO SUPPLY & INSTALL FRONT SPORTY GRILLE.		50.00	30.00
	TO REPAIR AND REPLACE FRONT BUMPER, FRONT BONNET, FRONT BOTH SIDE FENDER, ENERGY ABSORBER, FRONT. INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		2,800.00	1,120.00
	UNDERSPOILER AND FRONT SUPPORT PANEL. (NPA)	NOT NECESSARY	-	-
	TO RESPRAY FRONT BONNET, FRONT BUMPER, FRONT BOTH SIDE FENDER, FRONT BUMPER BEAM AND FRONT SUPPORT.		3,520.00	840.00
	PANEL. (NPA)	NOT NECESSARY	-	-
	TO CONDUCT FRONT LIGHTING SYSTEM TEST.		100.00	80.00
	TO CONDUCT FRONT HEADLAMP WASHER TEST.		100.00	60.00
	TO REPLACE AND RESPRAY FRONT BUMPER BEAM. (ADDITIONAL)		280.00	280.00
	TO REPLACE AND RESPRAY FRONT LHS FENDER. (ADDITIONAL)		560.00	560.00
			7,410.00	2,970.00
	<b>GRAND TOTAL</b>		<b>16,535.00</b>	<b>9,047.56</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>9,047.56</b>
	<b>LESS EXCESS</b>			<b>-500.00</b>
	<b>NETT LIABILITY</b>			<b>8,547.56</b>

Report Ref No. CS/UOI21000806/R1tf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.