

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21000811/T1GS3Q2  
**Date:** 29/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800153642
<b>Claimant Vehicle No :</b>	SHA2253Z	<b>Insured Vehicle No :</b>	SLS7716E
Date of Loss:	17/01/2021	Nature of Claim:	TP
		Claim No:	4594818539SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA2253Z</b>		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU299312
Reg. Date:	06/08/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU165139
Colour:	Blue	Odometer:	154303 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,114.16	643.12	471.04	42.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,055.00	445.00	29.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,614.16</b>	<b>1,698.12</b>	<b>916.04</b>	<b>35.04</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>182.99</b>	<b>118.87</b>	<b>64.12</b>	<b>35.04</b>

<b>Nett Amount (\$\$)</b>	<b>2,797.15</b>	<b>1,816.99</b>	<b>980.16</b>	<b>35.04</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (\$\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$125.19/day) (\$\$)</b>		375.57		
<b>Nett Liability (\$\$)</b>		<b>2,342.56</b>		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM -BLUE DRIVE	Necessary	26.60 FL	*26.60 FL
2	1		*PANEL -FENDER LH	Repair	588.80 FL	*- FL
3	1		*COVER-FR BUMPER	Deformed	430.90 FL	*430.90 FL
4	1		*CAP ASSY -WHEEL	Cut	346.40 FL	*346.40 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	1,392.70803.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	278.54160.78
					Total Parts (\$\$)	1,114.16643.12

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	800.00	525.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	TUFF COAT ON AFFECTED PARTS	New	50.00	0.00
4	CHECK ALL LIGHTING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,500.00</b>	<b>1,055.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >