

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21000820/T1VD3E2

Date: 11/03/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR005133	
Claimant Vehicle No :	SHC1079G	Insured Vehicle No :	SMV2189G	
Date of Loss:	17/01/2021	Nature of Claim:	TP	Claim No: M2100311

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1079G	Engine No:	G4LEJU076121
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU106514
Reg. Date:	10/08/2018 (Man. Year: 2018)	Odometer:	360486 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,733.48	1,939.64	793.84	29.04
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,560.00	1,115.00	445.00	28.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,304.48	3,065.64	1,238.84	28.78
+ GST 7.00/7.00% (S\$)	301.31	214.59	86.72	28.78
Nett Amount (S\$)	4,605.79	3,280.23	1,325.56	28.78

INSPECTION

Date of Assignment:	18/01/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	18/01/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1079G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Deformed	430.90 FL	-	*430.90 FL
2	1		*FRT FENDER LH	Repair	588.80 FL	-	*- FL
3	1		*FRT BUMPER MOULDING	Repair	368.50 FL	-	*- FL
4	1		*HEADLAMP ASSY LH	Cut	1,993.65 FL	-	*1,993.65 FL
5	1		*FRT BUMPER BRACKET LH	Not Necessary	35.00 FL	-	*- FL
F=Franchise part. L=ListItemDisc.							
Sub Total (S\$)					3,416.85	2,424.55	
- List Item Discount on L Items 20.00/20.00% (S\$)					683.37	484.91	
Total Parts (S\$)					2,733.48		1,939.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	525.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
5	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			1,560.00	1,115.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >