

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000823/QTD3Q2

**Date:** 17/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070166762 V1

**Claimant**  
**Vehicle No :** SBW3993U **Insured Vehicle No :** GBK7886H

**Date of Loss:** 14/01/2021 **Nature of Claim:** TP **Claim No:** 8775885358SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	<b>SBW3993U</b>		
<b>Make &amp; Model:</b>	HONDA VEZEL, 1.5 HYBRID (A)	<b>Engine No:</b>	L15B4027195
<b>Reg. Date:</b>	11/03/2016 (Man. Year: 2015)	<b>Chassis No:</b>	RU11107194
<b>Colour:</b>	Black	<b>Odometer:</b>	99409 km
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021 Inspected At:

Dynamics Mechanic Pte Ltd (HQ)  
184 Woodlands Industrial Park E5  
#01-03/04  
Singapore 757514

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
4	1		*FRT LH HEADLAMP ASSY	Scratched	0.00 F	*- F
5	1		*FRT LH HEAD LAMP BRACKET	Cracked	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**