

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000824/T1VF3E2

**Date:** 02/02/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993759
<b>Claimant Vehicle No :</b>	SJR7340J	<b>Insured Vehicle No :</b>	SGB3068S
Date of Loss:	14/01/2021	Nature of Claim:	TP
		Claim No:	3891764922SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJR7340J</b>	Engine No:	1NZX937951
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305122027
Reg. Date:	10/07/2009 (Man. Year: 2009)	Odometer:	312264 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	18/01/2021		
Date Inspected:	19/01/2021	Inspected At:	Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB Singapore 417895
Estimated Period of Repair:	6.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	* Check	0.00 F	*- F
6	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
7	1		*REAR END PANEL	Bent	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Bent	0.00 F	*- F
12	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LOCK	Bent	0.00 F	*- F
14	1		*BOOTLID RUBBER	Deformed	0.00 F	*- F
15	2		*BOOTLID HINGE	Bent	0.00 F	*- F
16	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F
17	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
18	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**

**0.00**

**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >