Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21000830/T1TD3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MR001004

Claimant
White No: SHC6873Y

Insured Vehicle No: GBF8040B

Vehicle No:

Date of Loss: 16/01/2021 Nature of Claim: TP Claim No: M2100315

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6873Y

Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDEH313442

Reg. Date: 02/09/2015 (Man. Year: 2015) Chassis No: KNAGM414MF5621943

Colour: Silver Odometer: 525557 km

Engine Capacity: 1685 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R15 Rear Tyre Size: 205/65R15
Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
Front Right Side: Maxxis 6 mm
Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,131.10	706.40	1,424.70	66.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	400.00	970.00	70.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,501.10	1,106.40	2,394.70	68.40
Approved Total (Overridden) (S\$)		850.00		
(S\$)	3,501.10	850.00	2,651.10	75.72
+ GST 7.00/7.00% (S\$)	245.08	59.50	185.58	75.72
Nett Amount (S\$)	3,746.18	909.50	2,836.68	75.72

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 19/01/2021 Inspected At: Premier Automotive Services Pte Ltd

(HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 04 Feb 2021)		
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SHC6873Y)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	696.00 FL	-	*696.00 FL
2	1		*REAR BUMPER LOWER COVER	Repair	206.00 FL	_	*- FL
3	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Not Necessary	58.00 FL	-	*-FL
4	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	-	*-FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	-	*-FL
6	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	106.00 FL	-	*-FL
7	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	-	*-FL
8	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	-	*-FL
9	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	-	*30.00 FS
10	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	-	*-FS
11	1		*REAR BUMPER TOP PROTECTOR	Necessary	80.00 FS	-	*50.00 FS
12	1		*SUNDRY	Not Necessary	50.00 FS	-	*-FS
F=Fra	anchise	part. S=	SpcNett. L=ListItemDisc.				
				Sub Total (S\$)	,	776.00	
			- List Item Discount on L Items 10.0	JU/10.00% (S\$)	185.90	69.60	
			Т	otal Parts (S\$)	2,131.10		706.40

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/WELD,CUT-OFF THE THE END PANEL,INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR PANEL	New	650.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,END PANEL	New	400.00	200.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	0.00
	Gross Labour Cost (S\$)		1,370.00	400.00
	Report was unsubmitted durin	a this print-out.		

< END OF ESTIMATES >