

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000832/DGS3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SHD3933Y

Date of Loss: 08/01/2021

Policy No:

Insured Vehicle No :

Nature of Claim:

SMA6469H

TP

Claim No: 2124307583SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD3933Y**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Reg. Date: 19/07/2017 (Man. Year: 2017)

Colour: Blue

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2ZRS054352

Chassis No: JTDKB3FU303560642

Odometer: 510382 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Front Left Side: DURATURN 5 mm

Front Right Side: DURATURN 5 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

195/65 R15

DURATURN 5 mm

DURATURN 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,573.82	13,565.54	9,008.28	39.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,900.00	1,860.00	49.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,333.82	15,465.54	10,868.28	41.27
Approved Total (Overridden) (S\$)		13,900.00		

(S\$)	26,333.82	13,900.00	12,433.82	47.22
+ GST 7.00/7.00% (S\$)	1,843.37	973.00	870.37	47.22
Nett Amount (S\$)	28,177.19	14,873.00	13,304.19	47.22
+ Loss of Use (15.0 x S\$50.00/day) (S\$)		750.00		
+ Car Rental (15.0 x S\$125.40/day) (S\$)		1,881.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		17,591.45		
Global Sum Settlement (S\$)		17,500.00		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Dented	950.50 FL	*950.50 FL
2	1		*INSULATOR ,HOOD	Not Necessary	398.10 FL	*- FL
3	10		*INSULATOR CLIPS	Not Necessary	36.80 FL	*- FL
4	1		*BONNET RUBBER	Not Necessary	35.50 FL	*- FL
5	1		*BONNET CABLE	Not Necessary	83.20 FL	*- FL
6	1		*BONNET HINGE (RH)	Bent	87.70 FL	*87.70 FL
7	1		*BONNET HINGE (LH)	Bent	87.70 FL	*87.70 FL
8	1		*BONNET LOCK	Bent	132.60 FL	*132.60 FL
9	1		*RADIATOR GRILLE	Broken	438.00 FL	*438.00 FL
10	1		*RADIATOR GRILLE EMBLEM	Broken /Dislodged	88.00 FL	*88.00 FL
11	1		*FRONT BUMPER COVER	Torn	499.90 FL	*499.90 FL
12	1		*FRONT BUMPER REINFORCEMENT	Dented / Bent	696.40 FL	*696.40 FL
13	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Deformed / Cut	115.70 FL	*115.70 FL
14	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	364.20 FL	*364.20 FL
15	1		*FRONT BUMPER LOWER REINFORCEMENT BRACKET (N/S)	Dented	330.00 FL	*330.00 FL
16	2		*FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH)	Not Necessary	641.40 FL	*- FL
17	1		*FRONT SIDE MEMBER SIDE COVER	Not Necessary	172.50 FL	*- FL
18	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
19	1		*FRONT BUMPER LOWER GRILLE	Deformed	166.90 FL	*166.90 FL
20	1		*LAMP ASSY ,FOG, RH	Cut / Mtg Broken	920.00 FL	*920.00 FL
21	1		*LAMP ASSY ,FOG, LH	Dislodged / Broken	920.00 FL	*920.00 FL
22	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	77.00 FL	*- FL
23	1		*FRONT LOWER PANEL	Bent	320.65 FL	*320.65 FL
24	2		*FRONT LOWER SIDE RAIL (LH/RH)	Not Necessary	230.80 FL	*- FL
25	1		*FRONT LOWER CROSSMEMBER	Not Necessary	357.70 FL	*- FL
26	1		*FRONT BUMPER TOP GARNISH	Not Necessary	225.40 FL	*- FL
27	1		*COVER ,FRONT BUMPER HOLE ,RH	Dislodged	28.38 FL	*28.38 FL
28	1		*COVER ,FRONT BUMPER HOLE ,LH	Cut / Distorted	28.38 FL	*28.38 FL
29	1		*ABSORBER ,FRONT BUMPER ,LOWER	Not Necessary	127.70 FL	*- FL
30	1		*UNIT ASSY ,HEADLAMP RH (LED)	Mtg Broken	3,455.00 FL	*2,637.60 FL
31	1		*UNIT ASSY ,HEADLAMP LH (LED)	Broken	3,455.00 FL	*2,637.60 FL
32	1		*HEADLAMP ECU	Not Necessary	682.60 FL	*- FL
33	1		*HEAD LAMP PANEL (RH)	Bent	240.10 FL	*240.10 FL
34	1		*HEAD LAMP PANEL (LH)	Bent	240.10 FL	*240.10 FL
35	1		*TOP PANEL CENTRE	Dented / Bent	364.98 FL	*364.98 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TOP PANEL SIDE (O/S)	Bent	145.90 FL	*145.90 FL
37	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
38	1		*RADIATOR ASSY	Bent	1,841.80 FL	*1,841.80 FL
39	1		*RADIATOR FAN GRILLE	Not Necessary	632.40 FL	*- FL
40	1		*GUIDE RADIATOR AIR NO.3	Not Necessary	299.70 FL	*- FL
41	1		*COOLANT	Not Necessary	45.00 FL	*- FL
42	1		*DEFLECTOR ,RADIATOR SIDE ,RH	Serviceable	83.50 FL	*- FL
43	1		*DEFLECTOR ,RADIATOR SIDE ,LH	Serviceable	83.50 FL	*- FL
44	1		*RADIATOR SPARE TANK HYBRID	Not Necessary	225.80 FL	*- FL
45	1		*RADIATOR BOTTOM MOUNTING	Not Necessary	27.50 FL	*- FL
46	1		*STAY ,RADIATOR SUPPORT RH	Not Necessary	65.70 FL	*- FL
47	1		*STAY ,RADIATOR SUPPORT LH	Not Necessary	65.70 FL	*- FL
48	1		*RADIATOR FAN BLADE (RH)	Not Necessary	233.10 FL	*- FL
49	1		*RADIATOR FAN BLADE (LH)	Not Necessary	233.10 FL	*- FL
50	1		*RADIATOR FAN MOTOR (RH)	Not Necessary	543.70 FL	*- FL
51	1		*RADIATOR FAN MOTOR (LH)	Not Necessary	543.70 FL	*- FL
52	2		*RADIATOR FAN COWLING (LH/RH)	Not Necessary	902.60 FL	*- FL
53	1		*HORN	Serviceable	112.71 FL	*- FL
54	1		*CONDENSER ASSY ,W/RECEIVER	Bent	1,336.60 FL	*1,336.60 FL
55	1		*FENDER SUB-ASSY ,FRONT RH	Repair	945.30 FL	*- FL
56	1		*FENDER SUB-ASSY ,FRONT LH	Dented	945.30 FL	*945.30 FL
57	1		*FRONT FENDER SHIELD CLIP	Not Necessary	14.90 FL	*- FL
58	1		*FRONT FENDER HYBRID EMBLEM ,LH	Necessary	86.50 FL	*86.50 FL
59	1		*FRONT FENDER HYBRID EMBLEM ,RH	Serviceable	86.50 FL	*- FL
60	1		*BRACKET ,FRONT SIDE PANEL, RH	Not Necessary	86.30 FL	*- FL
61	1		*BRACKET ,FRONT SIDE PANEL, LH	Not Necessary	86.30 FL	*- FL
62	1		*FRONT NO .PLATE }	Dislodged	25.00 FS	*45.00 FS
63	1		*FRONT NO .PLATE TRIM COVER }	Dislodged	30.00 FS	*- FS
64	1		*FRONT NO.PLATE GARNISH	Broken	99.00 FS	*99.00 FS
65	1		*FRONT BUMPER LOGO	Not Necessary	87.10 FS	*- FS
66	1		*TOP PANEL SIDE (LH)	Bent	145.90 FL	*145.90 FL
67	1		*FRONT FENDER SHIELD (LH)	Torn	198.50 FL	*198.50 FL
68	1		*ENGINE UNDER COVER	Dislodged	457.20 FL	*457.20 FL
69	1		*ENGINE UNDER COVER FRONT	Torn	288.30 FL	*288.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,157.00	18,039.39
- List Item Discount on L Items 20.00/25.00% (\$\$)	5,583.18	4,473.85
Total Parts (\$\$)	22,573.82	13,565.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	900.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	180.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX RADIATOR	New	90.00	50.00
7	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
8	REMOVE/REFIX FUSE BOX	New	120.00	0.00
Gross Labour Cost (S\$)			3,760.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >