Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21000833/AQD3Q2

**Date:** 25/02/2021

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

indo insurance ric. Ltd. I oney No

Claimant SLD6055P Insured Vehicle No: XE5891B

Date of Loss: 15/01/2021 Nature of Claim: TP Claim No: CDMFG21000096

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLD6055P

 Make & Model:
 HONDA VEZEL, 1.5 (A)
 Engine No:
 L15B4035173

 Reg. Date:
 23/06/2016 (Man. Year: 2016)
 Chassis No:
 RU11115167

 Colour:
 Black
 Odometer:
 186928 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 12,210.40  | 6,199.12   | 6,011.28   | 49.23  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 3,010.00   | 1,330.00   | 1,680.00   | 55.81  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 15,220.40  | 7,529.12   | 7,691.28   | 50.53  |
| Approved Total (Overridden) (S\$) |            | 6,000.00   |            |        |
| Nett Amount (S\$)                 | 15,220.40  | 6,000.00   | 9,220.40   | 60.58  |

**INSPECTION** 

Date of Assignment: 18/01/2021

Date Inspected: 21/01/2021 Inspected At: Cn Motors Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 BLK C #01-

41 AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2021)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLD6055P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

Total Parts (S\$) 12,210.40

**Amount** 

6,199.12

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qtv Part No. Particulars

| NO.   | Qty   | Part NO.    | ratuculais                         | Condition       | Repairer 5  | Amount       |
|-------|---|-------------|------------------------------------|-----------------|-------------|--------------|
| 1     | 1   |             | *FRONT R/H HEAD LAMP               | Cut             | 1,820.90 F  | *1,820.90 FL |
| 2     | 1   |             | *FRONT R/H HEAD LAMP LOWER BRACKET | Not Necessary   | 45.00 F     | *- FL        |
| 3     | 1   |             | *FRONT BUMPER                      | Deformed        | 495.80 F    | *495.80 FL   |
| 4     | 1   |             | *FRONT BUMPER LOWER LID            | Not Necessary   | 351.00 F    | *- FL        |
| 5     | 10  |             | *FRONT BUMPER CLIP                 | Necessary       | 65.00 F     | *30.00 FL    |
| 6     | 1   |             | *FRONT R/H BUMPER SIDE RETAINER    | Necessary       | 27.10 F     | *27.10 FL    |
| 7     | 1   |             | *FRONT BUMPER NUMBER PLATE         | Not Necessary   | 50.00 F     | *- FL        |
| 8     | 1   |             | *FRONT BUMPER REINFORCEMENT        | Not Necessary   | 321.80 F    | *-FL         |
| 9     | 1   |             | *FRONT R/H BUMPER FOG LAMP         | Not Necessary   | 327.70 F    | *-FL         |
| 10    | 1   |             | *FRONT R/H BUMPER FOG LAMP COVER   | Not Necessary   | 45.00 F     | *-FL         |
| 11    | 1   |             | *FRONT R/H FENDER                  | Dented          | 582.00 F    | *582.00 FL   |
| 12    | 1   |             | *FRONT R/H FENDER COWLING          | Torn            | 130.00 F    | *130.00 FL   |
| 13    | 6   |             | *FRONT R/H FENDER COWLING CLIP     | No              | 39.00 F     | *39.00 FL    |
| 14    | 1   |             | *FRONT R/H ARCH PROTECTOR          | Cut             | 166.00 F    | *166.00 FL   |
| 15    | 8   |             | *FRONT R/H ARCH PROTECTOR CLIP     | Necessary       | 52.00 F     | *20.00 FL    |
| 16    | 1   |             | *FRONT R/H LOWER ARM               | Bent            | 351.00 F    | *351.00 FL   |
| 17    | 1   |             | *FRONT R/H KNUCKLE ARM             | Damaged         | 238.70 F    | *238.70 FL   |
| 18    | 1   |             | *FRONT R/H KNUCKLE ARM BEARING     | Damaged         | 135.50 F    | *135.50 FL   |
| 19    | 1   |             | *FRONT R/H SHOCK ABSORBER          | Bent            | 430.10 F    | *430.10 FL   |
| 20    | 1   |             | *FRONT R/H DRIVE SHAFT             | Not Necessary   | 1,103.40 F  | *- FL        |
| 21    | 1   |             | *FRONT STEERING RACK               | Bent            | 2,270.60 F  | *1,750.00 FL |
| 22    | 1   |             | *FRONT R/H SIDE MIRROR ASSY        | Cut             | 782.80 F    | *782.80 FL   |
| 23    | 1   |             | *SET FRONT R/H RIM                 | Cut             | 2,000.00 FS | *400.00 FS   |
| 24    | 1   |             | *FRONT R/H TYRE                    | Punctured       | 380.00 FS   | *200.00 FS   |
| F=Fra | nchise  | part. S=Spc | Nett. L=ListItemDisc.              |                 |             |              |
|       |   |             |                                    | Sub Total (S\$) | 12,210.40   | 7,598.90     |
|       | - List Item Discount on L Items 0.00/20.00% (S\$) |             |                                    |                 | 0.00        | 1,399.78     |
|       |   |             |                                    |                 |             |              |

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No  | Particulars  | Lab.Type | Repairer's | Amount   |
|-----|--|----------|------------|----------|
| Lab | our Items  |          |            |          |
| 1   | TO REMOVE & REFIT CUSHION & TRIM BOARD                             | New      | 280.00     | 0.00     |
| 2   | TO REMOVE & REFIT FRONT UNDERCARRIAGE, DRIVE SHAFT & STEERING RACK | New      | 380.00     | 220.00   |
| 3   | TO CHECK WHEEL ALIGNMENT   | New      | 150.00     | 80.00    |
| 4   | TO CHECK WIRING  | New      | 100.00     | 30.00    |
| 5   | TUFF KOTE  | New      | 150.00     | 40.00    |
| 6   | TOWING FEE   | New      | 150.00     | 60.00    |
| 7   | PANEL BEATING  | New      | 1,000.00   | 400.00   |
| 8   | SPRAY PAINTING   | New      | 800.00     | 500.00   |
|     | Gross Labour Cost (S\$)  |          | 3,010.00   | 1,330.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >